


Title	CC	ONVE	RTI	NG .	ASR-	-33 TO	PDP-8/E		Tech Tip Number	LT33-TT-1
All		Proc	essoi	App	olicab	ility	Author Sweeney/Quinn	Rev	В	Cross Reference
x							Approvai F. Purcell	Date 7/3	1/73	



* If the Teletype Control Module is an M865, the split lugs are to be connected to the TTY as follows:

```
SPLIT LUG#4 = RDR RLY - #3 = TERM #3 
#7 = TERM #4 
#5 = TERM #7 
#6 = RDR RLY + 
#2 = TERM #6
```

The above chart has been designed to reduce the amount of time you would normally spend cross-referencing several different sets of prints. It is highly recommended that, before applying power to the reconfigured system, you double-check all wiring for correctness. Failure to do so could result in damage to the Teletype Control Module and/or the Teletype.

PAGE	399	PAGE REVISION	С	PUBLICATION DATE	August	1974

Title	Title CONVERTING ASR-33 TO PDP 8E (cont)				p LT33-TT-1
Ali	Processor Applicability	Author Sweeney/Quinn	Rev	В	Cross Reference
x		Approval F. Purcell Date	7/31,	/73	

Converting the ASR-33 to the PDP-8/E Occasionally a customer may request to have an older ASR-33 configured such that it can be used on any 8/E type system.

CAUTION: Prior to performing any rewiring, be certain that the teletype in question has in fact been modified for use on DEC's PDP-8 family of computers. (Reference the field service technical manual, LT33-TT-3)

Title ASR CONVERSION 280V,	50Hz V.S. 115V, 60Hz	Tech T Numbe	ip F LT33-TT2
All Processor Applicability	Author J. Blundell Quinn	Rev C	Cross Reference
x	Approval D. Staupe D	ate 7/10/74	
l) Disconnect and remove transformer from the tele	the step down type base.	0 3 6 B 0 C 2 5 D WHT & 1 4 D	POWER CO
2) Remove the AC supply strip inside the teletype	lead from the terminal	L	T BLK
 Connect the new AC poterminals, white to C, bl. to a chassis screw. 	wer cord to those same ack to #1 and green	GRN GND	APPROX
4) If the motor is rated desired Hz rating, it mus	t be replaced with cycle operation.	IOFT	APPROX V
(Not necessary if motor i 5) Change the fuse to cor- being used	s already 50/60 Hz). respond to the motor		ANSFORMER NTING&WIRING

Proper operating speed is determined by the ratio of the belt driving gear and its pinion gear: these must be replaced in this conversion.

The parts required for conversion can be specified as follows:

Part	Vendor Part#	DEC Part#
	60Hz 50Hz	60Hz 50Hz
Belt driving gear	181420 181855	29-11417 29-11431
Pinion gear	181411 181851	29-11412 29-11428
Motor	181870 182267	29-11432 29-11448
AC power cord	182510	29-16755
Plug 220V Fuse		
Puse	MDL 2.25 320246	90-08853 29-19119 12-11425
T		

Installation charges are based on time and material; there is no fixed charge for this conversion. Price for parts is approximately \$100.

PAGE 400

being used.

digital

FIELD SERVICE TECHNICAL MANUAL

Option or Designator

12 Bit 1

16 Bit 💢

18 Bit 36 Bit 🔀

LT33

Title PRICING POLICY FOR TELETYPE CONVERSIONS Tech				LT33 TT3
All	Processor Applicability	Author Walter MacKenzie Rev	0	Cross Reference
X		Approval W. Cummins Date 7-3	1-72	

The following policies and prices have been established as of June 1969 for modifying customer owned Teletypes for use with DEC computers.

TELETYPE MODEL	CONVERSION KIT ONLY (A)	DEC CONVERSION - Parts and Labor (B)
KSR-33	\$100.00	\$200.00
ASR-33	\$125.00	\$300.00
KSR-35	\$125.00	\$300.00
ASR-35	NOT AVAILABLE	\$1000.00

Conversion Kits - Do It Yourself

Each conversion kit, as listed above in column A, will include all necessary parts and installation instructions.

Conversions Done By DEC Personnel

Conversion prices, as listed in column B above, are based upon the assumption that the customer owned Teletype presented to DEC for conversion is in good operating order. Labor and/or parts required to restore a unit to good working condition will be billable at DEC's then prevailing rates.

Field Service mileage rates shall also apply in addition to the installation charges listed above.

DEC will provide a 30 day warranty of the conversion only.

The conversion kit for the ASR-35 shall remain proprietart in nature. This is based upon the fact that DEC has made extensive engineering investments in creating this modification and customers should expect to reimburse us for that effort.

COMPANY CONFIDENTIAL

PAGE	401	PAGE REVISION	0	PUBLICATION DATE	July 1972

CPL

Title	ASR 33 MODIFIC	Tip er LT33 TT#4		
All	Processor Applicability	Author Rev	v 0	Cross Reference
X		Approval W. Cummins Date 7	-31-72	

At times, the ASR 33 punch will not accept fanfold tape. To correct this, install the 1.85705 tape guide MOD Kit. These kits are available in the Field Service Stockroom and are priced at \$9.45.

-				CPL
Title			Tech T	ip
	ASR 35/81/M707	FAILURES	Numbe	LT33 TT#5
All	Processor Applicability	Author	Rev	Cross Reference
X		Approval W. Cummins	Date 7-13-72	

ASR 35/81/M707 FAILURES

Erratic failure of the M707 Teletype transmitter module has been a problem when an ASR 35 is connected to an 81; the M707 output transistor (Q3) (6534) is blown and the ASR 35 runs open. This will occur following rotation of the mode switch through the KT, T positions. Excessive transients were suspected and several ECO's have been suggested and implemented.

- 1. A D664 diode connected in parallel with the 470 ohm resistor from the base of Q3 to 5V on the M707 (cathode to +5V).
- On the W076 connector card, pin F, change the 750 ohm resistor to 1K, add 3 D671 diodes, pin H (cathode) to -15V, pin H to -5V (cathode), and pin M to ground (cathode).
- Use of thyrectors or arc suppressors across the selector magnetic terminals.

The specific problem has now been recognized as a circuit peculiarity in the ASR 35 which was overlooked in the design of the M707. The mode switch on the ASR 35 applies a short circuit to -15V at pin AV2 of the M707 (J12H2) as it is rotated between the KT and T positions. Current limiting circuitry was not provided for the 6534 and the excessive current destroys it.

Engineering first suggested that a 100 ohm resistor be inserted in series with the emitter circuit of the 6534 on the M707 and this was done on about 10 machines. It was discovered with further research that the normal 20 ma. marking current for the ASR 35 had been reduced to 11 ma. by this modification. Because teletype operation becomes marginal at 10 ma., it became obvious that this was unacceptable.

A final solution has been determined and will become an ECO;

- 1. Cut the etch between the 6534 collector and pin AV2 on the M707 and insert a 120 ohm 1/4W resistor in series.
- On the W076 change resistor R3 (which is connected between pins B and F) from either 750 or 1000 ohms to 820 ohms 1/2W.

CPL

digital

FIELD SERVICE TECHNICAL MANUAL

Option or Designator

LT33

12 Bit 🗵 16 Bit 😧 18 Bit 🗶 36 Bit 🔀

Title	SECURING TELETYPE	CABLE TO LOGIC FRAME	Tech T Numbe	p r LT33 TT# 6
All	Processor Applicability	Author	Rev 0	Cross Reference
	81 18	Approval W. Cummins	Date 7-31-72	

The cable from the teletype is dressed under the 81 cabinet, through the large opening and into logic frame slot J12. If the teletype happened to be positioned at the maximum distance which the cable would allow (assuming the logic frame in the normally closed position) or if the cable were to be looped around a caster and an attempt made to pull the logic frame forward, the horizontal stress could easily damage either the block or the WO76A connector card. It is necessary that the cable be dressed through the cable clamp at the lower rear corner of the logic frame where the power cables are secured to eliminate this possibility. A second clamp may be desirable at the bottom of the 81 cabinet to assure that sufficient slack exists irrespective of teletype position.

Title	ASR 33 READE	Tech Tip Number LT33 TT#7	
All	Processor Applicability	Author White/Arsenault Rev	0 Cross Reference
	81 8F	Approval W. Cummins Date 7-31	1 - 72

When ASR 33 Part II Program 3 fails roughly once per complete pass, the failure always occurs in the random stall section of test as a result of the reader fetching an extra character.

This problem is a synchronizing problem which exists in M706 modules of Revision J or earlier. It will be fixed in future revisions via an ECO to the M706. Boards of revision J or earlier can be made to work properly by the addition of a 470 PF capacitor from Pin BN2 of the M706 to ground.

COMPANY CONFIDENTIAL

PAGE 403 PAGE REVISION A PUBLICATION DATE May 1974

CPL

Title	TELETYPE READER POWE	р LT33-TT-8			
All	Processor Applicability	Author Bill Harrigan	Rev	0	Cross Reference
X		Approval W. Cummins Date	7 - 3	1-72	

A poor electrical connection between the 200 MFD capacitor and the circuit board etch has resulted in failures of the Teletype reader power supply. The symptoms will be either a blown 3 amp fuse or a defective rectifier, the latter resolved only by replacement of the power supply.

The poor connection is caused by the stripping away of etch by the teeth on the star washer used to secure the capacitor to the board. A standard washer should be installed between the star washer and the circuit board to eliminate this problem.

Title	TELETYPE PRINTS		Tech Tip Number	LT33-TT-3
All	Processor Applicability	Author Walter MacKenzie Rev	Ø	Cross Reference
х		Approval W. Cummins Date 12/1	2/73	

A well documented set of prints explaining our modification to teletypes is now available in drafting. You can order these prints under the following numbers:

Number	Revision	Description
7505038-0-0		ASR 33 120V 60HZ
7505039-0-0		ASR 33 340V 50/60HZ
7505040-0-0		KSR 33 240V 50/60HZ
7505041-0-0		KSR 33 120V 60HZ
7505042- 0-0		KSR 35 240V 50/60HZ
7505043-0-0		KSR 35 120V 60HZ

COMPANY CONFIDENTIAL

digital

FIELD SERVICE TECHNICAL MANUAL

Option or Designator

12 Bit x

16 Bit 😿

18 Bit 😿 | 36 Bit 😾

LT33

Title	OLD 33 TS, TU, TBP	NEW 3300 SERIES TELETYPE	AND Tech To Numbe	p r LT33-TT-10
All	Processor Applicability	Author Ray Alvarez	Rev _Ø	Cross Reference
X		ApprovalDick Russell Date	e6/25/74	

As of September 1973 DEC has been shipping the new style 3300 series teletype. There are some noted differences between these two models, and apparently some confusion has existed in the field. This techtip will help clear up the differences between the two models and also help to update documentation that will follow in the near future.

1) Internal Differences:

The reader power pack on the 3300 mounts within the main teletype case (in the call control unit area) rather than in the teletype base (stand). This elimates the mounting, unmounting, and repacking of the power pack previously required.

- 2) The 3300 series punch mechanism is always equipped for automatic operation (DC2 and DC4 control) but automatic operation is inhibited by a pair of clips installed at teletype. See teletype manual for details.
- 3) The 3300 printer mechanism is equipped with mechanism to provide the CR LF function when CR is received but this feature is inhibited by a clip installed at teletype. See teletype manual for details. This feature did not exist on DEC purchased 33 series units.
- 4) The answerback mechanism (and any other stunt box feature requiring disabling) is disabled (when specified by the DEC construction drawings) by means of an inhibit clip on the 3300. On 33 series units the answerback mechanism was disabled by removing the stunt box pawl associated with it. The 3300 clip can also be used on 33 series units.
- 5) The 3300 keyboard is equipped to generate even character parity but can be arranged to generate eighth-bit-marking code by swapping quick connect tabs. A 33 series unit either did or did not have a parity keyboard and changing a parity keyboard to non-parity operation required disassembly and modification of contact bars on the keyboard.
- NOTE A: 33 series units evolved over the years and details of parts replacement and subtleties of operation varied even for the same model number. Do not construe the above list of differences as implying that all DEC purchased 33 series machines of a particular model number were the same over their entire lifetime.
- MOTE B: A complete programming and operating description of all DEC supplied 33 Teletypes (after the PDP-6 and classic LINK) is contained in DEC specification A-SP-LT33- β -14 "LT33 Programming Specification" available from reproduction.

Title OLD 33 TS, TU, TBP (Cont.) Tech Tip Number LT3					
All	Processor Applicability	Author Ray Alvarez	Rev ø	Cross Reference	
Х		Approval Dick Russell Date	6/25/74		

1) Keyboard Differences:

The keyboard key which generates 136₈ will be labelled "A". It is presently labelled "¶".

- 2) The keyboard key which generates 137g will be labelled "_" (underscore). It is presently labelled "_".
- 3) The printer mechanism will print "A" when it receives 1368. It presently prints "A".
- 4) The printer mechanism will print "_" (underscore) when it receives 1378. It presently prints "4".
- 5) The printer mechanism will print "\", "]", and "A" when it receives 1748, 1758, and 1768 respectively. Presently it prints nothing when receiving these codes. NB: 1748 was formerly ACK, 1758, was formerly ALT MODE, and 1768 was formerly ESC1.
- 6) The keyboard will have a key labelled ESC which will generate the code $\emptyset 33_8$. There will be no key labelled ALT MODE and no way to generate the codes 175_8 or 176_8 from the keyboard.
- 7) The keyboard key which generates 1778 will be labelled DELETE. It is presently labelled RUB OUT.
- 8) These changes are already reflected on the pocket reference card for 8's and 11's.
- 9) All machines except the LT33-D type machines will generate even parity from the keyboard. At present some other LT33 units have the 8th (parity) bit always "1". It is planned that eventually all machines will generate even parity from the keyboard.

The ALT MODE/ESC change should not affect any properly written program. That is, DEC has in the past shipped model 33 Teletypes which have had either ALT MODE keys (175₈), ESC₁ keys (176₈) or ESC₂ keys (\$\psi 33_8\$). In addition, non-DEC terminals are variously designed to use 175 or \$\psi 33_8\$ as ALT MODE/ESC and if not in a "lower case" mode should also accept 175₈ and 176₈. (On lower case machines 175₈ is "?" and 176₈ is "~"). In addition, ALT MODE/ESC should not be "echoed" by the program unless it is intended to perform some particular function for some particular terminal (e.g. on some model 37 Teletypes the sequence "ESC 3" shifts the machine into red ribbon mode).

It is recommended that user programs which use "-" as a command operator (e.g., to direct a data transfer to one file from another) should be modified to accept "=" for this function as well as "-" since the left arrow will become underscore ("_").

It is believed that the symbols " \P " and " Λ " are sufficiently similar that no program change involving them is needed.

PAGE 406

digital

FIELD SERVICE TECHNICAL MANUAL

Option or Designator

12 Bit 🔀

16 Bit 😡

18 Bit 😾 📗

36 Bit 🙀

LT33 to LT35

Title	DIFFERENCES BETWEEN NOLD 33 TS, TU, TBP (C	EW 3300 SERIES TELETYPE ont.)	AND Tech Ti Number	LT33-TT-10
All	Processor Applicability	Author Ray Alvarez	Rev ø	Cross Reference
x		Approval Dick Russell Date	6/25/74	


Unrelated to the above described changes, the following programming practices are recommended in dealing with teletypewriter-like devices to ensure compatibility with the largest number of terminals.

- 1. A program unwilling to deal with lower case input should translate codes 140_8 to 173_8 to the corresponding upper case codes 100_8 thru 133_8 .
- 2. The eighth bit of each character (the 200₈ bit) should be ignored when received in general purpose programs. This bit is commonly even parity or a "1" but in some terminals can be odd parity or a "6".
- 3. The eighth bit of each character (the 200₈ bit) should be transmitted as even parity. This will not confuse 33's or 35's and is necessary on some other terminals.
- 4. Control characters should not be echoed when some particular action is expected from the teleprinter (e.g. control back slash, "FS" causes the cursor to be returned to the upper left hand corner of the screen on the VTØ5 and VTØ6).

In order to verify that software is not sensitive to the eighth bit ("parity bit") from Teletype it is useful to modify selected Teletypes so that keyboard characters always have their 8th bit spacing ("0") instead of the more usual marking ("1") 8th bit. The simple procedure is detailed on the attached sketch.

Machines which are modified should be prominently marked "Modified: Keyboard 8th bit zero."

Diagnostics such as PDP8E Teletype and KL8E Asynchronous Data Control Tests, are compatible except with one noted difference. On transmit from CPU to TTY, a 7-hole rub out will appear as "f" an up arrow. This is due to new 3300 series printers having one less function lever (slot 5) if customer so desires full compatibility he may order function lever #180-793 and have it installed at per call rates.



0

To make 8th Bit
Alway Spacing ("1")
Slip A Piece Of #18
AWG Sleeving Over
The Short Contact
Wire. The Wire Will
Not Seat Between The
Insulating Tabs
When Sleeved.

Right Side View Of Keyboard Contact Block (Non-Parity Keyboards)

PAGE 407

PAGE REVISION

PUBLICATION DATE July 1974

Title	ip LT35-TT-1			
All	Processor Applicability	Author Tom Bowman	Rev 0	Cross Reference
		Approval W. Cummins	Date 7-31-72	

Intermittent reader problems have resulted from a loosening of the sponge rubber pad which is mounted to the cover plate above the reader pins. Contact cement should be used to secure this pad as is now being done in production.

Title	PRICING POLICY FOR	TELETYPE CONVERSIONS	Tech 1 Numbe	
All	Processor Applicability	Author	Rev 0	Cross Reference
х		ApprovalW. Cummins	Date 8/17/72	LT33-TT-3

This Tech Tip is issued for cross reference purposes only.

Title KSR-35 LUBRICATION	Tech Tip Number LT35-TT-3	
All Processor Applicability	Author M. Schwartz Rev	0 Cross Reference
\times	Approval Lou Nay Date 02/	/15/73

The present PM procedure for KSR-35 Teletypes calls for lubrication on a quarterly basis. However, at most sites the console teletype runs 24 hours a day. The heat generated and centrifugal force will dissipate the lubricants within the clutch bearings, drums and shoes in less than 30 days.

Under the above operating conditions, monthly lubrication should be made - at least in the mainshaft area.

COMPANY CONFIDENTIAL

PAGE 408	04.05 051010101			
FAGE 408	PAGE REVISION	•	PUBLICATION DATE	1
		A	III OPFICATION DATE	197 I
		The state of the s		±21