

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D0400-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Jan-70

Description :

1ST Copyright year : 1970

Last Copyright Year : 1970

Expanded Description : Random JMP Test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

Product Date is actually 12-Jan-68
1st Copyright Year is actually 1968

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected .

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : M. Horovitz
Submitting Engineer : Horovitz
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

A

Compo

Compo

Diagn

Descr

Expan

Run

Proce

Opera

Devic

Probl

Kit N

Auth

Subm

Prod

Manu

Char

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D0500-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Jan-70

Description :

1ST Copyright year : 1970

Last Copyright Year : 1970

Expanded Description : Random JMP-JMS Test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Product Date is actually 12-Jan-68
1st Copyright Year is actually 1968

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : M. Horovitz
Submitting Engineer : Horovitz
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MCOC00

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D0700-B0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 01-Jan-70

Description :

1ST Copyright year : 1970

Last Copyright Year : 1970

Expanded Description : Random ISZ Test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Product Date is actually 28-Dec-67
1st Copyright is actually 1967

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : Horovitz
Submitting Engineer : Horovitz
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D1A00-C0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 01-Jan-70

Description :

1ST Copyright year : 1970

Last Copyright Year : 1970

Expanded Description : Memory Power On/Off Test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

Product Date is actually 16-Sep-68
1st Copyright Year is actually 1968

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : M. Horovitz
Submitting Engineer : Horovitz
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D2P00-E0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 01-Jan-70

Description :

1ST Copyright year : 1970

Last Copyright Year : 1974

Expanded Description : Family of 8 ASR33/35 TTY Test 1

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

Product Date is actually 02-Feb-69
1st Copyright Year is actually 1969

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 93

Operational Environment : 00

Device Affected : ASR33 ASR35

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J. Vrobel
Submitting Engineer : Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

Diagnostic Package Code : MD-08-D5F-A0

Description :

Expanded Description : RF08 Multi Disk Test

ECO Purpose : New

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

1ST Copyright year : 1969

Approved : Yes

Product Date : 01-Jan-70

Last Copyright Year : 1974

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Actual Product Date is 26-Mar-69

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : E. Haight
Submitting Engineer : E. Haight
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MCG000

A

Comp

Comp

Diag

Desc

Exp

Run

Proc

Oper

Devic

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D6C-C0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 01-Jan-70

Description :

1ST Copyright year : 1969

Last Copyright Year : 1974

Expanded Description : Cal Comp Plotter test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

Actual Product Date is 23-Mar-69

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 93 94

Operational Environment : 00

Device Affected : VP8I

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : R. Christopher
Submitting Engineer : Christopher
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : Vrobel
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

A

Comp

Comp

Diag

Desc

Expa

Run

Pro:

Oper

Devi

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D2G00-F0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 28-Feb-70

Description :

1st Copyright year : 1970

Last Copyright Year : 1974

Expanded Description : High Speed Reader Punch Test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 93 94

Operational Environment : 00

Device Affected : PC02 PC03

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : R. Koller
Submitting Engineer : VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. FULLER
Coordination Number : MC0000

A

Comp

Comp

Diag

Desc

Expa

Run

Proc

Oper

Devi

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D8E-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 09-Mar-70

Description :

1ST Copyright year : 1970

Last Copyright Year : 1970

Expanded Description : DC08-F + DC08H

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93

Operational Environment : 00

Device Affected : DC08F DC08H

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : G. ZAGARS
Submitting Engineer : G ZAGARS
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

Comp

Comp

Diag

Desc

Exp

Run

Proc

Oper

Devi

Prob

Kit

Auth

Subm

Proc

Manu

Char

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : MD-08-D8F-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 09-Mar-70

Description :

1ST Copyright year : 1970

Last Copyright Year : 1970

Expanded Description : DC08 + DC08H online test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93

Operational Environment : 00

Device Affected : DC08F DC08H

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : G. Zagars
Submitting Engineer : Zagars
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : Fuller
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D8C-A0

~~PRODUCT IDENTIFICATION~~

Patch Level : 0

Product Date : 15-Jun-70

Description :

1ST Copyright year : 1967

Last Copyright Year : 1967

Expanded Description : DB8-S DATA BREAK TEST 2

~~PRODUCT COMPONENTS AFFECTED~~

~~PRODUCTS OBSOLETED~~

~~PROBLEM/DESCRIPTION~~

~~SOLUTION/CORRECTION~~

~~PRODUCT CHARACTERISTICS~~

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected : DB8S

Problem Reports Affected :

Kit Number :

~~AUTHORIZATION~~

Author : B GREEN
Submitting Engineer : B GREEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D6C-E0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 05-Aug-70

Description :

1ST Copyright year : 1969

Last Copyright Year : 1969

Expanded Description : KV8I DISPLAY DIAG

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93

Operational Environment : 00

Device Affected : KV8I

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : ESTEINBERGER

Submitting Engineer : J VROBEL

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group :

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : Mu-08-DOA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Aug-70

Description :

1ST Copyright year : 1968

Last Copyright Year : 1968

Expanded Description : PDP-8I INSTRUCTION TEST 3A

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Devices Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B KOLLER
Submitting Engineer : B KOLLER
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : J VROBEL
Field Service Engineer :
Release Engineer : T.DAVIE
Coordination Number : MC0000

A

Com

Com

Dia

Des

Exp

Run

Pro

Ope

Dev

Pro

Kit

Aut

Sub

Pro

Man

Cha

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DOB-A0

Patch Level : 0

Product Date : 15-Aug-70

Description :

1ST Copyright year : 1968

Last Copyright Year : 1968

Expanded Description : PDP 8I EAE TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93

Operational Environment : 00

Device Affected : KE8I

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B KOLLER
Submitting Engineer : B KOLLER
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : M00000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D2C-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 19-Aug-70

Description :

1ST Copyright year : 1970

Last Copyright Year : 1970

Expanded Description : 680/I TTY RELIABILITY TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93

Operational Environment : 00

Device Affected : DL8I 680I

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : S BEEMAN
Submitting Engineer : S BEEMAN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

F 1

A

Compo

Compo

Diagn

Descr

Expan

Run

Proc

Oper

Devic

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D8B-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 05-Sep-70

Description :

1ST Copyright year : 1967

Last Copyright Year : 1967

Expanded Description : DB8-S DATA BREAK TEST 1

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected : DB08S

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B GREEN
Submitting Engineer : B GREEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : J VROBEL
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

F 1

A

Comp

Comp

Diagn

Descr

Expan

Run

Proc

Oper

Devi

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D2B-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 22-Sep-70

Description :

1ST Copyright year : 1970

Last Copyright Year : 1970

Expanded Description : 40 COL OPTICAL MARK CARD READER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93

Operational Environment : 00

Device Affected : CM8I

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : E BOUSE

Submitting Engineer : E BOUSE

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group :

Maintainer : MISNER

Field Service Engineer :

Release Engineer : J.DAVIES

Coordination Number : MC0000

F 1

A

Comp

Comp

Diag

Desc

Expa

Run

Proc

Oper

Devic

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D8A-D0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Oct-70

Description :

1ST Copyright year : 1968

Last Copyright Year : 1968

Expanded Description : REAL TIME CLOCK (KW8I)

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93

Operational Environment : 00

Device Affected : KW8I

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J KELLY

Submitting Engineer : KELLY

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group

: DIAG

Maintainer

: MISNER

Field Service Engineer

:

Release Engineer

: T.DAVIES

Coordination Number

: MC0000

F 1

A

Comp

Comp

Diag

Desc

Exp

Run

Proc

Oper

Dev

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D5H-C0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 02-Nov-70

Description :

1ST Copyright year : 1970

Last Copyright Year : 1974

Expanded Description : RK8 Disk Data Reliability

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected : RK08

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : M. Sturak
Submitting Engineer : M. Sturak
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D8D-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 05-Nov-70

Description :

1ST Copyright year : 1968

Last Copyright Year : 1968

Expanded Description : 689-AG ON-LINE DIAG EXERC

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93

Operational Environment : 00

Device Affected : 689AG

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : E KENNY
Submitting Engineer : E KENNY
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

Comp

Comp

Diag

Desc

Expa

Run

Proc

Oper

Devi

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DCI-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 12-Nov-70

Description :

1ST Copyright year : 1970

Last Copyright Year : 1970

Expanded Description : ACT-8E BASIC JUM-JMS TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : B HANSEN
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-C8-D0J-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 12-Nov-70

Description :

1ST Copyright year : 1970

Last Copyright Year : 1970

Expanded Description : ACT-8E RANDOM JMP-JMS TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD6K-C0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 01-Dec-70

Description :

1ST Copyright year : 1970

Last Copyright Year : 1974

Expanded Description : VC8I, 34D DISPLAY TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93

Operational Environment : 00

Device Affected : VC8I

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Kelley
Submitting Engineer : J Kelley
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D5K-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 18-Dec-70

Description :

1ST Copyright year : 1970

Last Copyright Year : 1974

Expanded Description : RK8 Disk Formatter

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected : RK08

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : F. Haight
Submitting Engineer : Haight
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

OF 1
B

A

Comp

Comp

Dia

Des

Exp

Run

Pro

Oper

Dev

Prob

Kit

Aut

Sub

Pro

Man

Cha

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D1K00-B0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 02-Feb-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1974

Expanded Description : KP8I/KR01 Power Fail Test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93

Operational Environment : 00

Device Affected : KP8I KR01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B. Heavey
Submitting Engineer : Heavey
Product Engineer :
Manufacturing Engineer :
Charge Number : VOC-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

A

Com

Com

Dia

Des

Exp

Run

Pro

Ope

Dev

Pro

Kit

Aut

Sub

Pro

Man

Cha

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

Diagnostic Package Code : MD-08-D1M-A0

Description :

Expanded Description : Memory Address Test

ECO Purpose : New

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 16-Feb-71

1ST Copyright year : 1971

Last Copyright Year : 1974

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B. Hansen
Submitting Engineer : B. Hansen
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

A

Com

Com

Dia

Des

Exp

Run

Pro

Ope

Dev

Pro

Kit

Aut

Sub

Pro

Man

Cha

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DON-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 25-Mar-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : ACT-8E JMP SELF TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment :

Device Affected : MM8E MM8EJ MM8EH

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : C CAMPBELL

Submitting Engineer : C CAMPBELL

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group :

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-D1U-A0

Patch Level : 0

Product Date : 25-Mar-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : ACT-8E MMB-E 4K CHECKERBOARD MODULE FOR 32K

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : V FREY
Submitting Engineer : V FREY
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DJA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 29-Apr-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : ACT-8E FOCAL 69 FOR ACT-8/E

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment :

Device Affected : ACT8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DSA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 29-Apr-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : ACT-8E SYMBOLIC EDITOR FOR ACT-8E

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : L BEYERSDOFER
Submitting Engineer : L BEYERSDOFER
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-0000C

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DSC-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 29-Apr-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : ACT-8E PAL IT1 FOR ACT8/E

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment :

Device Affected : ACT8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : L. BEYERSDORFER

Maintaining Group : DIAG

Submitting Engineer : L. BEYERSDOFER

Maintainer : MISNER

Product Engineer :

Field Service Engineer :

Manufacturing Engineer :

Release Engineer : T.DAVIES

Charge Number : V00-00000

Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DOG-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 11-Jun-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : RANDOM DCA TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconos) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D6A-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 18-Jun-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : PLOTTER CONTROL + DISPLAY (XY8E)

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : XY8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : BEYERSDOFER
Submitting Engineer : L BEYERSDOFER
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DOF-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 11-Jul-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : RANDOM ISZ TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

Diagnostic Package Code : MD-08-DOH-C0

Description :

Expanded Description : RANDOM JMP TEST

ECO Purpose : Change
Patch Level : 0

1ST Copyright year : 1971

Approved : Yes

Product Date : 11-Jul-71

Last Copyright Year : 1971

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D1G-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 11-Jul-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : PDP-8E MEMORY POWER ON/OFF TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : B HANSEN
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D2D-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 30-Sep-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : 40 COLUMN OPTICAL MARK CARD READER TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment :

Device Affected : CM8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HEAVEY
Submitting Engineer : B HEAVEY
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D9B-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 08-Oct-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : INSTRUCTION TEST PART 2

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : PMK01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D9C-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 08-Oct-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : ADDRESS TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : PMK01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D9K-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 08-Oct-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : MEMORY ADDRESS TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : MM8E PMK01 MM8EH MM8EJ

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
FORM : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD9A-D0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 14-Oct-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1974

Expanded Description : DATA RELIABILITY TEST (7TRACK) (TC58)

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : TC58 TU20 TU10

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : M Sturak
Submitting Engineer : M STURAK
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D9A-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 18-Oct-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : INSTRUCTION TEST PART 1

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : PMK01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DOP-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 27-Oct-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : DB8-E INTERPROCESSOR BUFFER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : DB8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D5J-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Nov-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1974

Expanded Description : RK8 Disk & Control Instr Test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

This program obsoleted by md-08-dirka-a

-----SOLUTION/CORRECTION-----

history starts at rev b

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected : RK08

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : M. Sturak
Submitting Engineer : M. Sturak
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DW1-B0

Patch Level : 0

Product Date : 21-Nov-71

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : ACT-8E AUTO MESSAGE

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 98

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

Component Part Description : ECO Purpose : Change Approved : Yes
 -----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DJY-B0 Patch Level : 0 Product Date : 23-Nov-71

Description : 1ST Copyright year : 1971 Last Copyright Year : 1971

Expanded Description : ACT 8E FOCAL 71 FOR ACT 8/E

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL Maintaining Group : DIAG

Submitting Engineer : J VROBEL Maintainer : MISNER

Product Engineer : Field Service Engineer :

Manufacturing Engineer : Release Engineer : T.DAVIES

Charge Number : V00-00000 Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D11-B0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 01-Jan-72

Description :

1ST Copyright year : 1972

Last Copyright Year : 1972

Expanded Description : M18-E BOOTSTRAP DIAG

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91

Operational Environment : 00

Device Affected : M18E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : J VROBEL
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DIRFA-A0

Patch Level : 0

Product Date : 25-Jan-72

Description :

1ST Copyright year : 1972

Last Copyright Year : 1972

Expanded Description : DEC/X8 MODULE 'RF08DS'

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88 93 94 89 12

Operational Environment : 40

Device Affected : RF08

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : L. Beyersdofer
Submitting Engineer : L. Beyersdofer
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : J. Vrobel
Field Service Engineer :
Release Engineer : T. Davies
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DOL-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 09-Feb-72

Description :

1ST Copyright year : 1972

Last Copyright Year : 1972

Expanded Description : EAE INSTRUCTION TEST 1

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : KE8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : E FORTMILLER

Submitting Engineer : E FORTMILLER

Product Engineer :

Manufacturing Engineer : V97-04518

Charge Number

Maintaining Group

Maintainer

Field Service Engineer

Release Engineer

Coordination Number

: DIAG

: MISNER

:

: T.DAVIES

: MC0668

A

Comp

Comp

Diag

Desc

Expa

Run

Proc

Oper

Devi

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHMRA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 18-Mar-72

Description :

1ST Copyright year : 1972

Last Copyright Year : 1972

Expanded Description : ROM CONTENTS

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : MR8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : C CONLEY
Submitting Engineer : C CONLEY
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

F 1

A

Comp

Comp

Diag

Desc

Expa

Run

Proc

Oper

Devi

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIKLA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 03-Apr-72

Description :

1ST Copyright year : 1972

Last Copyright Year : 1972

Expanded Description : DEC/X8 MODULE 'MULTTY'

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93 94 88 90 91 12

Operational Environment : 40

Device Affected : KL8E KL8J

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : L. Beyersdofer

Submitting Engineer : L. Beyersdofer

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group

: DIAG

Maintainer

: J Vrobel

Field Service Engineer

:

Release Engineer

: T. Davies

Coordination Number

: MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHKLD-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 06-Apr-72

Description :

1ST Copyright year : 1972

Last Copyright Year : 1972

Expanded Description : 8E TTY +KL8 ASYNC DATA CONT

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91

Operational Environment : 00

Device Affected : KL8 ASR33

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : E FORTMILLER

Submitting Engineer : E FORTMILLER

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group : DIAG

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DILPD-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 30-Aug-72

Description :

1ST Copyright year : 1972

Last Copyright Year : 1972

Expanded Description : LP08/F VERTICAL FORMAT DIAG

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 12

Operational Environment : 00

Device Affected : LP08

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : R BARNES
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

Comp

Comp

Diag

Desc

Exp

Run

Proc

Oper

Dev

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHVTA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 04-Dec-72

Description :

1ST Copyright year : 1972

Last Copyright Year : 1972

Expanded Description : DEC/X8 MODULE 'VT8E'

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 94 93 88 12

Operational Environment : 40

Device Affected : VT8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : L Beyersdorfer

Maintaining Group : DIAG

Submitting Engineer : L Beyersdofer

Maintainer : J Vrcbel

Product Engineer :

Field Service Engineer :

Manufacturing Engineer :

Release Engineer : T Davies

Charge Number : V00-00000

Coordination Number : M00000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIQBA-C0

~~PRODUCT IDENTIFICATION~~

Patch Level : 0

Product Date : 21-Jan-73

Description :

1ST Copyright year : 1973

Last Copyright Year : 1973

Expanded Description : FAMILY of 8 System Exerciser dectape kit

~~PRODUCT COMPONENTS AFFECTED~~

~~PRODUCTS OBSOLETED~~

~~PROBLEM/DESCRIPTION~~

~~SOLUTION/CORRECTION~~

~~PRODUCT CHARACTERISTICS~~

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 12 88 89 90 91 92 93 94

Operational Environment : 40

Device Affected : TC01 TU56 TC08 TU55 TD8E

Problem Reports Affected :

Kit Number :

~~AUTHORIZATION~~

Author : L. BEYERSDOFL
Submitting Engineer : L. Beyersdofer
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T. Davies
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DILTC-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 22-Jan-73

Description :

1ST Copyright year : 1973

Last Copyright Year : 1973

Expanded Description : PHOTOCOMP INTERFACE DIAG

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 93 94

Operational Environment : 00

Device Affected : LPC8

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : E. BOUSE
Submitting Engineer : E. BOUSE
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T. DAVIES
Coordination Number : MC0000

A

A

Comp

Comp

Diag

Desc

Exp

Run

Proc

Oper

Devic

Probl

Kit

Auth

Subm

Prod

Manu

Char

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHLAA-A0

~~PRODUCT IDENTIFICATION~~

Patch Level : 0

Product Date : 16-Feb-73

Description :

1ST Copyright year : 1973

Last Copyright Year : 1974

Expanded Description : DECWRITER CONTROL EXERCISER

~~PRODUCT COMPONENTS AFFECTED~~

~~PRODUCTS OBSOLETED~~

~~PROBLEM/DESCRIPTION~~

~~SOLUTION/CORRECTION~~

~~PRODUCT CHARACTERISTICS~~

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : LA30

Problem Reports Affected :

Kit Number :

~~AUTHORIZATION~~

Author : M STURAK
Submitting Engineer : M STURAK
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : J VROBEL
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHKAB-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : ()

Product Date : 12-Mar-73

Description :

1ST Copyright year : 1973

Last Copyright Year : 1973

Expanded Description : RANDOM AND TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

Comp

Comp

Diag

Desc

Exp

Run

Proc

Oper

Devi

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIICC-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 22-Mar-73

Description :

1ST Copyright year : 1973

Last Copyright Year : 1973

Expanded Description : TC58 RANDOM EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : TC58 TU20 TU10

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HEAVEY
Submitting Engineer : B HEAVEY
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

Comp

Comp

Diag

Desc

Expa

Run

Proc

Oper

Devi

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DITCD-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 26-Apr-73

Description :

1ST Copyright year : 1973

Last Copyright Year : 1973

Expanded Description : INSTRUCTION TEST PART 1 (TC58)

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : TC58 TU10 TU20

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : M STURAK
Submitting Engineer : M STURAK
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

Comp

Comp

Diag

Desc

Expa

Run

Proc

Oper

Devi

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIADF-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Mar-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : ADU01 DIAG

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : ADV01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL

Submitting Engineer : J VROBEL

Product Engineer :

Manufacturing Engineer :

Charge Number : V46-06845

Maintaining Group :

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC0515

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIAFB-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Mar-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : AFC8 DIAGNOSTICS

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93 94

Operational Environment : 00

Device Affected : AFC8

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL

Submitting Engineer : J VROBEL

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group :

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DUF-80

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 10-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : TC01 DECTAPE FORMATTER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : TC01 TU56 TC08 TU55

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD6H-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : A/D DIAGNOSTICS AND DEMO

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : AF04A

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T DAVIES
Coordination Number : MCO000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHMCA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : PDP-8E MEM EXT AND T.S. CONTROL TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : KM8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V18-06806

Maintaining Group : DIAG
Maintainer : J VROBEL
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1032

A

A

Comp

Comp

Diag

Desc

Expa

Run

Proc

Oper

Devi

Prob

Kit

Auth

Subm

Proc

Manu

Char

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D11-J0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : PDP-8S MEMORY ADDRESS TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

Comp

Comp

Diag

Desc

Expa

Run

Proc

Oper

Devi

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D15-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : PDP-8S 4K SENSE AMPLIFIER TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

Comp

Comp

Diag

Desc

Expa

Run

Proc

Oper

Devi

Prob

Kit

Auth

Subm

Prod

Manu

Char

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D8A-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : TIME SHARING 8 OPTION TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : 196A 196B 196C

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL

Submitting Engineer : J VROBEL

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group : DIAG

Maintainer : J VROBEL

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC0000

A

A

Comp

Comp

Diag

Desc

Expa

Run

Proc

Oper

Devi

Prob

Kit

Auth

Subm

Proc

Manu

Char

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D9D-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : RANDOM AND TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : PMK01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

Comp

Comp

Diag

Desc

Expa

Run

Proc

Oper

Dev

Prob

Kit

Auth

Subm

Proc

Manu

Char

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D9E-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : RANDOM AND TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : PMK01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : B HANSEN
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

Comp

Comp

Diag

Desc

Expa

Run

Proc

Oper

Dev

Prob

Kit

Auth

Subn

Proc

Manu

Char

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D9F-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : RANDOM ISI TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : PMK01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

Comp

Comp

Diag

Desc

Expa

Run

Proc

Oper

Dev

Prob

Kit

Auth

Subn

Proc

Manu

Char

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D9G-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : RAND DOM DCA TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : PMK01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D9H-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : RANDOM JMP TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : PMK01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D9J-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : RANDOM JMP-JMS TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : PMK01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

Diagnostic Package Code : MD-08-D9M-A0

Description :

Expanded Description : PMK-01 KP8E POWER FAIL TEST

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

1ST Copyright year : 1974

Last Copyright Year : 1974

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : KP8E PMK01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D9N-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : MEMORY POWER ON/OFF TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : MM8E MM8EJ MM8EH PMK01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D9P-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : JMP SELF TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : MM8E MM8EJ MM8EH PMK01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D9Q-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : IOT AND DATA TEST 6701

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : DP01A

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD4A-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : 8/I, 8 BASIC PARITY CHECKERBOARD

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 93

Operational Environment : 00

Device Affected : MP8 MP8I

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD4B-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : EXTENDED MEMORY PARITY TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 93

Operational Environment : 00

Device Affected : MP8 MP8I

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel

Submitting Engineer : J VROBEL

Product Engineer :

Manufacturing Engineer :

Charge Number : VJ0-00000

Maintaining Group :

Maintainer : DIAG
: MISNER

Field Service Engineer :

Release Engineer : T DAVIES

Coordination Number : MC0000

A

PAGE 1 OF 1

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD6J-D0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : AD08 DIAGNOSTICS

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : AD08

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel

Submitting Engineer : J Vrobel

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group :

Maintainer : DIAG

Field Service Engineer : MISNER

Release Engineer : T Davies

Coordination Number : MC0000

A

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD6M-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : VS38 DISPLAY DIAGNOSTICS

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : 338 VS38

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel

Submitting Engineer : J Vrobel

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group : DIAG

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T Davies

Coordination Number : MC0000

A

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD6Q-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : LOW LEVEL MULTIPLEXER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : AM03

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel

Submitting Engineer : J Vrobel

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group : DIAG

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T Davies

Coordination Number : MC0000

A

A

Comp

Comp

Diag

Des

Exp

Run

Pro

Oper

Dev

Prob

Kit

Aut

Sub

Pro

Man

Cha

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD6U-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last.Copyright Year : 1974

Expanded Description : AD01-A DIAGNOSTICS

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93

Operational Environment : 00

Device Affected : AD01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

A

Com

Com

Dia

Des

Exp

Run

Pro

Ope

Dev

Pro

Kit

Aut

Sub

Pro

Man

Cha

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

Diagnostic Package Code : MD-08-DD6W-B0

Description :

Expanded Description : AA50 D/A CONVERTER

ECO Purpose : Change

PRODUCT IDENTIFICATION

Patch Level : 0

1ST Copyright year : 1974

Approved : Yes

Product Date : 21-Apr-74

Last Copyright Year : 1974

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : AA50

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

A

Com

Com

Dia

Des

Exp

Run

Pro

Ope

Dev

Pro

Kit

Aut

Sub

Pro

Man

Cha

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD7C-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : TYPESET + SYSTEM EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00 50

Device Affected : TCSOE TC01 TC08 DF32 RF08 LP08

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

A

Com

Com

Dia

Des

Exp

Run

Pro

Ope

Dev

Pro

Kit

Aut

Sub

Pro

Man

Cha

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

Diagnostic Package Code : MD-08-DD85-C0

Description :

Expanded Description : DM01 EXERCISER

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

1ST Copyright year : 1974

Last Copyright Year : 1974

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : DM01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-PD8B-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : ONLINE IBM360 TO DX08/9 EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected : 338

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

A

Com

Com

Dia

Des

Exp

Ru

Pro

Ope

Dev

Pro

Kit

Aut

Sub

Pro

Mar

Cha

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD8M-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : VA38 CHARACTER GENERATOR TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : VA38

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD8T-A0

~~PRODUCT IDENTIFICATION~~

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : SIM 360/IBMs 360 CHANNEL SIMULATOR

~~PRODUCT COMPONENTS AFFECTED~~

~~PRODUCTS OBSOLETED~~

~~PROBLEM/DESCRIPTION~~

~~SOLUTION/CORRECTION~~

~~PRODUCT CHARACTERISTICS~~

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected : DX08 DX38 DX36

Problem Reports Affected :

Kit Number :

~~AUTHORIZATION~~

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : M0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD8U-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : DX08-S 360 DIAGNOSTICS EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : DX08 DX38 DX36

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel

Submitting Engineer : J Vrobel

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group : DIAG

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T Davies

Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DGDRA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : DR8-EA DIAGNOSTIC TPL PDP-8

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 93 94

Operational Environment : 00

Device Affected : DR8EA DW8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : M HARE

Submitting Engineer : M HARE

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-C0000

Maintaining Group :

Maintainer :

Field Service Engineer :

Release Engineer :

Coordination Number :

: DIAG

: MISNER

:

: T.DAVIES

: MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHAFA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : CDP/GLC-8E DIAGNOSTIC

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : CDP/GLC0

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T DAVIES
Coordination Number : MC0000

A

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIQCA-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : Family of 8 System Exerciser Linctape kit

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 12

Operational Environment : 40

Device Affected : TC12

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : L. BEYERSDOFER

Submitting Engineer : L. Beyersdofer

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group :

Maintainer :

Field Service Engineer :

Release Engineer :

Coordination Number :

: DIAG

: MISNER

: T. DAVIES

: MC0000

A

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHKLA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-May-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : KL8M MODEM CONTROL DIAGNOSTICS

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91

Operational Environment : 00

Device Affected : KL8M

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : K. WHITNEY

Submitting Engineer : K. WHITNEY

Product Engineer :

Manufacturing Engineer :

Charge Number : V18-05806

Maintaining Group : DIAG

Maintainer : VROBEL

Field Service Engineer :

Release Engineer : T. DAVIES

Coordination Number : MC0000

A

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHVTA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-May-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : VT8-E VIDEO DISPLAY TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : VT8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHVTB-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-May-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : VT8-E VIDEO DISPLAY TEST 2

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected : VT8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D01-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : INSTRUCTION TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

Com

Com

Dia

Des

Exp

Run

Pro

Ope

Dev

Pro

Kit

Aut

Sub

Pro

Mar

Cha

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D03-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : BASIC JMP-JMS TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

Com

Com

Dia

Des

Exp

Rur

Pro

Ope

Dev

Pro

Kit

Aut

Sub

Pro

Mar

Cha

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D04-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : RANDOM JMP TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

Com

Com

Dia

Des

Exp

Run

Pro

Ope

Dev

Pro

Kit

Aut

Sub

Pro

Man

Cha

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D05-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : RANDOM JMP-JMS TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

Con

Com

Diag

Des

Exp

RUN

Pro

Oper

Dev

Pro

Kit

Aut

Sub

Pro

Man

Cha

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : 6

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D06-A0

~~PRODUCT IDENTIFICATION~~

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : RANDOM DCA TEST

~~PRODUCT COMPONENTS AFFECTED~~

~~PRODUCTS OBSOLETE~~

~~PROBLEM/DESCRIPTION~~

~~SOLUTION/CORRECTION~~

~~PRODUCT CHARACTERISTICS~~

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

~~AUTHORIZATION~~

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

Co

Co

Di

De

Exp

RU

Pr

Op

De

Pr

Ki

AU

Su

Pr

Ma

Ch

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D07-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : RANDOM ISZ TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D1E00-?0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : Extended Memory Checker Board

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93

Operational Environment : 00

Device Affected : MM8 MM8I

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B. Hansen
Submitting Engineer : Hansen
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : Hansen
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D1G-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : PDP-8L EXTENDED MEMORY CONTROL (8K

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 94

Operational Environment : 00

Device Affected : KM8L

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D1H-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : PDP-8L EXTENDED MEORY CONTROL (12K)

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 94

Operational Environment : 00

Device Affected : KM8L

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : 9

Component Part Number :

Component Part Description :

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : MD-08-D1H00-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : Extended Memory Address Test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected : MM8 MM8I

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J. Vrobel
Submitting Engineer : J. Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D1L-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : PDP-8S MEMORY ADDRESS TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : MD-08-D1L00-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : Basic Memory Checkerboard (low)

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J. Vrobel
Submitting Engineer : Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : New

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-D2000-A0

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : CR03 Card Reader Test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : CR03

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : Vrobel
Submitting Engineer : Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : MD-08-D2800-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : LT08 Teleprinter Test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : Vrobel
Submitting Engineer : Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

A

Component Part Description : ECO Purpose : New Approved : Yes
 -----PRODUCT IDENTIFICATION-----
 Diagnostic Package Code : MD-08-D2A-A0 Patch Level : 0 Product Date : 21-Jun-74
 Description : 1ST Copyright year : 1974 Last Copyright Year : 1974

Expanded Description : DC02 Family-of-Eight Teletype Test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes
 Processors :
 Operational Environment : 00
 Device Affected : PT08 LT08 DC02 ASR35
 Problem Reports Affected :
 Kit Number :

-----AUTHORIZATION-----

Author	: Vrobel	Maintaining Group	: Diag.
Submitting Engineer	: Vrobel	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: D. Fuller
Charge Number	: V00-00000	Coordination Number	: MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-D2N00-80

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : CR01C Card Reader Test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : CR01C

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : Vrobel

Submitting Engineer : Vrobel

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group

Maintainer

Field Service Engineer

Release Engineer

Coordination Number

: Diag.

: MISNER

:

: D. Fuller

: MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-D4F-80

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : Pec Incremental Tape Random Exerciser

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93 94 89

Operational Environment : 00

Device Affected : TR02 TU20

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : John Vrobel

Submitting Engineer : Vrobel

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group :

Maintainer : MISNER

Field Service Engineer :

Release Engineer : Fuller

Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : New

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-D5A-A0

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : PDP-8L memory parity IOT test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 94

Operational Environment : 00

Device Affected : MP8L

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : Vrobel
Submitting Engineer : Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : Fuller
Coordination Number : MC0000

A

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D5D-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : Multi-user Disk Exerciser

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 93

Operational Environment : 00

Device Affected : DF32

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : Vrobel
Submitting Engineer : Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : Fuller
Coordination Number : MC0000

OF 1
B

A

Co

Co

Di

De

Ex

RU

Pr

Op

De

Pr

Ki

AL

SU

Pr

Ma

Ch

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D8B-B0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : TIME SHARE 8 HDWR EXEC

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 93

Operational Environment : 00

Device Affected : DC08

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D8VB-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : KW08S CLOCK TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : KW08

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D9I-B0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : WIRE STORAGE INTERFACE DIAG

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : DC04C

Program Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VORBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DBINA-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : SELF-START BINARY LOADER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 89

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J.VROBEL
Submitting Engineer : J.VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D.BEAUSOLEIL
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD3F-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : INCREMENTAL TAPE DELAY TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 94 93 89

Operational Environment : 00

Device Affected : TR02 TU20

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T DAVIES
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD4C-B0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : INCREMENTAL TAPE COMPATIBILITY (PDP-8I,8L)

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 94 93

Operational Environment : 00

Device Affected : TR02 TU20

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD4D-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : INCREMENTAL TAPE DATA RELIABILITY

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93 94 89

Operational Environment : 00

Device Affected : TR02 TU20

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD4E-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : PEC INCREMENTAL TAPE INSTRUCTION TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 94 93 89

Operational Environment : 00

Device Affected : TR02 TU20

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL

Submitting Engineer : J VROBEL

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T DAVIES
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD8G-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : DB88 TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : DB88

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

~~PRODUCT IDENTIFICATION~~

Diagnostic Package Code : MD-08-DD8I-B0

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : DB08A TEST

~~PRODUCT COMPONENTS AFFECTED~~

~~PRODUCTS OBSOLETED~~

~~PROBLEM/DESCRIPTION~~

~~SOLUTION/CORRECTION~~

~~PRODUCT CHARACTERISTICS~~

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : DB08

Problem Reports Affected :

Kit Number :

~~AUTHORIZATION~~

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T DAVIES
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

~~PRODUCT IDENTIFICATION~~

Diagnostic Package Code : MD-08-DD8X-A0

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : XOR BUFFER OPTION DIAGNOSTICS

~~PRODUCT COMPONENTS AFFECTED~~

~~PRODUCTS OBSOLETED~~

~~PROBLEM/DESCRIPTION~~

~~SOLUTION/CORRECTION~~

~~PRODUCT CHARACTERISTICS~~

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : CPUXOR

Problem Reports Affected :

Kit Number :

~~AUTHORIZATION~~

Author : J Vrobel

Submitting Engineer : J Vrobel

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group

: DIAG

Maintainer

: MISNER

Field Service Engineer

:

Release Engineer

: T Davies

Coordination Number

: MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : AC-08-QEACA-A0

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : SYSTEM MONITOR

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment :

Device Affected : ACT8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL

Maintaining Group : DIAG

Submitting Engineer : J VROBEL

Maintainer : J VROBEL

Product Engineer :

Field Service Engineer :

Manufacturing Engineer :

Release Engineer : T.DAVIES

Charge Number : V00-00000

Coordination Number : MC0000

A

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AC-08-QEACB-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : MINI MONITOR

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment :

Device Affected : ACT8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN

Submitting Engineer : B HANSEN

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group :

: DIAG

Maintainer :

: B HANSEN

Field Service Engineer :

Release Engineer :

: T.DAVIES

Coordination Number :

: MC0000

A
Co
Co
Di
De
Ex
Ru
Pr
Op
De
Pr
Ki
Au
Su
Pr
Ma
Ch

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DGMCA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1970

Last Copyright Year : 1974

Expanded Description : PDP-8, 8I, 8S EXTENDED MEMORY CNTRL TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 93 12

Operational Environment : 00

Device Affected : MC8I MC12

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : R MOORE
Submitting Engineer : R MOORE
Product Engineer : R MOORE
Manufacturing Engineer :
Charge Number : V99-06225

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0658

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHCMA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : 80 COL OPTICAL CARD READER TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : CM8F

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : BILL HEAVEY
Submitting Engineer : BILL HEAVEY
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHCMA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : 80 COL OPTICAL CARD READER TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : CM8F

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : BILL HEAVEY
Submitting Engineer : BILL HEAVEY
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

Diagnostic Package Code : MD-08-DIDFB-A0

Description :

Expanded Description : DF32 DISKLESS LOGIC TEST

ECO Purpose : Change

Approved : Yes

Patch Level : 0

Product Date : 21-Jun-74

1ST Copyright year : 1974

Last Copyright Year : 1974

-----PRODUCT IDENTIFICATION-----

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88 93 94 89

Operational Environment : 00

Device Affected : DF32

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author	: B HANSEN	Maintaining Group	: DIAG
Submitting Engineer	: B HANSEN	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: T.DAVIES
Charge Number	: V00-00000	Coordination Number	: MC0000

A

DIGITAL EQUIPMENT CORPORATION

PAGE 1 OF 1

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIDFC-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : INTERFACE ADDR DISK DATA TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 93 94 89

Operational Environment : 00

Device Affected : DF32 DF32D

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO Purpose : Change Approved : Yes

Diagnostic Package Code : MD-08-DIH-A0 Patch Level : 0 Product Date : 21-Jun-74

Description : 1ST Copyright year : 1974 Last Copyright Year : 1974

Expanded Description : PDP-8L extended memory control (12K)

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes
 Processors : 94
 Operational Environment : 00
 Device Affected : KM8L
 Problem Reports Affected :
 Kit Number :

-----AUTHORIZATION-----

Author	: Vrobel	Maintaining Group	: Diag.
Submitting Engineer	: Vrobel	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: Fuller
Charge Number	: V00-00000	Coordination Number	: MC0000

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DILVA-A0

~~PRODUCT IDENTIFICATION~~

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : LV12/VL8 PRINTER/PLOTTER TEST

~~PRODUCT COMPONENTS AFFECTED~~

~~PRODUCTS OBSOLETED~~

~~PROBLEM/DESCRIPTION~~

~~SOLUTION/CORRECTION~~

~~PRODUCT CHARACTERISTICS~~

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 12

Operational Environment : 00

Device Affected : LV12 LV8 LV8E

Problem Reports Affected :

Kit Number :

~~AUTHORIZATION~~

Author : R. SHOOP
Submitting Engineer : R SHOOP
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIRTA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : RT01/02 TERMINAL DIAG

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : RT01 DC02 RT02 KL8 PT08

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : R BAKER
Submitting Engineer : R BAKER
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DUZ-C0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : TD8E DECTAPE FORMATTER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD2V-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 24-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : PA60C DIAGNOSTIC

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected : PA60C

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DDBMA-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 15-Jul-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : BM812-I EXT MEMORY DATA + CHECKERBOARD TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93 12

Operational Environment : 00

Device Affected : BM812I

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : R MOORE
Submitting Engineer : R MOORE
Product Engineer :
Manufacturing Engineer :
Charge Number : V99-06225

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0659

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D02-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jul-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : INSTRUCTION TEST PART 2

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : VOC-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Y

Diagnostic Package Code : MD-08-DOI-C0

~~PRODUCT IDENTIFICATION~~

Patch Level : 0

Product Date : 21-Jul-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : INSTRUCTION TEST PART 1

~~PRODUCT COMPONENTS AFFECTED~~

~~PRODUCTS OBSOLETED~~

~~PROBLEM/DESCRIPTION~~

~~SOLUTION/CORRECTION~~

~~PRODUCT CHARACTERISTICS~~

Run Time (seconds) 1st Pass :

2nd Pass :

ACI Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

~~AUTHORIZATION~~

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-D28-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jul-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : LT08 TELEPRINTER TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : LT08

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DBA-80

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jul-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : BINARY LOADER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD8W-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : C

Product Date : 21-Jul-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : DC02 TELETYPE FLAG TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 12 94 93

Operational Environment :

Device Affected : DC02

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T davies
Coordination Number : M00000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD8P-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 19-Aug-74

Description :

1ST Copyright year : 1968

Last Copyright Year : 1974

Expanded Description : PT08 DATA PHONE

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : PT08B PT08C

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : A Rickens
Submitting Engineer : A Rickens
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-D4C-A0

Patch Level : 0

Product Date : 21-Aug-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : PDP 8I MEMORY PARITY IOT TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93

Operational Environment : 00

Device Affected : MP8I

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : J VROBEL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHMRP-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Aug-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : MR80RB 2K PROM INTERNAL TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment : 00

Device Affected : MR8FB

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : W HEAVEY
Submitting Engineer : W HEAVEY
Product Engineer :
Manufacturing Engineer :
Charge Number : V18-06806

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0656

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description : ECO Purpose : Change Approved : Yes
 -----PRODUCT IDENTIFICATION-----
 Diagnostic Package Code : MD-08-DIVTB-A0 Patch Level : 0 Product Date : 21-Aug-74
 Description : 1ST Copyright year : 1974 Last Copyright Year : 1974

Expanded Description : VT20 HOST COMPUTER PROGRAM
 -----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----
 THIS PROGRAM IS A KL8-JA DATA HANDLING ROUTINE TO BE USED
 WITH MD-11-DBVTA(VT20 DIAGNOSTIC TEST), TEST 21.

-----PRODUCT CHARACTERISTICS-----
 Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88
 Operational Environment :
 Device Affected :
 Problem Reports Affected :
 Kit Number :

-----AUTHORIZATION-----
 Author : ED BADGER Maintaining Group : DIAG
 Submitting Engineer : ED BADGER Maintainer : MISNER
 Product Engineer :
 Manufacturing Engineer : Field Service Engineer :
 Charge Number : V00-00000 Release Engineer : J.DAVIES
 Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AC-08-QJACA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Oct-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : PDP-8/A LOADER/MONITOR FOR ACT-8/A

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

PDP8/A LOAD MONITOR FOR ACT 8/A

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 06

Device Affected : ACT 8/A APT 8/A

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : M. HARE
Submitting Engineer : M. HARE
Product Engineer :
Manufacturing Engineer :
Charge Number : V18-07573

Maintaining Group : DIAG
Maintainer : M. HARE
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0711

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DJMSA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Oct-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : 1-4K MS8-A MOS MEMORY TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 92

Operational Environment : 00

Device Affected : MS8A ACT8/E ACT8/A CPUXOR

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : DALE HECK
Submitting Engineer : DALE HECK
Product Engineer :
Manufacturing Engineer :
Charge Number : V61-07730

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0027

A

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DDTFB-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 01-Dec-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : DECTAPE FORMATTER PROGRAM TC

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : M MITCHELL
Submitting Engineer : M MITCHELL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

OF 1

A

DIGITAL EQUIPMENT CORPORATION

PAGE 1 OF 1

A
Cor
Cor
Di
De
Exp
Ru
Pr
Op
De
Pr
Ki
AU
Su
Pr
Ma
Ch

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DJEXA-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 15-Dec-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : 1K TO 32K RANDOM MEMORY REFERENCE INSTRUCTION EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 92

Operational Environment : 00

Device Affected : KK8A APT8/A

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN

Submitting Engineer : B HANSEN

Product Engineer :

Manufacturing Engineer :

Charge Number : V61-07730

Maintaining Group

: DIAG

Maintainer

: MISNER

Field Service Engineer

:

Release Engineer

: T.DAVIES

Coordination Number

: MC0028

A

Co

Co

Di

De

Ex

RU

Pr

Op

De

Pr

Ki

Au

Su

Pr

Ma

Ch

A

OF 1
B

OF 1

A

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIQAA-D0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Jan-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1975

Expanded Description : DEC/X8 PROCEDURE ABSTRACT FOR CUSTOMIZED EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91 92 88 12 94 93

Operational Environment : 50 40

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J. Vrobel
Submitting Engineer : J. Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V18-06806

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T. Davies
Coordination Number : MC0000

A
Co
Co
Di
De
Ex
C
Pa
DJ
R
Pr
Op
De
Pr
Ki
A
Su
Pr
Ma
Ch

Component Part Description : ECO Purpose : Change Approved : Yes
 -----PRODUCT IDENTIFICATION-----
 Diagnostic Package Code : MD-08-DJEXB-A0 Patch Level : 0 Product Date : 15-Jan-75
 Description : 1st Copyright year : 1974 Last Copyright Year : 1975
 Expanded Description : 2K TO 32K PDP-8A PROCESSOR EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----
 Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 92
 Operational Environment : 00
 Device Affected : KK8A DKC8AA APT8A MS8A
 Problem Reports Affected :
 Kit Number :

-----AUTHORIZATION-----

Author	: B HANSEN	Maintaining Group	: DIAG
Submitting Engineer	: B HANSEN	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: T.DAVIES	Release Engineer	: T.DAVIES
Charge Number	: V18-07573	Coordination Number	: MC0821

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DJKMA-A0

Patch Level : 0

Product Date : 15-Jan-75

Description :

1ST Copyright year : 1974

Last Copyright Year : 1975

Expanded Description : KM8-A OPTION TEST #2

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 92

Operational Environment : 00

Device Affected : KM8A APT8/A CPUXOR

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V18-06806

Maintaining Group : DIAG
Maintainer : HANSEN
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1026

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DJMRD-A0

Patch Level : 0

Product Date : 15-Jan-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1975

Expanded Description : PDP8/A MR8-A CONVERSION

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 92 89

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number : ZF211

-----AUTHORIZATION-----

Author : HANK POULTER

Submitting Engineer : POULTER

Product Engineer :

Manufacturing Engineer :

Charge Number : V18-08202

Maintaining Group :

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC0018

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DHKAD-A0

Patch Level : 0

Product Date : 17-Mar-75

Description :

1ST Copyright year : 1971

Last Copyright Year : 1975

Expanded Description : MEMORY ADDRESS TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91

Operational Environment : 00 50

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : D MACOMBER

Submitting Engineer : D MACOMBER

Product Engineer :

Manufacturing Engineer :

Charge Number : V18-08202

Maintaining Group : DIAG

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC1340

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DIUDA-B0

Patch Level : 0

Product Date : 21-Jun-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : UDC8 SYSTEM FUNCTION EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
DIUDA-B-D		DIUDA-B-PB					

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : UDC-8

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author	: J VROBEL	Maintaining Group	: PRO ENH
Submitting Engineer	: J VROBEL	Maintainer	: VROBEL
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. VROBEL	Release Engineer	: T.DAVIES
Charge Number	: V00-00000	Coordination Number	: MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DIUDA-C0

Patch Level : 0

Product Date : 07-May-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : UDC8 SYSTEM FUNCTION EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
DIUDA-C-D		DIUDA-C-PB					

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

COUNTER MODULES (W734)

1. ERROR TYPEOUT THAT COUNTER INTERRUPTED BEFORE OVERFLOW IF ANY W734 WERE LOCATED IN SLOT #1.
2. FREQUENCY TOLERANCE OF 3% BETWEEN COUNTS.

-----SOLUTION/CORRECTION-----

1. ON INTERRUPT FROM COUNTER THAT WAS NOT UNDER TEST, A TEST PARAMETER THAT WAS USED BY THE COUNTER UNDER TEST WAS BEING USED BUT NOT RESTORED, NOT IT IS.
2. RAISED FREQUENCY TOLERANCE TO 6%.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : UDC-8

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author	: E. BADGER	Maintaining Group	: CRO PRO
Submitting Engineer	: E. BADGER	Maintainer	: MISNER
Product Engineer	: P. POMERGY	Field Service Engineer	: L. GOELZ
Manufacturing Engineer	: R. SAVELL	Release Engineer	: T.DAVIES
Charge Number	: V00-00000	Coordination Number	: MC0622

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AC-08-QHMKA-D0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 15-Apr-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1976

Expanded Description : 2223 16K11U MEMORY EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : K. FISHER
Submitting Engineer : K FISHER
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : K FISHER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHTSF-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 15-Apr-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1975

Expanded Description : TM8-E/TS03 UTILITY DRIVER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : TM8E TS03

Problem Reports Affected :

Kit Number : ZF220

-----AUTHORIZATION-----

Author : R BARNES
Submitting Engineer : R BARNES
Product Engineer :
Manufacturing Engineer :
Charge Number : V98-05104

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1238

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DJADA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 22-Apr-75

Description :

1ST Copyright year : 1974

Last Copyright Year : 1975

Expanded Description : A/D CONVERTER MULTIPLEXER DIAG

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
DJADA-B-D		DJADA-B-PB		DJADA-B-UA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

1. PRINTS THE WRONG MAINDEC NUMBER IN THE TITLE.
2. DISPLAYS THE WRONG MAINDEC NUMBER IN THE HEADER FOR EACH PAGE.
3. GIVES THE WRONG NUMBER OF SWITCH REGISTER BITS TO BE USED IN THE DOCUMENTATION.

-----SOLUTION/CORRECTION-----

1. CHANGE THE MAINDEC # IN THE TITLE PRINTOUT.
2. CHANGE THE MAINDEC # IN THE HEADER OF EACH PAGE.
3. CHANGE IN THE DOCUMENTATION REGARDING THE # OF SWITCH REGISTER BITS TO BE USED.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : AD8A PDP8

Problem Reports Affected :

Kit Number : ZF216

-----AUTHORIZATION-----

Author	: V. BREUER	Maintaining Group	: CRO PRO
Submitting Engineer	: V. BREUER	Maintainer	: SHOOP
Product Engineer	: G. SIROIS	Field Service Engineer	: B. O'DONNELL
Manufacturing Engineer	: J. INGLEUDE	Release Engineer	: T.DAVIES
Charge Number	: V00-00000	Coordination Number	: MC4618

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIVTC-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Apr-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1975

Expanded Description : VT55 VIDEO TERMINAL ACCEPTANCE TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : VT55

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : V BREVER
Submitting Engineer : V BREVER
Product Engineer :
Manufacturing Engineer :
Charge Number : V84-07763

Maintaining Group : CPL-MR
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHMEA-B0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 15-May-75

Description :

1ST Copyright year : 1974

Last Copyright Year : 1975

Expanded Description : PDP-8 DIAGNOSTICS MEDIUM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : RK8E RK05 RX8E RX01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HEAVEY
Submitting Engineer : B HEAVEY
Product Engineer :
Manufacturing Engineer :
Charge Number : V18-06806

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0973

OF 1

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

Co

Co

Di

De

Ex

RU

Pr

Op

Ca

Pr

Ki

Al

Sc

Pr

Ma

Ch

A

Co

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change
Patch Level : 0

Approved : Yes

Diagnostic Package Code : MD-08-DJKMA-B0

Product Date : 15-Jul-75

Description :

1ST Copyright year : 1974

Last Copyright Year : 1975

Expanded Description : K8-A OPTION TEST #2

PRODUCT COMPONENTS AFFECTED

Component Part Number	Media Variable						
DJKMA-B-D		DJKMA-B-FA		DJKMA-B-PB		DJKMA-B-UA	

PRODUCTS OBSOLETE

PROBLEM/DESCRIPTION

SOLUTION/CORRECTION

PRODUCT CHARACTERISTICS

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 92

Operational Environment : 00

Device Affected : K8-A

Problem Reports Affected :

Kit Number : ZF010 ZF206 ZF209

AUTHORIZATION

Author	: B HANSEN	Maintaining Group	: PRO ENH
Submitting Engineer	: B. HANSEN	Maintainer	: VROBEL
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. VROBEL	Release Engineer	: S. DUMDEY
Charge Number	: V18-06806	Coordination Number	: MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHMAA-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Jun-75

Description :

1ST Copyright year : 1974

Last Copyright Year : 1975

Expanded Description : 2223 8K11L MEMORY EXERCISER PROGRAM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : G PAPA ZIAN
Submitting Engineer : G PAPA ZIAN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AC-08-QHMGA-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Jun-75

Description :

1ST Copyright year : 1974

Last Copyright Year : 1975

Expanded Description : 2223 8K8EJ MEMORY EXERCISER PROGRAM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment :

Device Affected : MM8E MM8EJ

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : G. PAPA ZIAN

Submitting Engineer : G. PAPA ZIAN

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group

: DIAG

Maintainer

: G. PAPA ZIAN

Field Service Engineer

:

Release Engineer

: T.DAVIES

Coordination Number

: MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

OF 1
B

A
Co
Co
Di
De
Ex
Ru
Pr
Op
De
Pr
Ki
Au
Su
Pr
Ma
Ch

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AC-08-QHMSA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Jun-75

Description :

1ST Copyright year : 1974

Last Copyright Year : 1975

Expanded Description : 2223 MS8AA MEMORY EXERCISER PROGRAM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment :

Device Affected : MS8AA

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : G. PAPAIZAN
Submitting Engineer : G. PAPAIZAN
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : G. PAPAIZAN
Field Service Engineer :
Release Engineer : T. DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHTSE-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Jun-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1975

Expanded Description : TM8-E/TS03 DRIVE FUNCTION TIMER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : TM8E TS03

Problem Reports Affected :

Kit Number : ZF222

-----AUTHORIZATION-----

Author : R BARNES

Submitting Engineer : R BARNES

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group :

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DJH7A-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Jun-75

Description :

1ST Copyright year : 1974

Last Copyright Year : 1975

Expanded Description : G8016 Power Supply Diagnostics

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected : G8016

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : M. Sandler
Submitting Engineer : M. Sandler
Product Engineer :
Manufacturing Engineer :
Charge Number : V18-07573

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : D. Fuller
Coordination Number : MC0000

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A
Co

Co
Di

De
Ex

C
Pa
DH

Ru
Pr

Op
De

Pr
Ki

Al
Su
Pr
Ma
Ch

A
Co

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DCLMA-A0

Patch Level : 0

Product Date : 15-Jul-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1975

Expanded Description : CL8 MAINTENANCE GUIDE

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 92

Operational Environment :

Device Affected : CL8 DS310 CMS1 CLASSIC

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B MJOS
Submitting Engineer : B MJOS
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DJCLA-A0

Patch Level : 0

Product Date : 11-Aug-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1975

Expanded Description : CL8 OPTIN TEST 1 AND 2

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 92

Operational Environment : 00

Device Affected : DKC8AA KM8A

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN

Submitting Engineer : B HANSEN

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group :

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC0000

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHKAF-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 12-Aug-75

Description :

1ST Copyright year : 1971

Last Copyright Year : 1975

Expanded Description : PDP-8/E INSTRUCTION TEST 1

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

REPLACES MD-8E-DOAB

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00 50

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : D.MACOMBER

Submitting Engineer : D.MACOMBER

Product Engineer :

Manufacturing Engineer :

Charge Number : V97-04110

Maintaining Group :

Maintainer : DIAG

Field Service Engineer :

Release Engineer :

Coordination Number :

: MISNER

: D.BEAUSOLEIL

: MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DHKAC-A0

Patch Level : 0

Product Date : 15-Aug-75

Description :

1ST Copyright year : 1971

Last Copyright Year : 1975

Expanded Description : MM8E MEMORY CHECKERBOARD

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91

Operational Environment : 00 50

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : D MACOMBER

Submitting Engineer : D MACOMBER

Product Engineer :

Manufacturing Engineer :

Charge Number : V18-08202

Maintaining Group :

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC1343

OF 1
R

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : MD-08-DHKEB-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 19-Jun-76

Description :

1ST Copyright year : 1972

Last Copyright Year : 1976

Expanded Description : KE8E (EAE) INSTRUCTION TEST 1

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
DHKEB-A-PB		DHKEB-A-UA		DHKEB-A-D			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THE PURPOSE OF THIS DECO IS TO ANNOUNCE THE NEW REVISION OF THE KE8-A INSTRUCTION TEST 1 PROGRAM. THE PROGRAM WAS UPDATED TO RUN AUTOMATICALLY ON THE APT-8 TEST SYSTEM. THIS REPLACES 8E-DOLB.

-----SOLUTION/CORRECTION-----

REPLACES MD-8E-DOLB

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88
Operational Environment : 00 20 99

Device Affected : KE8-E

Problem Reports Affected :

Kit Number : ZF011 ZF139 ZF013

-----AUTHORIZATION-----

Author	: D RICE	Maintaining Group	: DIAG
Submitting Engineer	: D RICE	Maintainer	: J VROBEL
Product Engineer	:	Field Service Engineer	: B. EASH
Manufacturing Engineer	: B. KELLICKER	Release Engineer	: S. DUMDEY
Charge Number	: V97 -04518	Coordination Number	: MC0666

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change
Patch Level : 0

Approved : Yes

Diagnostic Package Code : MD-08-DHKGA-B0

Product Date : 15-Aug-75

Description :

1ST Copyright year : 1972

Last Copyright Year : 1975

Expanded Description : KG8-EA DIAGNOSTICS

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 92

Operational Environment : 00

Device Affected : KG8EA

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : DAVIS-POULTER
Submitting Engineer : POULTER
Product Engineer :
Manufacturing Engineer :
Charge Number : V97-04110

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DJKKB-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Aug-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1975

Expanded Description : PDP8A CPU TEST WITH CONSOLE PACKAGE

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 92 89

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number : ZF008 ZF009

-----AUTHORIZATION-----

Author : HARE-POULTER
Submitting Engineer : POULTER
Product Engineer :
Manufacturing Engineer :
Charge Number : V18-06806

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1035

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AC-08-QHMB-A-80

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 09-Oct-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1975

Expanded Description : 2223 8K8AA MEMORY EXERCISER PROGRAM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89

Operational Environment :

Device Affected : 2223D

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : G. PAPA ZIAN
Submitting Engineer : KAY FISHER
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : JOHN VROBEL
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

OF 1
B

A
C
C
D
D
E
R
P
O
D
P
K
A
S
P
M
C

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Patch
-----PRODUCT IDENTIFICATION-----

Approved : Yes

Diagnostic Package Code : MD-08-DHDRH-A1

Patch Level : 1

Product Date : 15-Oct-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1975

Expanded Description : DR8-ED EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : DR8ED

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : E BADGER
Submitting Engineer : ED BADGER
Product Engineer :
Manufacturing Engineer :
Charge Number : V58-08127

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : J. DAVIES
Coordination Number : MC1239

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHLKB-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Oct-75

Description :

1ST Copyright year : 1971

Last Copyright Year : 1975

Expanded Description : KL8M KL8E/F DC08H ONLINE TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00

Device Affected : KL8E KL8M DC08H KL8F

Problem Reports Affected :

Kit Number : ZF145

-----AUTHORIZATION-----

Author : B HANSEN

Submitting Engineer : B HANSEN

Product Engineer :

Manufacturing Engineer :

Charge Number : V18-08202

Maintaining Group :

Maintainer : MISMER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC1276

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DILAB-D0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Oct-75

Description :

1ST Copyright year : 1974

Last Copyright Year : 1975

Expanded Description : LA36 TERMINAL DIAGNOSTICS

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 12

Operational Environment : 00

Device Affected : LA36 LA35 LA37

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : R BAKER
Submitting Engineer : R BAKER
Product Engineer :
Manufacturing Engineer :
Charge Number : V98-06691

Maintaining Group : DIAG
Maintainer : J VROBEL
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0238

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHDKA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Nov-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1975

Expanded Description : DK8E CLOCKS DIAGNOSTIC

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00

Device Affected : DK8EA DK8EP DK8EC DK8ES

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J VROBEL

Submitting Engineer : J VROBEL

Product Engineer :

Manufacturing Engineer :

Charge Number : V18-08202

Maintaining Group : DIAG

Maintainer : J VROBEL

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC1331

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHKAA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Nov-75

Description :

1ST Copyright year : 1973

Last Copyright Year : 1975

Expanded Description : 8E ADDER TESTS

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00 50

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : D MACOMBER

Submitting Engineer : D MACOMBER

Product Engineer :

Manufacturing Engineer :

Charge Number : V18-08202

Maintaining Group : DIAG

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC1344

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change
-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Approved : Yes

Diagnostic Package Code : MD-08-DHKAG-A0

Product Date : 15-Nov-75

Description :

1ST Copyright year : 1971

Last Copyright Year : 1975

Expanded Description : PDP8/E INSTRUCTION TEST 2

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

OBSOLETE MD-8E-DOBB

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00 40

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : D MACOMBER
Submitting Engineer : D MACOMBER
Product Engineer :
Manufacturing Engineer :
Charge Number : V18-08202

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1344

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change
-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Approved : Yes

Diagnostic Package Code : AC-08-QHMRD-A0

Product Date : 15-Nov-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1975

Expanded Description : MR8-FB PROM DIAG

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

NEW PROGRAM MR8-FB PROM DIAGNOSTICS CREATED TO RUN
(EXCLUSIVELY) ON APT8A

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected : MR8FB

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : D. MACOMBER
Submitting Engineer : D. MACOMBER
Product Engineer :
Manufacturing Engineer :
Charge Number : V18-08202

Maintaining Group : DIAG
Maintainer : D. MACOMBER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1345

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : AC-08-QHSEC-D0

Patch Level : 0

Product Date : 15-Nov-75

Description :

1ST Copyright year : 1974

Last Copyright Year : 1975

Expanded Description : 2223 11USTK 16K/32K STACK EXERCISER PROGRAM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 90 89

Operational Environment :

Device Affected : H217 H224

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : T. SAWYER
Submitting Engineer : T SAWYER
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : K FISHER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AC-08-QHSED-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Nov-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1975

Expanded Description : 2223 STACH EXERCIS R FOR H221 AND H222 STACKS

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 90 89

Operational Environment :

Device Affected : H221 H222

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : T SAWYER
Submitting Engineer : TOM SAWYER
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : K FISHER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MCO000

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

OF 1
B

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AC-08-QHSEE-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Nov-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1975

Expanded Description : 2223 STACK EXERCISER FOR H219 STACKS

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 90 89

Operational Environment :

Device Affected : H219

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : T SAWYER
Submitting Engineer : T SAWYER
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : K FISHER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHLSA-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Dec-75

Description :

1ST Copyright year : 1972

Last Copyright Year : 1975

Expanded Description : LS8 LINEPRINTER TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 93 09 90 92 12

Operational Environment : 00

Device Affected : LS8

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : WILL HEAVEY

Submitting Engineer : W HEAVEY

Product Engineer :

Manufacturing Engineer :

Charge Number : E18-08202

Maintaining Group :

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC1374

A
C
C
D
D
E

R
P
O
D
P
K

A
S
P
M
C

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A
C

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHPBA-A0

Patch Level : 0

Product Date : 15-Dec-75

Description :

1ST Copyright year : 1975

Last Copyright Year : 1975

Expanded Description : PROM BLASTER PROGRAM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : MR873A

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : DWIGHT BAKER

Submitting Engineer : J COMEUAE

Product Engineer :

Manufacturing Engineer :

Charge Number : V23-08191

Maintaining Group :

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC0017

OF 1
B

A
C
C
D
D
E
-
R
F
O
D
P
K
-
A
S
F
M
C

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AC-08-QIKGA-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 15-Dec-75

Description :

1ST Copyright year : 1972

Last Copyright Year : 1975

Expanded Description : KG8-EA DIAGNOSTICS

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected : KG8EA

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : D. MACOMBER
Submitting Engineer : D. MACOMBER
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : D. MACOMBER
Field Service Engineer :
Release Engineer : T. DAVIES
Coordination Number : MC0000

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHVTC-D0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 25-Feb-76

Description :

1ST Copyright year : 1976

Last Copyright Year : 1976

Expanded Description : VT50-VT52 VIDEO TERMINAL ACCEPTANCE TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : VT50 VT52

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : M SANDLER

Submitting Engineer : M SANDLER

Product Engineer :

Manufacturing Engineer : V18-08202

Maintaining Group : DIAG

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC0195

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AC-08-QHICB-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 15-Mar-76

Description :

1ST Copyright year : 1976

Last Copyright Year : 1976

Expanded Description : ICS8 FILES BOX TEST PROGRAM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

NEW RELEASE OF ICS8 FILE BOX TEST TO CHECK ICS8 FILE BOX

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected : ICS8

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : K WRIGHT

Maintaining Group : DIAG

Submitting Engineer : K WRIGHT

Maintainer : K WRIGHT

Product Engineer :

Field Service Engineer :

Manufacturing Engineer :

Release Engineer : T DAVIES

Charge Number : V46-07759

Coordination Number : MC0230

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHVTD-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 19-Mar-76

Description :

1ST Copyright year : 1976

Last Copyright Year : 1976

Expanded Description : VT61 VIDEO TERMINAL ACCEPTANCE TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : VT61

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : M SANDLER
Submitting Engineer : M SANDLER
Product Engineer :
Manufacturing Engineer :
Charge Number : V18-08202

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0521

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDERPAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DJADA-C0

Patch Level : 0

Product Date : 15-May-76

Description :

1ST Copyright year : 1974

Last Copyright Year : 1976

Expanded Description : A/D CONVERTER MULTIPLEXER DIAG

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
DJADA-C-PB		DJADA-C-UA					

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

THE AD8-A DIAG HAS BEEN UPDATED TO INCLUDE THE SOFTWARE SWITCH REGISTER AND CONSOLE PACKAGE.

-----SOLUTION/CORRECTION-----

N/A

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : AD8A PDP8

Problem Reports Affected :

Kit Number : ZF216

-----AUTHORIZATION-----

Author	: V. BREUER	Maintaining Group	: SM SYS
Submitting Engineer	: V. BREUER	Maintainer	: MISNER
Product Engineer	: G. SIROIS	Field Service Engineer	: C. CLINE
Manufacturing Engineer	: B. KILLICKER	Release Engineer	: S. DUMDEY
Charge Number	: E18 -08202	Coordination Number	: MC0378

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDERPAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AC-08-QHLAA-GJ

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Apr-76

Description :

1ST Copyright year : 1975

Last Copyright Year : 1976

Expanded Description : LA36 POWER BOARD TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Changes to the LA36 Power Board, and its test procedure, have necessitated changes to QHLAA

-----SOLUTION/CORRECTION-----

RELEASE QHLAA REVISION G.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : LA36

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : R. BAKER
Submitting Engineer : R. QUENNEVILLE
Product Engineer :
Manufacturing Engineer :
Charge Number : V98-06691

Maintaining Group : DIAG
Maintainer : R. QUENNEVILLE
Field Service Engineer :
Release Engineer : T. DAVIES
Coordination Number : MC0276

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Coue : AC-08-QHMVA-C0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 15-Apr-76

Description :

1ST Copyright year : 1976

Last Copyright Year : 1976

Expanded Description : 222E MV11 MEMORY EXERCISER PROGRAM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :-

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment :

Device Affected : MMV11A,B G653 G655 H223 H225

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : K. FISHER
Submitting Engineer : K. FISHER
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : K. FISHER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

Component Part Number : DIGITAL EQUIPMENT CORPORATION PAGE 1 OF 1
DIAGNOSTIC ENGINEERING CHANGE ORDER Form : B

Component Part Description : ECO Purpose : Change Approved : Yes

Diagnostic Package Code : AC-08-QHLAB-E0 ~~PRODUCT IDENTIFICATION~~ Patch Level : 0 Product Date : 15-Jul-76

Description : 1ST Copyright year : 1975 Last Copyright Year : 1976

Expanded Description : LA180 POWER BOARD TEST

~~PRODUCT COMPONENTS AFFECTED~~

~~PRODUCTS OBSOLETE~~

~~PROBLEM/DESCRIPTION~~

Increase usage of LA180 Power Board testers now makes it desirable to have SDC support.

~~SOLUTION/CORRECTION~~

Release current version (Rev.E) of QHLAB via SDC.

~~PRODUCT CHARACTERISTICS~~

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88

Operational Environment :

Device Affected : LA180

Problem Reports Affected :

Kit Number :

~~AUTHORIZATION~~

Author	: B. BAKER	Maintaining Group	: DIAG
Submitting Engineer	: B. BAKER	Maintainer	: VROBEL
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: T.DAVIES
Charge Number	: V98-06830	Coordination Number	: MC0322

A

Component Part Number : DIGITAL EQUIPMENT CORPORATION PAGE 1 OF 1
DIAGNOSTIC ENGINEERING CHANGE ORDER Form : B

A

Component Part Number : DIGITAL EQUIPMENT CORPORATION PAGE 1 OF 1
DIAGNOSTIC ENGINEERING CHANGE ORDER Form : B

Component Part Description : ECO Purpose : Change Approved : Yes

Diagnostic Package Code : AC-08-QHMCA-D0 PRODUCT IDENTIFICATION Patch Level : 0 Product Date : 15-Jul-76

Description : 1ST Copyright year : 1975 Last Copyright Year : 1976

Expanded Description : 2223 8K11C MEMORY EXERCISER PROGRAM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88

Operational Environment :

Device Affected : MM11B MM11C MM11D MM11BP MM11CP MM11DP H221 H222 G6512

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author	: K. FISHER	Maintaining Group	: DIAG
Submitting Engineer	: K FISHER	Maintainer	: K.FISHER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: T.DAVIES
Charge Number	: V00-00000	Coordination Number	: MC0000

A

Component Part Number : DIGITAL EQUIPMENT CORPORATION PAGE 1 OF 1
DIAGNOSTIC ENGINEERING CHANGE ORDER Form : B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change
-----PRODUCT IDENTIFICATION-----

Approved : Yes

Diagnostic Package Code : MD-08-DJVKA-A0

Patch Level : 0

Product Date : 15-Jul-76

Description :

1ST Copyright year : 1976

Last Copyright Year : 1976

Expanded Description : VK8-A INTERNAL LOGIC/DISPLAY DIAGNOSTICS

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 92

Operational Environment : 00

Device Affected : VK8A APT8A

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : E18-08202

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0682

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

~~PRODUCT IDENTIFICATION~~

Diagnostic Package Code : MD-08-DHDHB-A0

Patch Level : 0

Product Date : 15-Aug-76

Description :

1ST Copyright year : 1976

Last Copyright Year : 1976

Expanded Description : DH8E BINARY LOADER

~~PRODUCT COMPONENTS AFFECTED~~

~~PRODUCTS OBSOLETED~~

~~PROBLEM/DESCRIPTION~~

~~SOLUTION/CORRECTION~~

~~PRODUCT CHARACTERISTICS~~

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 92 89 90 91

Operational Environment : 00 50

Device Affected : DH8E

Problem Reports Affected :

Kit Number :

~~AUTHORIZATION~~

Author : D ADAMS

Submitting Engineer : D ADAMS

Product Engineer :

Manufacturing Engineer :

Charge Number : V23-08191

Maintaining Group : DIAG

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC0699

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHKEC-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Aug-76

Description :

1ST Copyright year : 1972

Last Copyright Year : 1976

Expanded Description : KE8-E (EAE) INSTRUCTION TEST 2

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

REPLACES MD-8E-DOMB

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : KE8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : D RICE
Submitting Engineer : D RICE
Product Engineer :
Manufacturing Engineer :
Charge Number : V97-04518

Maintaining Group : DIAG
Maintainer : J VROBEL
Field Service Engineer :
Release Engineer : T.DAVIES
Coordinatic Number : MC0663

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DILAC-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Aug-76

Description :

1ST Copyright year : 1975

Last Copyright Year : 1976

Expanded Description : LA180 PRINTER DIAGNOSTIC

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 12

Operational Environment : 00

Device Affected : LA180

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN
Submitting Engineer : B HANSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : E18-08202

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0588

A

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DJDKA-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Aug-76

Description :

1ST Copyright year : 1974

Last Copyright Year : 1976

Expanded Description : DKC8-AA OPTION TEST #1

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : DKC8AA CPUXOR APT8A

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HANSEN

Submitting Engineer : B HANSEN

Product Engineer :

Manufacturing Engineer :

Charge Number : V18-07573

Maintaining Group : DIAG

Maintainer : B HANSEN

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHDHA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 16-Aug-76

Description :

1ST Copyright year : 1976

Last Copyright Year : 1976

Expanded Description : DH8E HOST PROGRAM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 50

Device Affected : DH8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : DAVID ADAMS

Submitting Engineer : DAVE ADAMS

Product Engineer :

Manufacturing Engineer :

Charge Number : V23-08191

Maintaining Group : DIAG

Maintainer : DAVE ADAMS

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC0698

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHDHC-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 16-Aug-76

Description :

1st Copyright year : 1976

Last Copyright Year : 1976

Expanded Description : DH8E REMOTE LOADER PROGRAM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 50

Device Affected : DH8E

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : D ADAMS

Submitting Engineer : D ADAMS

Product Engineer :

Manufacturing Engineer :

Charge Number : V23-08191

Maintaining Group

: DIAG

Maintainer

: MISNER

Field Service Engineer

:

Release Engineer

: T.DAVIES

Coordination Number

: MC0726

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DHRXA-B0

Patch Level : 0

Product Date : 15-Nov-76

Description :

1ST Copyright year : 1975

Last Copyright Year : 1976

Expanded Description : DEC/X8 MODULE FLOPPY RX8-E DISK SYSTEM EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 40

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B HEAVEY
Submitting Engineer : B Heavey
Product Engineer :
Manufacturing Engineer :
Charge Number : V89-08202

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0953

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECD Purpose : Change

Approved : Yes

Diagnostic Package Code : AC-08-QIMMA-D0

PRODUCT IDENTIFICATION

Patch Level : 0

Product Date : 15-Nov-76

Description :

1ST Copyright year : 1976

Last Copyright Year : 1976

Expanded Description : MEMORY BURN-IN PROGRAM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : B. MOORE
Submitting Engineer : B. MOORE
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : B. MOORE
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MCO000

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHKLC-D0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 06-Jan-77

Description :

1ST Copyright year : 1972

Last Copyright Year : 1976

Expanded Description : KL8-F DOUBLE BUFFERED ASYNCHRONOUS INTERFACE DIAGNOSTICS

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

PROGRAM WOULD NOT RUN STANDALONE ON THE APT 8-A TEST SYSTEM

-----SOLUTION/CORRECTION-----

UPDATE PROGRAM TO RUN STANDALONE ON THE APT 8-A TEST SYSTEM
HISTORY COUNT STARTS AT REV D

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91 92 93 94 12

Operational Environment : 00

Device Affected : KL8F

Problem Reports Affected :

Kit Number : ZF011 ZR011 ZF143

-----AUTHORIZATION-----

Author : P. COYNE
Submitting Engineer : D. RICE
Product Engineer :
Manufacturing Engineer :
Charge Number : V89-08202

Maintaining Group : SMLSYS
Maintainer : GLENN JOHNSON
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1106

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

Diagnostic Package Code : MD-08-DHRKA-E0

Description :

Expanded Description : RK8E DISKLESS CONTROL TEST

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 06-Jan-77

1ST Copyright year : 1972

Last Copyright Year : 1976

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DIAGNOSTIC WOULD FAIL WHEN TESTING WITH EXTENDED MEMORIES

-----SOLUTION/CORRECTION-----

PROGRAM WAS UPDATED TO INCLUDE 'DEPO' WHICH CORRECTED THE PROBLEM

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91 92 93 94 12

Operational Environment : 00 20 99

Device Affected : RK8E RK05F RK05J

Problem Reports Affected :

Kit Number : ZF008 ZK122 ZF177 ZF012 ZK127

-----AUTHORIZATION-----

Author : J VROBEL
Submitting Engineer : D RICE
Product Engineer :
Manufacturing Engineer : T SHALLOW
Charge Number : V89-08202

Maintaining Group : DIAG
Maintainer : G. JOHNSON
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1123

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

Comp

Comp

Diag

Desc

Exp

A GL
LAND
AND

A 'DEI
VOLA
RECO
FOR

Run

Proc

Opera

Devic

Probl

Kit M

Auth
Subm
Produ
Manu
Charg

A

Comp

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Patch

Approved : Yes

Diagnostic Package Code : MD-08-DHRKB-G1

-----PRODUCT IDENTIFICATION-----
Patch Level : 1

Product Date : 06-Jan-77

Description :

1ST Copyright year : 1972

Last Copyright Year : 1977

Expanded Description : RK8E DRIVE CONTROL TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

STATUS ERROR IN TEST 13 WHEN TESTING DRIVES OTHER THAN DRIVE 0

-----SOLUTION/CORRECTION-----

TOGGLE IN PATCH BELOW

-----DEPO PATCH AREA-----

Loc	From	To	Mnemonic	Loc	From	To	Mnemonic
0741	7301	4453		1373		5770	
0742	4453	1157					
0743	3143	4774					
0745	7640	7610					
0774		1370					
1370		0					
1371		3143					
1372		4444					

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92 93 94 12

Operational Environment : 00 20 99

Device Affected : RK8E RK05J RK05F

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author	: J.VROBEL	Maintaining Group	: SMLSYS
Submitting Engineer	: D.RICE	Maintainer	: MISNER
Product Engineer	: T.SHALLOW	Field Service Engineer	:
Manufacturing Engineer	: T.SHALLOW	Release Engineer	: D.BEAUSOLEIL
Charge Number	: V89-08202	Coordination Number	: MC1303

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

Compo

Compo

Diagn

Descr

Expans

THIS
WHICH
OF UP

COMME
THE F
THE R
START
AFTER

Run T

Proce

Opera

Devic

Probl

Kit N

Autho
Submi
Produ
Manuf
Charg

A

Compo

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHTAB-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 06-Jan-77

Description :

1ST Copyright year : 1972

Last Copyright Year : 1976

Expanded Description : TAB-E DATA RELIABILITY TEST

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
DHTAB-C-D		DHTAB-C-PB		DHTAB-C-FA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

PROGRAM WOULD NOT RUN STANDALONE OF THE APT 8-A TEST SYSTEM.

-----SOLUTION/CORRECTION-----

UPDATED PROGRAM TO RUN UNDER CONTROL OF THE APT 8-A TEST SYSTEM.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors : 90 91 92 93 94 12

Operational Environment : 00 20

Device Affected : TABE TU60

Problem Reports Affected : :

Kit Number : ZF012 ZF180

-----AUTHORIZATION-----

Author	: NONE	Maintaining Group	: SMLSYS
Submitting Engineer	: D.RICE	Maintainer	: MISNER
Product Engineer	: D.RICE	Field Service Engineer	:
Manufacturing Engineer	: KELLICHT	Release Engineer	: D.BEAUSOLEIL
Charge Number	: V89-08202	Coordination Number	: MC1107

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHTSA-B0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 16-Jan-77

Description :

1ST Copyright year : 1975

Last Copyright Year : 1977

Expanded Description : TM8-E/TS03 CONTRCL TEST PART 1

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
DHTSA-B-D		DHTSA-B-PB		DHTSA-B-FA			

-----PRODUCTS OBSOLETEFD-----

-----PROBLEM/DESCRIPTION-----

PROGRAM WOULD NOT RUN STANDALONE ON THE APT8-A TEST SYSTEM.

-----SOLUTION/CORRECTION-----

UPDATED PROGRAM TO RUN STANDALONE ON THE APT8-A TEST SYSTEM/

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors : 89 90 91 92 93 94 12

Operational Environment : 00 20

Device Affected : TM8E TS03

Problem Reports Affected :

Kit Number : ZF222

-----AUTHORIZATION-----

Author	: R.BARNES	Maintaining Group	: SMLSYS
Submitting Engineer	: D.RICE	Maintainer	: MISNER
Product Engineer	: D.RICE	Field Service Engineer	:
Manufacturing Engineer	: T.SHALLOW	Release Engineer	: D.BEAUSOLEIL
Charge Number	: V98-08202	Coordination Number	: MC1252

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

Compor

Compor

Diagnoc

Descri

Expand

Run Ti

Proces

Operat

Device

Proble

Kit Nu

Author

Submit

Produc

Manufa

Charge

A

Compor

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHTSB-B0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 16-Jan-77

Description :

1ST Copyright year : 1975

Last Copyright Year : 1977

Expanded Description : TM8-E/TS03 CONTROL TEST PART 2

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
DH. B-B-D		DHTSB-B-PB		DHTSB-B-FA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

PROGRAM WOULD NOT RUN STANDALONE ON THE APT8-A TEST SYSTEM.

-----SOLUTION/CORRECTION-----

UPDATED PROGRAM TO RUN STANDALONE ON THE APT8-A TEST SYSTEM.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors : 89 90 91 92 93 94 12

Operational Environment : 00 20

Device Affected :

Problem Reports Affected :

Kit Number : ZF222

-----AUTHORIZATION-----

Author	: R.BARNES	Maintaining Group	: SMLSYS
Submitting Engineer	: D.RICE	Maintainer	: MISNER
Product Engineer	: D.RICE	Field Service Engineer	:
Manufacturing Engineer	: T.SHALLOW	Release Engineer	: D.BEAUSOLEIL
Charge Number	: V98-08202	Coordination Number	: MC1253

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

Component

Component

Diagnostic

Description

Expanded

Run Time

Process

Operat

Device

Problem

Kit Num

Author

Submit

Product

Manufac

Change

A

Component

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHTSC-B0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 16-Jan-77

Description :

1ST Copyright year : 1975

Last Copyright Year : 1977

Expanded Description : TM8-E/TS03 DATA RELIABILITY

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
DHTSC-B-D		DHTSC-B-PB		DHTSC-B-FA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

PROGRAM WOULD NOT RUN STANDALONE ON THE APT8-A TEST SYSTEM.

-----SOLUTION/CORRECTION-----

UPDATED PROGRAM TO RUN STANDALONE ON THE APT8-A TEST SYSTEM.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors : 89 90 91 92 93 94 12

Operational Environment : 00 20

Device Affected :

Problem Reports Affected :

Kit Number : ZF222

-----AUTHORIZATION-----

Author	: R.BARNE	Maintaining Group	: SMLSYS
Submitting Engineer	: D.RICE	Maintainer	: MISNER
Product Engineer	: D.RICE	Field Service Engineer	:
Manufacturing Engineer	: T.SHALLOW	Release Engineer	: D.BEAUSOLEIL
Charge Number	: V98-08202	Coordination Number	: MC1254

A

Compon

Compon

Diagnos

Descrip

Expande

Run Tim

Process

Operati

Device

Problem

Kit Num

Author

Submit

Product

Manufac

Charge

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHTSD-B0

PRODUCT IDENTIFICATION

Patch Level : 0

Product Date : 16-Jan-77

Description :

1ST Copyright year : 1975

Last Copyright Year : 1977

Expanded Description : IM8-E/TS03 MULTIDRIVE EXERCISER

PRODUCT COMPONENTS AFFECTED							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
DHTSD-B-D		DHTSD-B-PB		DHTSD-B-FA			

PRODUCTS OBSOLETE

PROBLEM/DESCRIPTION

PROGRAM WOULD NOT RUN STANDALONE ON THE APT8-A TEST SYSTEM.

SOLUTION/CORRECTION

UPDATED PROGRAM TO RUN STANDALONE ON THE APT8-A TEST SYSTEM.

PRODUCT CHARACTERISTICS

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors : 89 90 91 92 93 94 12

Operational Environment : 00 20

Device Affected :

Problem Reports Affected :

Kit Number : ZF222

AUTHORIZATION

Author	: R.BARNES	Maintaining Group	: SMLSYS
Submitting Engineer	: D.RICE	Maintainer	: MISNER
Product Engineer	: D.RICE	Field Service Engineer	:
Manufacturing Engineer	: T.SHALLOW	Release Engineer	: D.BEAUSOLEIL
Charge Number	: V98-08202	Coordination Number	: MC1255

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHTMF-CO

PRODUCT IDENTIFICATION

Patch Level : 0

Product Date : 17-Jan-77

Description :

1ST Copyright year : 1972

Last Copyright Year : 1977

Expanded Description : TM8-E RANDOM EXERCISER

PRODUCT COMPONENTS AFFECTED

Component Part Number	Media Variable						
DHTMF-C-D		DHTMF-C-PB		DHTMF-C-FA			

PRODUCTS OBSOLETED

PROBLEM/DESCRIPTION

PROGRAM WOULD NOT RUN STANDALONE ON THE APT8-A TEST SYSTEM

SOLUTION/CORRECTION

UPDATED PROGRAM TO RUN STANDALONE ON THE APT8-A TEST SYSTEM

PRODUCT CHARACTERISTICS

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors : 89 90 91 93 94 12

Operational Environment : 00 20

Device Affected : TM8E TU10

Problem Reports Affected :

Kit Number : ZF012 ZF184

AUTHORIZATION

Author	: L.BEYERSDORFER	Maintaining Group	: SMLSYS
Submitting Engineer	: D.RICE	Maintainer	: MISNER
Product Engineer	: D.RICE	Field Service Engineer	:
Manufacturing Engineer	: T.SHALLOW	Release Engineer	: D.BEAUSOLEIL
Charge Number	: V98-08202	Coordination Number	: MC1251

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIPRA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 04-Feb-77

Description :

1ST Copyright year : 1977

Last Copyright Year : 1977

Expanded Description : PRS01 PAPER TAPE READER TOGGLE IN PROGRAM FOR KL8J

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

A PROGRAM WAS NEEDED TO AID IN INSTALLING AND MAINTAINING
PRS01 READERS ON PDP-8'S.

-----SOLUTION/CORRECTION-----

THIS TOGGLE IN PROGRAM TESTS PRS01 READER CONNECTED VIA A KL8J
OR EQUIVILENT INTERFACE.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 89 90 91 92 93 94

Operational Environment : 00

Device Affected : PRS01

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J COMEAU
Submitting Engineer : J COMEAU
Product Engineer :
Manufacturing Engineer :
Charge Number : V98-05077

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1302

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIKIA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 11-Feb-77

Description :

1ST Copyright year : 1967

Last Copyright Year : 1977

Expanded Description : PDP-8 INSTRUCTION TEST PART 2A

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

FAILURES COULD OCCUR WHEN RUNNING THIS TEST BECAUSE
OF ILLEGAL INTERRUPTS FROM AN ON-LINE LINE PRINTER.

-----SOLUTION/CORRECTION-----

ADDED AN INSTRUCTIO TO CLEAR THE LINE PRINTER DEVICE FLAG DURING
THE INITIALIZATION OF THIS DIAGNOSTIC.
NOTE: MD-08-DIKIA-A OBSOLESTES AND REPLACES MD-08-D01-A.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : No

Processors : 88 89 90 91 92 93 09 04

Operational Environment : 00

Device Affected : CPU

Problem Reports Affected :

Kit Number : ZF001

-----AUTHORIZATION-----

Author : S JENSEN

Submitting Engineer : S JENSEN

Product Engineer :

Manufacturing Engineer : W KELLICKER

Charge Number : V98-05077

Maintaining Group :

Maintainer : MISNER

Field Service Engineer : S JOHNSON

Release Engineer : T.DAVIES

Coordination Number : MC1129

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DJKKA-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Feb-77

Description :

1ST Copyright year : 1974

Last Copyright Year : 1977

Expanded Description : PDP-8A CPU TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

A GLITCH ON THE POWER LINE CAUSE A FALSE FAILURE ERROR MESSAGE
LAND THE PROCESSOR TO HALT. THIS PROBELM OCCURRS ON APT
AND PREVENTS LONG ACCEPTANCE RUNS.

-----SOLUTION/CORRECTION-----

A DELAY HAS BEEN ADDED TO THE POWER FAILURE, AFTER THE
VOLATILE INFORMATION HAS BEEN SAVED, TO ALLOW
RECOVERY FROM A GLITCH. THIS SOLUTION HAS BEEN IMPLEMENTED
FOR APT ONLY. IT DOES NOT AFFECT THE FIELD.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :	2nd Pass :	ACT Sequence Number :	Multimedia Affected : Yes
Processors : 89 90 91 92			
Operational Environment : 00 10 20			
Device Affected : KK8A			
Problem Reports Affected :			
Kit Number :			

-----AUTHORIZATION-----

Author : S JENSEN	Maintaining Group : DIAG
Submitting Engineer : S JENSN	Maintainer : MISNER
Product Engineer :	Field Service Engineer :
Manufacturing Engineer :	Release Engineer : T.DAVIES
Charge Number : V98-05077	Coordination Number : MC1064

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

Comp

Comp

Diag

Desc

Expa

Com

Part

DJMR

THIS

MAIN

AND

Run

Proc

Oper

Devic

Prob

Kit

Auth

Subm

Prodi

Manu

Char

A

Comp

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHRKC-H0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 18-Feb-77

Description :

1ST Copyright year : 1972

Last Copyright Year : 1977

Expanded Description : RK8E/RK8L DATA RELIABILITY

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

THIS DECO INTRODUCES THE 'H' REVISION OF THE PROGRAM WHICH COVERS ALL PREVIOUS DEPOS AND ALLOWS THE EXERCISING OF UP TO 8 DRIVES WITH AN RK8L CONTROLLER.

-----SOLUTION/CORRECTION-----

COMMENT: THE RK8E CONTROLLER WILL RUN 0-3 DRIVES WITH THE FAMILY OF 8 PROCESSORS. THE RK8L CONTROLLER WILL RUN 0-7 DRIVES WITH PROCESSORS STARTING WITH THE PDPPDP8-E AND '8' PROCESSORS DEVELOPED AFTER THE PDP8-E.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :	2nd Pass :	ACT Sequence Number :	Multimedia Affected : Yes
Processors	: 89 90 91 92 39 94 12		
Operational Environment	: 00 20 99		
Device Affected :	RK8E KR8L RK05J RK05J		
Problem Reports Affected :			
Kit Number	: ZF008 ZK127 ZF213 ZF012 ZF177		

-----AUTHORIZATION-----

Author	: VROBEL/HEAVEY	Maintaining Group	: SML SYS
Submitting Engineer	: W HEAVEY	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: T.DAVIES
Charge Number	: V89-08202	Coordination Number	: MC1199

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DOA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 05-Mar-77

Description :

1ST Copyright year : 1971

Last Copyright Year : 1971

Expanded Description : Memory Protect Test

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 94

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : E. Steinberger

Submitting Engineer : Steinberger

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group

Maintainer

Field Service Engineer

Release Engineer

Coordination Number

: Diag.

: MISNER

:

: Fuller

: MC0000

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

Compon

Compon

Diagn

Descri

Expand

IF RUN
SIZE M
FOR 'T
MADE I

PLEASE

Loc
10701
10763
10764
10765

Run Ti

Proces

Operat

Device

Proble

Kit Nu

Author
Submit
Produc
Manufa
Charge

A

Compon

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHLQA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Mar-77

Description :

1ST Copyright year : 1977

Last Copyright Year : 1977

Expanded Description : DEC/X8 MODULE 'LQP-8'

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 40

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : Dave Orin

Submitting Engineer : Dave Orin

Product Engineer :

Manufacturing Engineer :

Charge Number : V40-08224

Maintaining Group : DIAG

Maintainer : Dave Orin

Field Service Engineer :

Release Engineer : T Davies

Coordination Number : MC1125

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

Compon

Compon

Diagno

Descri

Expand

PROGRA
CORREC

ADDED
IF SO,
DO NOT

Run Ti

Proces

Operat

Device

Proble

Kit Num

Author
Submit
Produc
Manufa
Charge

A

Compon

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHLQB-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Mar-77

Description :

1ST Copyright year : 1977

Last Copyright Year : 1977

Expanded Description : LQP-8 MULTIPLE PRINTER DIAG

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : D ORIN
Submitting Engineer : D. ORIN
Product Engineer :
Manufacturing Engineer :
Charge Number : V40-08224

Maintaining Group : DIAG
Maintainer : G JOHNSON
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1126

A

Compon

Compon

Diagnos

Descrip

Expand

1) PROG

1) MADE
2) ADDE

Run Tim

Process

Operati

Device

Problem

Kit Num

Author
Submitt
Product
Manufac
Charge

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHPCA-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 15-Mar-77

Description :

1ST Copyright year : 1971

Last Copyright Year : 1975

Expanded Description : HIGHSPEED READER/PUNCH TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

REPLACES MD-8E-D2CA

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number : ZF011 ZF173 ZF171

-----AUTHORIZATION-----

Author : S JENSEN
Submitting Engineer : S JENSEN
Product Engineer :
Manufacturing Engineer :
Charge Number : V98-05077

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0939

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIDBA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Mar-77

Description :

1ST Copyright year : 1971

Last Copyright Year : 1977

Expanded Description : DB8-E INTERPROCESSOR BUFFER TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected :

Problem Reports Affected :

Kit Number : ZF120

-----AUTHORIZATION-----

Author : D RICE
Submitting Engineer : D RICE
Product Engineer :
Manufacturing Engineer :
Charge Number : V89-08202

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1104

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

OF 1
B

OF 1
B

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHMRB-B0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 14-Apr-77

Description :

1ST Copyright year : 1973

Last Copyright Year : 1977

Expanded Description : MR8-EA READ ONLY MEMORY TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

THE SECOND COLUMN OF INSERT ERROR PRINTOUT IS INCORRECT
FOR EVEN ADDRESSES.

-----SOLUTION/CORRECTION-----

CORRECTED INSERT ERROR PRINTOUT
ROUTINE FOR EVEN ADDRESSES TO RETRIEVE THE CORRECT DATA
FOR PRINTING
HISTORY STATS AT REV. B

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : No

Processors : 89 90 91

Operational Environment : 00

Device Affected : MR8EA

Problem Reports Affected :

Kit Number : ZF165

-----AUTHORIZATION-----

Author : S. JENSEN

Submitting Engineer : S. JENSEN

Product Engineer :

Manufacturing Engineer : T SHALLOW

Charge Number : E98-05077

Maintaining Group

: PRO ENG

Maintainer

: MISNER

Field Service Engineer

:

Release Engineer

: T.DAVIES

Coordination Number

: MC1330

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change
-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Approved : Yes

Diagnostic Package Code : MD-08-DHRKA-B0

Product Date : 21-Apr-77

Description :

1ST Copyright year : 1972

Last Copyright Year : 1977

Expanded Description : DEC/X8 MODULE 'RK8EDS'

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

MD-X8-DHRKA-A was updated to a 'B' revision to include
the capability of testing 0-7 RK05 Drives with an
RK8L Controller.

-----SOLUTION/CORRECTION-----

history count starts at REV. B.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :	2nd Pass :	ACT Sequence Number :	Multimedia Affected : Yes
Processors :	89 90 91 92 93 94		
Operational Environment :	00 20 99		
Device Affected :	RK8E RK8L		
Problem Reports Affected :			
Kit Number :	ZF229 ZK229		

-----AUTHORIZATION-----

Author :	W Heavey	Maintaining Group :	DIAG
Submitting Engineer :	W Heavey	Maintainer :	J Vrobel
Product Engineer :		Field Service Engineer :	
Manufacturing Engineer :	T Shallow III	Release Engineer :	T Davies
Charge Number :	V89-08202	Coordination Number :	MC1291

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIRXB-E0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-May-77

Description :

1ST Copyright year : 1975

Last Copyright Year : 1977

Expanded Description : RX8-RX01 DATA RELIABILITY/EXERCISER PROGRAM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

DOCUMENT INDICATE INCORRECT TRACK AND SECTOR ADDRESSES.
DIAGNOSTIC COULD NOT DETECT A RAMP MISADJUSTMENT.

-----SOLUTION/CORRECTION-----

THE DOCUMENT WAS CORRECTED TO REFLECT THE PROPER INFORMATION.
THE DIAGNOSTIC WAS UPDATED TO INCLUDE A TEST FOR THE
RAMP MISADJUSTMENT.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91 92 93 94 12

Operational Environment : 00 20 99

Device Affected : RX8E RX01

Problem Reports Affected :

Kit Number : ZF008 ZR122 ZF177 ZF012 ZF127

-----AUTHORIZATION-----

Author : M. STURAK

Submitting Engineer : D. RICE

Product Engineer :

Manufacturing Engineer : T. SHALLOW

Charge Number : V89-08202

Maintaining Group :

SML SYS

Maintainer :

G. JOHNSON

Field Service Engineer :

Release Engineer :

T. DAVIES

Coordination Number :

MC1380

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DJM RB-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 02-May-77

Description :

1ST Copyright year : 1977

Last Copyright Year : 1977

Expanded Description : MR8-SA ROM LOADER PROGRAM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THIS DECO INTRODUCES MD-08-DJM RB-A. THE MR8-SA ROM
LOADER PROGRAM IS USED TO BLAST/VERIFY MR8-A ROM
BOARDS WITH THE MR8-SA OPTION.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :	2nd Pass :	ACT Sequence Number :	Multimedia Affected : No
Processors : 89 90 91 92			
Operational Environment : 00 99			
Device Affected : MR8SA			
Problem Reports Affected :			
Kit Number : ZF204			

-----AUTHORIZATION-----

Author : W HEAVEY	Maintaining Group : DIAG
Submitting Engineer : W HEAVEY	Maintainer : MISNER
Product Engineer :	Field Service Engineer :
Manufacturing Engineer : T.SHALLOW	Release Engineer : T.DAVIES
Charge Number : V89-08202	Coordination Number : MC1554

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DJMRC-A0

Patch Level : 0

Product Date : 02-May-77

Description :

1ST Copyright year : 1977

Last Copyright Year : 1977

Expanded Description : MR8-SA ROM MAINTENANCE DIAGNOSTICS

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
DJMRC-A-D		DJMRC-A-PB		DJMRC-A-FA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THIS DECO INTRODUCES MD-08-DJMRC-A. THE MR8-SA ROM MAINTENANCE DIAGNOSTIC IS USED TO CALIBRATE, TEST AND VERIFY THE MR8-SA ROM LOADER ELECTRONICS.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors : 89 90 91 92

Operational Environment : 00 99

Device Affected : MR8SA

Problem Reports Affected :

Kit Number : ZF204

-----AUTHORIZATION-----

Author	: W HEAVEY	Maintaining Group	: DIAG
Submitting Engineer	: W HEAVEY	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: T. SHALLOW	Release Engineer	: T. DAVIES
Charge Number	: V89-08202	Coordination Number	: MC1455

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DILPE-C0

PRODUCT IDENTIFICATION

Patch Level : 0

Product Date : 04-May-77

Description :

1ST Copyright year : 1974

Last Copyright Year : 1977

Expanded Description : LP04/LP08 AND LP14 LINE PRINTER TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

THE DIAGNOSTIC NEEDED TO BE UPDATED
TO TEST THE LP14 WHICH IS A HIGHER SPEED PRINTER
AND HAS A DIFFERENT ARRANGEMENT OF THE CHARACTER ON THE DRUM.

-----SOLUTION/CORRECTION-----

ADDED A SWITCH FOR LP14'S. MODIFIED THE PRINT SPEED TEST.
FOR DIFFERENT CHARACTER ARRANGEMENT AND HIGHER SPEED.
MODIFIED HIGH SPEED PRINTER TEST AND DRUM PATTERN TEST FOR
DIFFERENT CHARACTER ARRANGEMENT.
HISTORY STARTS AT REV C

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :	2nd Pass :	ACT Sequence Number :	Multimedia Affected : Yes
Processors	: 88 89 90 91 92 93 94 12		
Operational Environment	: 00		
Device Affected :	LP05 LP08 LP14		
Problem Reports Affected :			
Kit Number	: ZF008 ZF011 ZF210		

-----AUTHORIZATION-----

Author	: S JENSEN	Maintaining Group	: DIAG
Submitting Engineer	: S JENSEN	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: T.DAVIES
Charge Number	: E98-05368	Coordination Number	: MC1331

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DIG-C0

Patch Level : 0

Product Date : 21-Jun-77

Description :

1ST Copyright year : 1974

Last Copyright Year : 1974

Expanded Description : PDP-8L Extended Memory Control (8K)

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 94

Operational Environment : 00

Device Affected : KM8L

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : Vrobel
Submitting Engineer : Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : Diag.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : Fuller
Coordination Number : MC0000

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Patch

Approved : Yes

Diagnostic Package Code : MD-08-DJFPB-B1

-----PRODUCT IDENTIFICATION-----

Patch Level : 1

Product Date : 28-Jun-77

Description :

1ST Copyright year : 1976

Last Copyright Year : 1977

Expanded Description : FPP-8A INSTURCTION TEST AND DATA EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

IF RUNNING DATA EXERCISER ON SYSTEM WITH A MEMORY
SIZE MORE THAN 16K, THE PROGRAM WILL GENERATE EXPONENTS
FOR 'TEST 15' THAT CANNOT BE ALIGNED IN CALCULATIONS
MADE IN FIELDS 4-7.

-----SOLUTION/CORRECTION-----

PLEASE MAKE THE FOLLOWING PATCH I FIELD 1:

-----DEPO PATCH AREA-----

Loc	From	To	Mnemonic	Loc	From	To	Mnemonic
10701	3014	5363					
10763	3014	3014					
10764	3014	7100					
10765	3014	5302					

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : FPP8A

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author	:	W HEAVEY	Maintaining Group	:	DIAG
Submitting Engineer	:	W HEAVEY	Maintainer	:	G JOHNSON
Product Engineer	:		Field Service Engineer	:	
Manufacturing Engineer	:		Release Engineer	:	T.DAVIES
Charge Number	:	V89-08202	Coordination Number	:	MC1453

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHLQA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 06-Jul-77

Description :

1ST Copyright year : 1977

Last Copyright Year : 1977

Expanded Description : LQP-8 PRINTER DIAGNOSTIC

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

PROGRAM NEEDS CHANGES TO MAKE COMPATINLE WITH VT78;
CORRECT POWER FAIL AND LOOP ON TEST MALFUNCTIONS.

-----SOLUTION/CORRECTION-----

ADDED CODE TO TEST IF RUNNING UNDER VT78 CONTROL.
IF SO, AVOID TESTING OF STATUS F 15 5 8 & 9 WHICH
DO NOT EXIST IN VT78 PRINTER INTERFACE.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 99

Device Affected : VT78

Problem Reports Affected :

Kit Number : ZF008 ZF014

-----AUTHORIZATION-----

Author : DAVID ORIN
Submitting Engineer : B. POLAND
Product Engineer :
Manufacturing Engineer : T SHALLOW
Charge Number : E89-09394

Maintaining Group : DIAG
Maintainer : BOB MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1459

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIRXA-D0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 06-Jul-77

Description :

1ST Copyright year : 1975

Last Copyright Year : 1977

Expanded Description : RX8/RK01 DIAGNOSTIC PROGRAM

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

1) PROGRAM NEEDS CHANGES TO MAKE COMPATIBLE FOR VT78

-----SOLUTION/CORRECTION-----

1) MADE NECESSARY CHANGES FOR COMPATIBILITY
2) ADDED NEW CONSOLE PACKAGE

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 780

2nd Pass : 780

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 92

Operational Environment : 00 22 99

Device Affected : RX8E RX01

Problem Reports Affected :

Kit Number : ZF008 ZF014 ZF010 ZF220

-----AUTHORIZATION-----

Author : B. LECOQ
Submitting Engineer : B. LECOQ
Product Engineer :
Manufacturing Engineer : T. SHALLOW
Charge Number : E89-09394

Maintaining Group : DIAG
Maintainer : BOB MISNER
Field Service Engineer :
Release Engineer : T. DAVIES
Coordination Number : MC1458

A

Component

Component

Diagnostic

Description

Expanded

Run Time

Process

Operati

Device

Problem

Kit Num

Author

Submitt

Product

Manufac

Charge

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DJEXC-B0

Patch Level : 0

Product Date : 06-Jul-77

Description :

1ST Copyright year : 1975

Last Copyright Year : 1977

Expanded Description : 4K TO 32K PDP-8A PROCESSOR EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

1) NOT COMPATIBLE FOR VT78

-----SOLUTION/CORRECTION-----

1) MADE NECESSARY CHANGES FOR VT78 COMPATIBILITY
2) ADDED NEW CONSOLE PACKAGE
HISTORY STARTS AT REV B.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 120

2nd Pass : 120

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 92

Operational Environment : 00 20 99

Device Affected : PDP8A

Problem Reports Affected :

Kit Number : ZF008 ZF014 ZF009

-----AUTHORIZATION-----

Author : BRUCE HANSEN
Submitting Engineer : B POLAND
Product Engineer :
Manufacturing Engineer : T SHALLOW
Charge Number : E89-09394

Maintaining Group : DIAG
Maintainer : BOB MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1460

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change
PRODUCT IDENTIFICATION
Patch Level : 0

Approved : Yes

Diagnostic Package Code : MD-08-DKVTA-A0

Product Date : 06-Jul-77

Description :

1ST Copyright year : 1977

Last Copyright Year : 1977

Expanded Description : VT78 MOS MEMORY DIAGNOSTIC

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 75

2nd Pass : 75

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 92

Operational Environment : 00 20 99

Device Affected : VT78

Problem Reports Affected :

Kit Number : ZF014

-----AUTHORIZATION-----

Author : B. LECOQ
Submitting Engineer : R LECOG
Product Engineer :
Manufacturing Engineer :
Charge Number : E89-09394

Maintaining Group : DIAG
Maintainer : BOB MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1456

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DKVTB-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 06-Jul-77

Description :

1ST Copyright year : 1977

Last Copyright Year : 1977

Expanded Description : VT78 CPU DIAGNOSTIC

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass : 20

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00 20 99

Device Affected : VT78

Problem Reports Affected :

Kit Number : ZF014

-----AUTHORIZATION-----

Author : B POLAND

Submitting Engineer : B POLAND

Product Engineer :

Manufacturing Engineer : T SHALLOW II

Charge Number : E89-09394

Maintaining Group : D AG

Maintainer : E S MISNER

Field Service Engineer :

Release Engineer : T.DAVIES

Coordination Number : MC1457

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIQAC-E0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 18-Jul-77

Description :

1ST Copyright year : 1976

Last Copyright Year : 1977

Expanded Description : PDP-8 MAININDEX INDEX

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

INDEX WAS UPDATE TO REFLECT CHANGES TO PDP-8 DIAGNOSTICS

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : RELENG
Submitting Engineer : C CINNAMON
Product Engineer :
Manufacturing Engineer :
Charge Number : V98-08162

Maintaining Group : RELENG
Maintainer : RELENG
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1494

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DIZAA-F0

Patch Level : 0

Product Date : 18-Jul-77

Description :

1ST Copyright year : 1976

Last Copyright Year : 1977

Expanded Description : PDP8 MULTIMEDIA

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THE FOLLOWING MULTIMEDIA REVISIONS WILL BE EFFECTIVE IN
AUGUST 1977.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : RELENG
Submitting Engineer : L. WILLIAMS
Product Engineer : RELENG
Manufacturing Engineer :
Charge Number : V98-08162

Maintaining Group : RELENG
Maintainer : RELENG
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC1493

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : MD-08-DJDKA-D0

Patch Level : 0

Product Date : 06-Jul-77

Description :

1ST Copyright year : 1974

Last Copyright Year : 1977

Expanded Description : DKC8-AA OPTION TEST #1

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
DJDKA-D-D		DJDKA-D-PB		DJDKA-D-FA		DJDKA-D-UA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

NEW MULTIPLE OPTION CONTROLLER HARDWARE REQUIRED
PROGRAM MODIFICATION AND DOCUMENT UPDATE.

-----SOLUTION/CORRECTION-----

MODIFIED AND UPDATED FOR MULTIPLE OPTION CONTROLLER
(4K VERSION ONLY)

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 92

Operational Environment : 00 99 20

Device Affected : DKC8-AA

Problem Reports Affected : CC0000753

Kit Number : ZF010 ZF206 ZF208 ZF207

-----AUTHORIZATION-----

Author	: B HANSEN	Maintaining Group	: SM SYS
Submitting Engineer	: D. ORIN	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: D. BROWN	Release Engineer	: S. DUMDEY
Charge Number	: V89 -08202	Coordination Number	: MC1469

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DJKLA-D0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 06-Jul-77

Description :

1ST Copyright year : 1975

Last Copyright Year : 1977

Expanded Description : KL8-A MULTIPLE SERIAL LINE UNIT DIAG

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
DJKLA-D-D		DJKLA-D-PB		DJKLA-D-FA		DJKLA-D-UA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

NEW MULTIPLE OPTION CONTROLLER HARDWARE REQUIRED
PROGRAM MODIFICATION.

-----SOLUTION/CORRECTION-----

CREATED CONDITIONAL ASSEMBLY SOURCES DJKLAD. SRC
AND DJKLBD. SRC AND MAIN SOURCE DJKLXD. SRC,
DJKLAD. BIN IS THE PROGRAM WITHOUT MULTIPLE
OPTION CONTROLLER CAPABILITY. DJKLBD. BIN HAS
THE MULTIPLE OPTION CAPABILITY WHICH REQUIRED
DELETION OF THE TERMINAL TEST.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 99 20

Device Affected : KL8-A

Problem Reports Affected : CC0000751

Kit Number : ZF011 ZF225

-----AUTHORIZATION-----

Author	: B HANSEN	Maintaining Group	: SM SYS
Submitting Engineer	: D. ORIN	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: D. BROWN	Release Engineer	: S. DUMDEY
Charge Number	: V89 -08202	Coordination Number	: MC1470

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DIKLA-C0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 06-Jul-77

Description :

1ST Copyright year : 1973

Last Copyright Year : 1977

Expanded Description : KL8-JA/KA/KB/KC/KD LOOP BACK TEST

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
DIKLA-C-D		DIKLA-C-PB		DIKLA-C-FA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

1. NEW MULTIPLE OPTION CONTROLLER HARDWARE REQUIRED PROGRAM MODIFICATION AND DOCUMENT UPDATE.
2. PROGRAM REQUIRED APT COMPATIBILITY AND SWITCHLESS CAPABILITY.

-----SOLUTION/CORRECTION-----

1. MODIFIED AND UPDATED FOR MULTIPLE OPTION CONTROLLER.
2. ADDED APT CODE AND CONSOLE PACKAGE.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92 93 12

Operational Environment : 00 99 20

Device Affected : KL8J

Problem Reports Affected : CC0000752

Kit Number : ZF010 ZF144

-----AUTHORIZATION-----

Author	: B. HANSEN	Maintaining Group	: SM SYS
Submitting Engineer	: D ORIN	Maintainer	: JOHNSON
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: T. SHALLOW	Release Engineer	: S. DUMDEY
Charge Number	: V89 -08202	Coordination Number	: MC1472

A

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DJFPB-C0

PRODUCT IDENTIFICATION

Patch Level : 0

Product Date : 02-Sep-77

Description :

1ST Copyright year : 1976

Last Copyright Year : 1977

Expanded Description : FPP-8A INSTRUCTION TEST AND DATA EXERCISER

PRODUCT COMPONENTS AFFECTED							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
DJFPB-C-D		DJFPB-C-PB		DJFPB-C-FA			

PRODUCTS OBSOLETED

PROBLEM/DESCRIPTION

THIS DECO 'MD-08'DJFPB-C'. THE 'C' REVISION SOLVES THE PROBLEM DESCRIBED IN DEPO FOR MD-08-DJFPB-B. THE DEPO CORRECTED EXPONENT ALIGNMENT PROBLEMS WHEN RUNNING PROGRAM WITH MEMORY SIZE OVER 16K.

SOLUTION/CORRECTION

PRODUCT CHARACTERISTICS

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : FPP-8A

Problem Reports Affected :

Kit Number : ZF011 ZF226 ZF214

AUTHORIZATION

Author	: W HEAVEY	Maintaining Group	: SM SYS
Submitting Engineer	: W HEAVEY	Maintainer	: MISNER
Product Engineer	: D. WHITE	Field Service Engineer	: B. EASH
Manufacturing Engineer	: D. BROWN	Release Engineer	: S. DUMDEY
Charge Number	: V89-08202	Coordination Number	: MC1526

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHKEB-B0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 21-Sep-77

Description :

1ST Copyright year : 1972

Last Copyright Year : 1977

Expanded Description : KE8-A (EAE) INSTRUCTION TEST 1

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
DHKEB-B-D		DHKEB-B-PB		DHKEB-B-FA		DHKEB-B-UA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

PROGRAM ENTERED 'TICK' SUBROUTINE WITHOUT A CLEARED ACC AND CONSEQUENTLY FALSELY RECOGNIZED 'APT' AS BEING AVAILABLE, THEREBY PROCEEDING TO BRANCH ACCORDING TO 'APT', RESULTING IN PROGRAM FAILURE.

-----SOLUTION/CORRECTION-----

1. CLEAR ACC AS 'TICK' ROUTINE IS ENTERED.
2. FOUND INCORRECT COMBINATION OF A SUBROUTINE CALL AND A MICPOINSTRUCTION WRITTEN AS ONE COMMAND.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 390 2nd Pass : 390 ACT Sequence Number : Multimedia Affected : Yes

Processors : 88

Operational Environment : 00 20 99

Device Affected : KE8-E

Problem Reports Affected :

Kit Number : ZF011 ZF139 ZF013

-----AUTHORIZATION-----

Author	: A. BALAMOTIS	Maintaining Group	: PRO ENH
Submitting Engineer	: A. BALAMOTIS	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: D. BROWN	Release Engineer	: S. DUMDEY
Charge Number	: V98 -08162	Coordination Number	: MC1551

A

A

Compo

Compo

Diagn

Descr

Expan

Comp

Part

DJKTA

New S

Run T

Proce

Opera

Devic

Proble

Kit Nu

Autho

Submi

Produ

Manuf

Charg

A

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD9E-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 08-Nov-77

Description :

1ST Copyright year : 1968

Last Copyright Year : 1974

Expanded Description : INSTRUCTION TEST PART 2 (TC58)

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : TC58 TU20 TU10

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Roderhiser

Submitting Engineer : J Roderhiser

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group

: DIAG

Maintainer

: MISNER

Field Service Engineer

:

Release Engineer

: T Davies

Coordination Number

: MC0000

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1

A

Compo

Compo

Diagno

Descr

Expand

Compo

Part N

AC-622

Error

due to

Histor

Correc

correc

Run Ti

Proces

Operat

Device

Proble

Kit Nu

Author

Submit

Produc

Manufa

Charge

DEPO F

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD9F-C0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 08-Nov-77

Description :

1ST Copyright year : 1969

Last Copyright Year : 1974

Expanded Description : DATA RELIABILITY TEST (9TRACK) (TC58)

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : TU20 TU10 TC58

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Rodenhiser

Submitting Engineer : J Roderihiser

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group : diag
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

Compon

Compon

Diagno

Descri

Expand

Compo
Part N
AC-653

Documen
tity and

Bits 0-
bits 6-

Run Tin

Proces

Operat

Device

Proble

Kit Num

Author
Submit
Produc
Manufa
Charge

DEPO PA
(Direc

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD2Q-D0

PRODUCT IDENTIFICATION

Patch Level : 0

Product Date : 09-Nov-77

Description :

1ST Copyright year : 1968

Last Copyright Year : 1974

Expanded Description : FAMILY OF 8 ASR33/35 TTY TEST 2

PRODUCT COMPONENTS AFFECTED

PRODUCTS OBSOLETE

PROBLEM/DESCRIPTION

SOLUTION/CORRECTION

PRODUCT CHARACTERISTICS

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 93

Operational Environment : 00

Device Affected : ASR33 ASR35

Problem Reports Affected :

Kit Number :

AUTHORIZATION

Author : J Vrobel
Submitting Engineer : J Vrobel
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T Davies
Coordination Number : MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD3E-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 09-Nov-77

Description :

1ST Copyright year : 1968

Last Copyright Year : 1974

Expanded Description : TC01 EXTENDED MEMORY EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected : TC01 TC08 TU55 TU56

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel

Submitting Engineer : J VRobel

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group

: DIAG

Maintainer

: MISNER

Field Service Engineer

Release Engineer

: T Davies

Coordination Number

: MC0000

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD3R-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 09-Nov-77

Description :

1ST Copyright year : 1967

Last Copyright Year : 1974

Expanded Description : TC01 RANDOM EXERCISER

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment : 00

Device Affected : TC01 TC08 TU56 TU55

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Vrobel

Submitting Engineer : J Vrobel

Product Engineer :

Manufacturing Engineer :

Charge Number : V00-00000

Maintaining Group : DIAG

Maintainer : MISNER

Field Service Engineer :

Release Engineer : T Davies

Coordination Number : MC0000

A

Component Part Number :

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DD6T-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 09-Nov-77

Description :

1ST Copyright year : 1968

Last Copyright Year : 1974

Expanded Description : AA05/AA07 CALIBRATION CHECK

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 93 88

Operational Environment : 00

Device Affected : AA05 AA07

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : J Hittell
Submitting Engineer : J HITTELL
Product Engineer :
Manufacturing Engineer :
Charge Number : V00-00000

Maintaining Group : DIAG
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T DAVIES
Coordination Number : MC0000

A

Component Part Number : AE-5000A-A0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : 00-00000-00

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AHKEC-B0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 07-Dec-77

Description : AHKEC B0 KE8-E INSTR TEST 2

1ST Copyright year : 1972

Last Copyright Year : 1977

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-6273B-MA		AK-6275B-MA		AH-6274B-MA		AF-6273B-MA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Incorrect information in the instructions tended to confuse the user.

-----SOLUTION/CORRECTION-----

Fixed instructions; program O.K.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 600 2nd Pass : 600 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90

Operational Environment : 00 20

Device Affected : KE8E EAE

Problem Reports Affected : CC0000817

Kit Number : ZF011 ZF013 ZF139

-----AUTHORIZATION-----

Author	: A. Balamotis	Maintaining Group	: Diag. Eng
Submitting Engineer	: A. Balamotis	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: K. Fleming
Charge Number	: V98-05077	Coordination Number	: MC1622

OF 1

A

A

Component Part Number : 00-00000-00

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : NA

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : AXLAA-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 21-Dec-77

Description : NA

1ST Copyright year : 1977

Last Copyright Year : 1977

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C692A-MA		AK-C694A-MA		AH-C693A-MA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

Needed Dec-X8 module to exercise the LA-180 line printer when driven by a PDP-8/A parallel I/O board #8316-D.

-----SOLUTION/CORRECTION-----

Creation of 'AXLAAA0' which was derived from the DEC/X8 module 'PRINTER'.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 92

Operational Environment : 20 50

Device Affected : LA180

Problem Reports Affected : CC0000860

Kit Number : ZF008 ZF014

-----AUTHORIZATION-----

Author	: A. Balamotis	Maintaining Group	: Diag. Eng
Submitting Engineer	: A. Balamotis	Maintainer	: J Vrobel
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: K. Fleming
Charge Number	: V98-05077	Coordination Number	: MC1659

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHKMA-D0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 10-Jan-78

Description :

1ST Copyright year : 1972

Last Copyright Year : 1977

Expanded Description : PDP-8E Extended Memory Data and Checkerboard Test

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
DHKMA-D-D		DHKMA-D-PB		DHKMA-D-FA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Diagnostic did not support memories greater than 32K.
No test of MOS memory was provided,

-----SOLUTION/CORRECTION-----

Diagnostic was updated to include a march pattern for the MS8-E and updated to allow testing of 128K of memory.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92 93 94 12

Operational Environment : 00 20 99

Device Affected : KM8E KM8A

Problem Reports Affected : CC0000843

kit Number : ZF234 ZF009 ZF235 ZF209 ZF008 ZF010 ZF146

-----AUTHORIZATION-----

Author	: V Frey	Maintaining Group	: Small Sys
Submitting Engineer	: D Rice	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: Carl Cline
Manufacturing Engineer	:	Release Engineer	: K Fleming
Charge Number	: V89-08825	Coordination Number	: MC1781

-----CONTINUATION-----

DEPO PATCH AREA CONTINUED;
ZF010-PB ZF234-PB

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : MD-08-DHKMC-C0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 10-Jan-78

Description :

1ST Copyright year : 1971

Last Copyright Year : 1977

Expanded Description : PDP-8E EXTENDED MEMORY ADDRESS TEST (EAE)

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91 92 93 94 12

Operational Environment : 00 20 99

Device Affected : KM8E KM8A

Problem Reports Affected : CC0000855

Kit Number : ZF234 ZF009 ZF010 ZF209 ZF235 ZF146 ZF008

-----AUTHORIZATION-----

Author : V Frey

Maintaining Group : Small Sys

Submitting Engineer : D Rice

Maintainer : MISNER

Product Engineer :

Field Service Engineer : C Cline

Manufacturing Engineer :

Release Engineer : K Fleming

Charge Number : V89-08825

Coordination Number : MC1782

-----CONTINUATION-----

DEPO PATCH AREA CONTINUED;
ZF146-PB

ZF234-PB

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Patch

Approved : Yes

Diagnostic Package Code : MD-08-DIRXB-E1

-----PRODUCT IDENTIFICATION-----
Patch Level : 1

Product Date : 10-Jan-78

Description :

1ST Copyright year : 1975

Last Copyright Year : 1977

Expanded Description : RX01/RX8E Data Reliability/Exerciser Program

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

Diagnostic would get lost should a character be typed from
the keyboard while a message was printing

-----SOLUTION/CORRECTION-----

Enter the following patch.

-----DFPO PATCH AREA-----

Loc	From	To	Mnemonic	Loc	From	To	Mnemonic
05304	3023	3174					
05313	1023	1174					
10332	5304	5310					

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected : RX8E RX01

Problem Reports Affected :

Kit Number : ZF008 ZR122 ZF177 ZF127 ZF012 ZF117

-----AUTHORIZATION-----

Author : M Sturak
Submitting Engineer : D Rice
Product Engineer :
Manufacturing Engineer :
Charge Number : V89-08825

Maintaining Group : Sml Sys
Maintainer : G Johnson
Field Service Engineer : C Cline
Release Engineer : K Fleming
Coordination Number : MC1784

A

A

Comp

Comp

Diag

Desc

Expa

Com
Part
AC-6

Inde

Run

Proc

Oper

Devic

Prob

Kit

Auth
Subm
Prodi
Manu
Charg

A

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : MD-08-DJKTA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 10-Jan-78

Description :

1ST Copyright year : 1977

Last Copyright Year : 1977

Expanded Description : KT8-A Memory Management Option Diagnostic

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
DJKTA-A-D		DJKTA-A-PB		DJKTA-A-FA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

New Submission

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 90 2nd Pass : 90 ACT Sequence Number : Multimedia Affected : Yes

Processors : 92

Operational Environment : 00 20 99

Device Affected : KT8A

Problem Reports Affected :

Kit Number : ZF235

-----AUTHORIZATION-----

Author : D Rice	Maintaining Group : Small Sys
Submitting Engineer : D Rice	Maintainer : G Johnson
Product Engineer :	Field Service Engineer : Carl Cline
Manufacturing Engineer :	Release Engineer : K Fleming
Charge Number : V89-08825	Coordination Number : MC1783

A

A

Compo

Compo

Diagn

Descr

Expan

The f
May 1

Run T

Proce

Opera

Devic

Probl

Kit N

Autho

Submi

Produ

Manuf

Charg

CHANG

A

A

Component Part Number : AF-6220B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 00

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AHDKA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jan-78

Description : AHDKAB0 DK8E CLOCKS DIAG

1ST Copyright year : 1971

Last Copyright Year : 1977

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-6220B-MA		AK-6222B-MA		AH-6221B-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Error responses result when using a PDP-8/A processor due to timing differences, History count starts at Rev. B0.

-----SOLUTION/CORRECTION-----

Corrected program via variable starting address which correct for timing differences.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 210 2nd Pass : 210 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00

Device Affected : DK8E

Problem Reports Affected :

Kit Number : ZF011 ZF131

-----AUTHORIZATION-----

Author	: A Balamotis	Maintaining Group	: Diag Eng
Submitting Engineer	: A Balamotis	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: K Fleming
Charge Number	: V98-05077	Coordination Number	: MC1673

-----CONTINUATION-----

DEPO PATCH AREA; NOT PATCHABLE

A

A

Compo

Compo

Diagn

Descr

Expan

Compo

Part

AC-C2

Docum

Run T

Proce

Opera

Device

Proble

Kit Nu

Author

Submi

Produ

Manuf

Charg

A

A

Component Part Number : AF-6535E-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : NA

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AILAB-E0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 23-Feb-78

Description : LA36 TERM DIAG

1ST Copyright year : 1974

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-6535E-MA		AK-6537E-MA		AH-6536E-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Documentation error regarding IOT code loading for tty and kbd

-----SOLUTION/CORRECTION-----

Bits 0-5 = printer (tty)
bits 6-11 = keyboard (kbd)

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 00

Device Affected : LA36

Problem Reports Affected : AA0001353

Kit Number : ZF008 ZF010 ZF215

-----AUTHORIZATION-----

Author	: A Balamotis	Maintaining Group	: Pro Enh
Submitting Engineer	: A Balamotis	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: K Fleming
Charge Number	: V98-05077	Coordination Number	: MC1882

-----CONTINUATION-----

DEPO PATCH AREA
(Directions Change Only) Paragraph 4-1-4

Bits 0-5 = TTY code
Bits 6-11 = KBD code

A

Component Part Number : 00-00000-00

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Description : NA

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIZAA-H0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 06-Mar-78

Description : NA

1ST Copyright year : 1976

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

The following multimedia revisions will be effective in
March 1978.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : Release Eng
Submitting Engineer : D Beausoleil
Product Engineer :
Manufacturing Engineer :
Charge Number : V98-08162

Maintaining Group : Release Eng
Maintainer : C Cinnamon
Field Service Engineer :
Release Engineer : K Fleming
Coordination Number : MC1802

-----CONTINUATION-----

DEPO PATCH AREA:

CHANGE LOC X8-DIQAE FROM L TO AXQAE-M DEC/X8 DT
CHANGE LOC X8-DDQAA FROM L TO AXQAA-M DEC/X8 LT
CHANGE LOC X8-DJRXA FROM F TO AXRXA-G DEC/X8 RX
CHANGE LOC 08-DH05B FROM O TO AH05B-P COS 300 RK
CHANGE LOC 08-DJRXA FROM L CC/8 #1

CHANGE LOC 08-DJRXB FROM E PDP-8 RX
CHANGE LOC 08-DJRXC FROM H RX01 #1
CHANGE LOC 08-DJRXD FROM D RX01 #2
CHANGE LOC 08-DJRXE FROM C CL/8 #2
CHANGE LOC 08-DJRXF FROM C TO AJRXE-D RX01 #3

A

Component Part Number : 00-00000-00

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : 00-00000-00

Component Part Description : NA

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXQAF-K0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 06-Mar-78

Description : NA

1ST Copyright year : 1973

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C290K-MA		AH-C292K-MA					

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Doc. updated to reflect Dec/X8 module changes.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number : ZF229

-----AUTHORIZATION-----

Author	: J Vrobel	Maintaining Group	: Rel Eng
Submitting Engineer	: D Beausoleil	Maintainer	: C Cinnamon
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: K Fleming
Charge Number	: V98-08162	Coordination Number	: MC1801

-----CONTINUATION-----

DEPO PATCH AREA:
CHANGE LOC 08-DJRXX FROM A RX01 #4

CHANGE LOC 08-DKRXA FROM A VT78 RX
CHANGE LOC 08-AJRXH FROM NEW FLOPPY TO A WS202 RX

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C656A-M0

Component Part Description : NA

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : AJRLA-A0

PRODUCT IDENTIFICATION

Patch Level : 0

Product Date : 03-Apr-78

Description : NA

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

PRODUCT COMPONENTS AFFECTED

Component Part Number	Media Variable						
AC-C656A-MA		AK-C658A-MA		AH-C657A-MA			

PRODUCTS OBSOLETED

PROBLEM/DESCRIPTION

This is a new diagnostic to test RL8A without the use of a drive.

SOLUTION/CORRECTION

PRODUCT CHARACTERISTICS

Run Time (seconds) 1st Pass : 5 2nd Pass : 90 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A

Problem Reports Affected :

Kit Number : ZF233

AUTHORIZATION

Author : J Rich	Maintaining Group : Small Sys
Submitting Engineer : Jack Rich	Maintainer : Glenn Johnson
Product Engineer :	Field Service Engineer : C Cline
Manufacturing Engineer : Dave Brown	Release Engineer : K Fleming
Charge Number : V89-09395	Coordination Number : MC1973

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C660A-M0

Component Part Description : NA

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : AJRLB-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 03-Apr-78

Description : NA

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C660A-MA		AK-C662A-MA		AH-C661A-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

This a new diagnostic to test all RL8-A/RL01 drive functions except for read/write.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 150 2nd Pass : 150 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A/RL0

Problem Reports Affected :

Kit Number : ZF233

-----AUTHORIZATION-----

Author	: Jack Rich	Maintaining Group	: Sml Sys
Submitting Engineer	: Jack Rich	Maintainer	: Glenn Johnson
Product Engineer	:	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: Dave Brown	Release Engineer	: K Fleming
Charge Number	: V89-09395	Coordination Number	: MC1974

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C664A-M0

Component Part Description : ECO TALLY 00

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : AJRLC-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 03-Apr-78

Description : AJRLCA0 RL8A/RL01 DR PT2

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C664A-MA		AK-C666A-MA		AH-C665A-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

This is a new diagnostic to test RL8-A/RL01 read/write functionality

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 60 2nd Pass : 300 AC1 Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A/RL0

Problem Reports Affected :

Kit Number : ZF233

-----AUTHORIZATION-----

Author	: Jack Rich	Maintaining Group	: Sml Sys
Submitting Engineer	: Jack Rich	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: Dave Brown	Release Engineer	: K Fleming
Charge Number	: V89-09395	Coordination Number	: MC1975

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-C682A-M0

Component Part Description : ECO TALLY 00

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : AJRLG-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 03-Apr-78

Description : AJRLGA0 RL8-A/RL01 PCK VFYR

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C682A-MA		AK-C684A-MA		AH-C683A-MA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

This is a new program to update RL01 field bad sector files.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A/RL0

Problem Reports Affected :

Kit Number : ZF233

-----AUTHORIZATION-----

Author	: Jack Rich	Maintaining Group	: Sml Sys
Submitting Engineer	: Jack Rich	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: Dave Brown	Release Engineer	: K Fleming
Charge Number	: V89-09395	Coordination Number	: MC1976

A

A

Component Part Number : AF-C672A-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : NA

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : AJRLE-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 14-Apr-78

Description : NA

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component
Part Number
AK-C674A-MA

Media
Variable

Component
Part Number
AC-C672A-MA

Media
Variable

Component
Part Number
AH-C673A-MA

Media
Variable

Component
Part Number

Media
Variable

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

A new product RL8-A (M8433) and RL01 disk drive required
a performance exerciser program to exercise the RL8-A
/RL01 subsystem.

-----SOLUTION/CORRECTION-----

New release program AJRLEA RL8-A/RL01 performance
exerciser created.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 99 20

Device Affected : RL8A

Problem Reports Affected :

Kit Number : ZF233 ZF015 ZJ233

-----AUTHORIZATION-----

Author : D Orin
Submitting Engineer : D Orin
Product Engineer :
Manufacturing Engineer : D Brown
Change Number : V89-09395

Maintaining Group : Sml Sys
Maintainer : G Johnson
Field Service Engineer :
Release Engineer : K Fleming
Coordination Number : MC1979

A

A

Component Part Number : AF-C676A-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : NA

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : AXRLA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 14-Apr-78

Description : NA

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component
Part Number
AK-C678A-MA

Media
Variable

Component
Part Number
AC-C676A-MA

Media
Variable

Component
Part Number
AH-C677A-MA

Media
Variable

Component
Part Number

Media
Variable

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

New product RL8-A (M8433) and RL01 disk drive required
a Dec/X8 Subsystem Exerciser module.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 50

Device Affected : RL8A

Problem Reports Affected :

Kit Number : ZF229

-----AUTHORIZATION-----

Author : D Orin

Submitting Engineer : D Orin

Product Engineer :

Manufacturing Engineer : D Brown

Charge Number : V89-09395

Maintaining Group

: Sml Sys

Maintainer

: G Johnson

Field Service Engineer

:

Release Engineer

: K Fleming

Coordination Number

: MC1980

A

A

A

Component Part Number : 00-00000-00

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : NA

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIZAA-10

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 04-May-78

Description : NA

1ST Copyright year : 1976

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

The following multi-media revisions will be effective in
May 1978.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : Release Eng
Submitting Engineer : D Beausoleil
Product Engineer :
Manufacturing Engineer : C Cinnamon
Charge Number : V98-08162

Maintaining Group : Release Eng
Maintainer : C Cinnamon
Field Service Engineer :
Release Engineer : K Fleming
Coordination Number : MC2022

-----CONTINUATION-----

CHANGE LOC AXQAE FROM M TO N DEC/X8 DT
CHANGE LOC AXQAA FROM M TO N DEC/X8 LT
CHANGE LOC AXRXA FROM G TO H DEC/X8 RX
CHANGE LOC AH05B FROM P TO Q COS 300 RK
CHANGE LOC 08-DJRXA FROM L TO AJRXA-M CL/8 #1
CHANGE LOC 08-DJRXB FROM E TO AJRXB-F PDP-8 RX
CHANGE LOC 08-DJRXC FROM H TO AJRXC-I RX01 #1

CHANGE LOC 08-DJRXD FROM D TO - RX01 #2
CHANGE LOC 078-DJRXE FROM C TO - CL/8 #2
CHANGE LOC AJRXF FROM D TO - RX01 #3
CHANGE LOC 08-DJRXG FROM A TO AJRXG-B RX01 #4
CHANGE LOC 08-DKRXA FROM A TO - VT78 RX
CHANGE LOC AJRXH FROM A TO B WS202 RX

A

A

Comp

Comp

Diagn

Descr

Expan

Comp

Part

AK-C

Does

UPDA

THIS

Run

Proce

Opera

Devic

Probl

Kit N

Auth

Subm

Produ

Manuf

Charg

A

A

Component Part Number : AF-6281B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 00

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AHKLA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 31-May-78

Description : AHKLAB0 KL8M MODM CNTRL

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AK-6284B-MA		AC-6281B-MA		AH-6282B-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Diagnostic would not run on 8-1 or other old 12 bit CPUs.
HISTORY COUNT STARTS AT REV B.

-----SOLUTION/CORRECTION-----

Added routines to simulate commands needed for the old CPUs.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88 89 90 91 93 12

Operational Environment : 00

Device Affected : KL8M

Problem Reports Affected : CC0000707

Kit Number : ZF011 ZF145

-----AUTHORIZATION-----

Author	: K C Whitney	Maintaining Group	: Pro Enh
Submitting Engineer	: A Balamotis	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: Dave Brown NH	Release Engineer	: K Fleming
Charge Number	: V98-05460	Coordination Number	: MC2015

Component Part Number : AF-6285C-MC

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AHKLB-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-May-78

Description : N/A

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-6285C-MA		AK-6287C-MA		AF-6285C-M0		AH-6286C-MA	
AL-6288C-NA							

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

DIAGNOSTIC WOULD NOT RUN ON 8-1 OR OTHER OLD 12 BIT CPUS.

-----SOLUTION/CORRECTION-----

ADDED ROUTINES TO SIMULATE COMMAND NEEDED FOR THE OLD CPUS.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88 89 90 91 93 12

Operational Environment : 00

Device Affected : KL8M KL8E/F DC08

Problem Reports Affected : CC0000707

Kit Number : ZF011 ZF203 ZF145

-----AUTHORIZATION-----

Author	: K.C.WHITNEY	Maintaining Group	: PRO EHN
Submitting Engineer	: A.BALAMOTIS	Maintainer	: J.VROBEL
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: DAVE BROWN	Release Engineer	: T.DAVIES
Charge Number	: V98-05460	Coordination Number	: MC2016

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-6285C-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AHKLB-C0

PRODUCT IDENTIFICATION

Patch Level : 0

Product Date : 31-May-78

Description : AHKLBC0 KL8M KL8E/F DC08H ONL

1ST Copyright year : 1971

Last Copyright Year : 1978

Expanded Description :

PRODUCT COMPONENTS AFFECTED

Component Part Number	Media Variable						
AK-6287C-MA		AC-6285C-MA		AH-6286C-MA			

PRODUCTS OBSOLETE

PROBLEM/DESCRIPTION

Diagnostic would not run on 8-I or other old 12 bit CPU's

SOLUTION/CORRECTION

Added routines to simulate commands needed for the old CPU's.

PRODUCT CHARACTERISTICS

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88 89 90 91 93 12

Operational Environment : 00

Device Affected : KL8M KL8E/F DC08

Problem Reports Affected : CC0000707

Kit Number : ZF011 ZF203 ZF145

AUTHORIZATION

Author	: K C Whitney	Maintaining Group	: Pro Enh
Submitting Engineer	: A Balamotis	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: Dave Brown NH	Release Engineer	: K Fleming
Charge Number	: V98-05460	Coordination Number	: MC2016

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-6289E-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AHKLC-E0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 31-May-78

Description : AHKLCEO KL8F ASYNC INTFC

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-6292E-MA		AC-6289E-MA		AH-6291E-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Diagnostic would not run on 8-I or other old bit CPUs.

-----SOLUTION/CORRECTION-----

Added routines to simulate commands needed for the old CPUs.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88 89 90 91 93 12

Operational Environment : 00

Device Affected : KL8F

Problem Reports Affected : CC0000707

Kit Number : ZF011 ZF143

-----AUTHORIZATION-----

Author	: Patrick Coyne	Maintaining Group	: Pro Enh
Submitting Engineer	: A Balamotis	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: Dave Brown NH	Release Engineer	: K Fleming
Charge Number	: V98-05460	Coordination Number	: MC2017

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

Component Part Number :

Component Part Description :

ECO Purpose : Patch

Approved : Yes

Diagnostic Package Code : MD-08-DHRKA-E1

-----PRODUCT IDENTIFICATION-----

Patch Level : 1

Product Date : 14-Jun-78

Description :

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description : RK8E DISKLESS CONTROL TEST

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Due to hardware incompatibilities, DHRKA will not run properly on a PDP-8/A processor configuration

-----SOLUTION/CORRECTION-----

Do not use DHRKA test on a PDP-8/A system.
THIS IS AN UNCONDITIONAL PATCH

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91

Operational Environment : 00 20

Device Affected : RK05

Problem Reports Affected :

Kit Number : ZF008 ZK127 ZJ177 ZF012 ZF177 ZF127 ZF023

-----AUTHORIZATION-----

Author : J Vrobel
Submitting Engineer : A Balamotis
Product Engineer :
Manufacturing Engineer :
Charge Number : V98-05460

Maintaining Group : Pro Enh
Maintainer : MISNER
Field Service Engineer :
Release Engineer : K Fleming
Coordination Number : MC2058

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-E460A-A0

Component Part Description : ECO TALLY 00

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : ARMMB-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 14-Jun-78

Description : ARMMBA0 MM11-YP DIAG

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-E461A-AA		AC-E460A-AA		AL-E462A-NA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

This is the first release of the ARMMBA (STK228) Memory Diagnostic. It will be used to check out MM11-YP memory stacks on the 2223 Memory Tester.

-----SOLUTION/CORRECTION-----

IN HOUSE USE ONLY

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89

Operational Environment : 40

Device Affected : MM11YP

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author	: Al Williams	Maintaining Group	: Mem Diag
Submitting Engineer	: Al Williams	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: D Brown NH	Release Engineer	: K Fleming
Charge Number	: V96-06159	Coordination Number	: MC2077

A

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AK-C670A-MA

Component Part Description : 00

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLD-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 29-Jun-78

Description : AJRLDA0 RL8-A/RL01 DR CPT VFY

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C668A-MA		AK-C670A-MA		AH-C669A-MA		AF-C668A-M0	
AL-C671A-NA							

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

NEW PRODUCT RL8-A (M8433) CONTROLLER AND RL01 DISK DRIVE
REQUIRED A DRIVE COMPATIBILITY VERIFY THAT ALL DRIVES
ON 1 OR MORE RL01 SUBSYSTEMS ARE COMPATIBLE.

-----SOLUTION/CORRECTION-----

NEW RELEASE PROGRAM AJRLDA RL8A/RL01 DRIVE COMPATIBILITY
VERIFIER PROGRAM CREATED.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 99 20

Device Affected : RL8A (M8433)

Problem Reports Affected :

Kit Number : ZF233 ZF238 ZF237 ZF016 ZF015

-----AUTHORIZATION-----

Author	: D.ORIN	Maintaining Group	: SML SYS
Submitting Engineer	: D.ORIN	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: CARL CLINE
Manufacturing Engineer	: K. MASSEY	Release Engineer	: T.DAVIES
Charge Number	: V89-08202	Coordination Number	: MC2141

A

OF 1

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-E610A-A0

Component Part Description : ECO TALLY 00

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : ARLAC-A0

Patch Level : 0

Product Date : 07-Jul-78

Description : ARLACA0 M7728/LA36 QV TEST

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-E610A-AA		AK-E611A-AA		AL-E612A-NA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

STANDALONE QUICK VERIFY TEST STATION USED BY MANUFACTURING
IN PHOENIX ARIZONA REQUIRED SPECIAL TEST PROGRAM
TO CONTROL TEST STATION HARDWARE AND PROVIDE USER CONTROL

-----SOLUTION/CORRECTION-----

CREATED NEW RELEASE PROGRAM
IN HOUSE USE ONLY.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 19 2nd Pass : 19 ACT Sequence Number : Multimedia Affected : No

Processors : 89 90

Operational Environment : 00

Device Affected : M7728

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author	: D.ORIN	Maintaining Group	: SML SYS
Submitting Engineer	: D.ORIN	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: K.MASSEY	Release Engineer	: T.DAVIES
Charge Number	: V89-08202	Coordination Number	: MC2161

A

A

Component Part Number : AF-E613A-A0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : 00

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : ARLAD-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 07-Jul-78

Description : ARLADAO M7728/LA36 QY TEST

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-E613A-AA		AK-E614A-AA		AL-E615A-NA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

STANDALONE QUICK VERIFY/DIAGNOSE TEST STATION
USED BY MANUFACTURING IN PHOENIX ARIZONA
REQUIRED SPECIAL TEST PROGRAM TO CONTROL
TEST STATION HARDWARE AND PROVIDE USER CONTROL

-----SOLUTION/CORRECTION-----

CREATED NEW RELEASE PROGRAM
IN HOUSE USE ONLY.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 19 2nd Pass : 19 ACT Sequence Number : Multimedia Affected : No

Processors : 89 90

Operational Environment : 00

Device Affected : M7728

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author	: D. ORIN	Maintaining Group	: SML SYS
Submitting Engineer	: D. ORIN	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: K. MASSEY	Release Engineer	: T. DAVIES
Charge Number	: V89-08202	Coordination Number	: MC2157

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-C656B-M0

Component Part Description : AJRLAB0 RL8-A DSKLS CTRLR

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLA-B0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 31-Jul-78

Description : AJRLAB0 RL8-A DSKLS CTRLR

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-C656B-MA		AK-C658B-MA		AH-C657B-MC		AL-C659B-NA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

COLORADO MANUFACTURING REQUESTED CHANGES WHEN RUNNING ON MULTIPLE OPTION TESTER.

-----SOLUTION/CORRECTION-----

REPORT ERRORS WHEN ON M.O.T. AND INCLUDE UNIT NUMBER ALLOW THREE FAILURES BEFORE DROPPING UNIT.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 5 2nd Pass : 90 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A

Problem Reports Affected : CC0000964

Kit Number : ZF233 ZF238 ZF016

-----AUTHORIZATION-----

Author	: J Rich	Maintaining Group	: Small Sys
Submitting Engineer	: Jack Rich	Maintainer	: Glenn Johnson
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: Dave Brown	Release Engineer	: T DAVIES
Charge Number	: E89-08202	Coordination Number	: MC2163

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-C660B-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLB-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 31-Jul-78

Description : AJRLBBO RL8-A/RL01 DR PT1

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C660B-MA		AK-C662B-MA		AH-C661B-MA		AL-C663B-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

SEEK TIMING PROBLEM IN SECOND PASS

-----SOLUTION/CORRECTION-----

CHANGE TIMING FROM BEGINNING OF SEEK, RATHER THAN FROM STATE CHANGE.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 150 2nd Pass : 150 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A/RL0

Problem Reports Affected : CC0000963

Kit Number : ZF233 ZF238 ZF016

-----AUTHORIZATION-----

Author	: Jack Rich	Maintaining Group	: Sml Sys
Submitting Engineer	: Jack Rich	Maintainer	: Glenn Johnson
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: Dave Brown	Release Engineer	: T.DAVIES
Charge Number	: E89-08202	Coordination Number	: MC2164

A

A

Comp

Comp

Diag

Desc

Expa

Com

Part

AC-C

DOES

UPDA

THIS

Run

Proc

Oper

Devi

Prob

Kit

Auth

Subm

Prod

Manu

Char

1

A

A

Component Part Number : AF-C217B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXCDA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXCDAB0 DEC/X8 MDO CDP8

1ST Copyright year : 1973

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AK-C219B-MA		AC-C217B-MA		AH-C218B-MA			

-----PRODUCTS OBSOLETE-----

Does not support 128K system configurations.

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128K.
THIS ECO REPLACES MD-X8-DICDA-A.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2189

A

A

Compo

Compo

Diagn

Descr

Expan

Comp

Part

AC-C2

DOES

UPDAT

THIS

Run T

Proce

Opera

Devic

Probl

Kit N

Autho

Submi

Produ

Manuf

Charg

A

A

Component Part Number : AF-C180B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXCRA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXCRAB0 DEC/X8 MOD CARD8E

1ST Copyright year : 1973

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C182B-MA		AC-C180B-MA		AH-C181B-MA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

Does not support 128K system configurations.

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128K.
THIS ECO REPLACES MD-X8-DHCRA-A.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2190

Component Part Number : AF-C293B-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXRFA-B0

PRODUCT IDENTIFICATION

Patch Level : 0

Product Date : 01-Aug-78

Description : AXRFAB0 DEC/X8 MOD RF08DS

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

PRODUCT COMPONENTS AFFECTED							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-C293B-MA		AK-C295B-MA		AH-C294B-MA			

PRODUCTS OBSOLETE

PROBLEM/DESCRIPTION
DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.

SOLUTION/CORRECTION
UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.
THIS ECO REPLACES MD-X8-DIRFA-A.

PRODUCT CHARACTERISTICS			
Run Time (seconds)	1st Pass :	2nd Pass :	ACT Sequence Number :
Processors	: 12 88 89 90 91 92		
Operational Environment	: 50		
Device Affected :	DEC/X8		
Problem Reports Affected	: CC0000949		
Kit Number	: ZF229	ZF238	ZK229

AUTHORIZATION			
Author	: D. RICE	Maintaining Group	: SML SYS
Submitting Engineer	: D. RICE	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: CARL CLINE
Manufacturing Engineer	:	Release Engineer	: S. DUMDEY
Charge Number	: V89-08202	Coordination Number	: MC2218

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-C296B-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXRKA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXRKAB0 DEC/X8 MOD RK8DS

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component
Part Number
AC-C296B-MA

Media
Variable

Component
Part Number
AK-C298B-MA

Media
Variable

Component
Part Number
AH-C297B-MA

Media
Variable

Component
Part Number

Media
Variable

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.
THIS ECO REPLACES MD-X8-DIRKA-A.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZF238 ZK229

-----AUTHORIZATION-----

Author : D. RICE
Submitting Engineer : D. RICE
Product Engineer :
Manufacturing Engineer :
Charge Number : V89-08202

Maintaining Group : SML SYS
Maintainer : MISNER
Field Service Engineer : CARL CLINE
Release Engineer : S. DUMDEY
Coordination Number : MC2219

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C196C-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXRKB-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXRKB0 DEC/X8 MOD RK8EDS

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component
Part Number
AC-C196C-MA

Media
Variable

Component
Part Number
AK-C198C-MA

Media
Variable

Component
Part Number
AH-C197C-MA

Media
Variable

Component
Part Number

Media
Variable

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.
THIS ECO REPLACES MD-X8-DHRKA-B0/00

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZF238 ZK229

-----AUTHORIZATION-----

Author : D. RICE
Submitting Engineer : D. RICE
Product Engineer :
Manufacturing Engineer :
Charge Number : V89-08202

Maintaining Group : SML SYS
Maintainer : MISNER
Field Service Engineer : CARL CLINE
Release Engineer : S. DUMDEY
Coordination Number : MC2220

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C676B-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXRLA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXRLAB0 DEC/X8 MOD RL8A

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-C676B-MA		AK-C678B-MA		AH-C677B-MA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZF238 ZK229

-----AUTHORIZATION-----

Author	: D. RICE	Maintaining Group	: SML SYS
Submitting Engineer	: D. RICE	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: CARL CLINE
Manufacturing Engineer	:	Release Engineer	: S. DUMDEY
Charge Number	: V89-08202	Coordination Number	: MC2221

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C199C-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : AXRXB-C0

Patch Level : 0

Product Date : 01-Aug-78

Description : AXRXBC0 DEC/X8 MOD FLOPPY

1ST Copyright year : 1975

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C199C-MA		AK-C201C-MA		AH-C200C-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.
THIS ECO REPLACES MD-X8-DHRXA-B0/00.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZF238 ZK229

-----AUTHORIZATION-----

Author	: D. RICE	Maintaining Group	: SML SYS
Submitting Engineer	: D. RICE	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: CARL CLINE
Manufacturing Engineer	:	Release Engineer	: S. DUMDEY
Charge Number	: V89-08202	Coordination Number	: MC2222

A

A

Component Part Number : AF-C302D-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXTCB-D0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXTCB00 DEC/X8 MOD TC58MT

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C302D-MA		AK-C304D-MA		AH-C303D-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.
HISTORY COUNT STARTS AT REV C-0.

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.
THIS ECO REPLACES MD-X8-DITCB-C-0

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229 ZF238

-----AUTHORIZATION-----

Author	: D. RICE	Maintaining Group	: SML SYS
Submitting Engineer	: D. RICE	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: CARL CLINE
Manufacturing Engineer	:	Release Engineer	: S. DUMDEY
Charge Number	: V89-08202	Coordination Number	: MC2225

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-C173B-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXTCC-B0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 01-Aug-78

Description : AXTCCB0 DEC/X8 MOD TC12LT

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C173B-MA		AK-C175B-MA		AH-C174B-MA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

DOES NOT SUPPORT 128k SYSTEM CONFIGURATIONS.

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128k.
THIS ECO REPLACES MD-X8-DDTCA-A.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZF238 ZK229

-----AUTHORIZATION-----

Author	: D. RICE	Maintaining Group	: SML SYS
Submitting Engineer	: D. RICE	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: CARL CLINE
Manufacturing Engineer	:	Release Engineer	: MAUREEN HANSEN
Charge Number	: V89-08202	Coordination Number	: MC2226

A

A

Component Part Number : AF-C205C-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 02

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXTDA-C0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 01-Aug-78

Description : AXTDAC0 DEC/X8 MOD TD8EDT

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C205C-MA		AK-C207C-MA		AH-C206C-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.
THIS ECO REPLACES MD-X8-DHTDA-B0/01.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CCOG00949

Kit Number : ZF229 ZF238 ZK229

-----AUTHORIZATION-----

Author	: D. RICE	Maintaining Group	: SML. SYS.
Submitting Engineer	: D. RICE	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: CARL CLINE
Manufacturing Engineer	:	Release Engineer	: MAUREEN HANSEN
Charge Number	: V89-08202	Coordination Number	: MC2227

-----CONTINUATION-----

1

A

A

Component Part Number : AF-C208C-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXDMA-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXDMA0 DEC/X8 MOD TM8EMT

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C208C-MA		AK-C210C-MA		AH-C209C-MA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.
HISTORY COUNT STARTS AT REV B.

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.
THIS ECO REPLACES MD-X8-DHTMA-B.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZF238 ZK229

-----AUTHORIZATION-----

Author	: D. RICE	Maintaining Group	: SML.SYS.
Submitting Engineer	: D.RICE	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: CARL CLINE
Manufacturing Engineer	:	Release Engineer	: MAUREEN HANSEN
Charge Number	: V89-08202	Coordination Number	: MC2228

A

A

Component Part Number : AF-C211B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXVCA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXVCAB0 DEC/X8 MOD VCAD8E

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C211B-MA		AK-C213B-MA		AH-C212B-MA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.
THIS ECO REPLACES MD-X8-DHVCA-A.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZF238 ZK229

-----AUTHORIZATION-----

Author	: D. RICE	Maintaining Group	: SML. SYS.
Submitting Engineer	: D. RICE	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: CARL CLINE
Manufacturing Engineer	:	Release Engineer	: MAUREEN HANSEN
Charge Number	: V89-08202	Coordination Number	: MC2229

A

A

Compo

Compo

Diagn

Descr

Expan

Comp
Part
AK-C2

DOES
HISTO

Updat
THIS

Run T

Proce

Opera

Devic

Probl

Kit N

Autho
Submi
Produ
Manuf.
Charg

A

A

Component Part Number : AF-C214B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXVTA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXVTAB0 DEC/X8 MOD VT8E

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-C214B-MA		AK-C216B-MA		AH-C215B-MA			

-----PRODUCTS OBSOLETE-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.
THIS ECO REPLACES MD-X8-DHVTA-A-0

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZF238 ZK229

-----AUTHORIZATION-----

Author	: D. RICE	Maintaining Group	: SML SYS
Submitting Engineer	: D. RICE	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: CARL CLINE
Manufacturing Engineer	:	Release Engineer	: S. DUMDEY
Charge Number	: V89-08202	Coordination Number	: MC2230

Component Part Number : AF-C305B-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXXYA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXXYAB0 DEC/X8 MOD PLOTTER

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component
Part Number
AC-C305B-MA

Media
Variable

Component
Part Number
AK-C307B-MA

Media
Variable

Component
Part Number
AH-C306B-MA

Media
Variable

Component
Part Number

Media
Variable

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.
THIS ECO REPLACES MD-X8-DIXYA-A-0

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZF238 ZK229

-----AUTHORIZATION-----

Author : D. RICE
Submitting Engineer : D. RICE
Product Engineer :
Manufacturing Engineer :
Charge Number : V89-08202

Maintaining Group : SML SYS
Maintainer : MISNER
Field Service Engineer : CARL CLINE
Release Engineer : S. DUMDEY
Coordination Number : MC2231

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C226C-MO

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXDFA-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXDFACO DEC/X8 MOD DF32DS

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C228C-MA		AC-C226C-MA		AH-C227C-MA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

Does not support 128K system configurations.
HISTORY COUNT STARTS AT REV B.

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128K.
THIS ECO REPLACES MD-X8-DIDFA-B.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2193

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-C229E-M0

Component Part Description : ECO TALLY 04

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXDKA-E0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXDKAE0 DEC/X8 MOD TIMERA

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C231E-MA		AC-C229E-MA		AH-C230E-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Does not support 128K system configurations.
HISTORY STARTS AT REV B-0.

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128K.
THIS ECO REPLACES MD-X8-DIDKA-D.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2232

A

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C308B-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXFPA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXFPAB0 DEC/X8 MOD FPP8A

1ST Copyright year : 1976

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C310B-MA		AC-C308B-MA		AH-C309B-MA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128k.
THIS ECO REPLACES MD-X8-DJFPA-A0/00.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08825	Coordination Number	: MC2195

A

A

Component Part Number : AF-C232B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXFPB-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXFPBB0 DEC/X8 MOD FPP12

1st Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C234B-MA		AC-C232B-MA		AH-C233B-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Does not support 128K system configurations.

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.
THIS ECO REPLACES MD-X8-DIFPA-A.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author : Don Rice
Submitting Engineer : Don Rice
Product Engineer : Straka/Cook
Manufacturing Engineer : WAIVERED
Change Number : V89-08202

Maintaining Group : Sml Sys
Maintainer : MISNER
Field Service Engineer : Carl Cline
Release Engineer : K Fleming
Coordination Number : MC2196

A

A

Component Part Number : AF-C186B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXICA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXICAB0 DEC/X8 MOD ICSX8

1ST Copyright year : 1975

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C188B-MA		AC-C186B-MA		AH-C187B-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Does not support 128k system configurations.

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.
THIS ECO REPLACES MD-X8-DHICA-A.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :	2nd Pass :	ACT Sequence Number :	Multimedia Affected : Yes
Processors : 12 88 89 90 91 92			
Operational Environment : 50			
Device Affected : DEC/X8			
Problem Reports Affected : CC0000949			
Kit Number : ZF229 ZK229			

-----AUTHORIZATION-----

Author : Don Rice	Maintaining Group : Sml Sys
Submitting Engineer : Don Rice	Maintainer : MISNER
Product Engineer : Straka/Cook	Field Service Engineer : Carl Cline
Manufacturing Engineer : WAIVERED	Release Engineer : K Fleming
Charge Number : V89-08202	Coordination Number : MC2197

A

Component Part Number : AF-C235B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXKAA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXKAAB0 DEC/X8 MOD MRI08A

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C237B-MA		AC-C235B-MA		AH-C236B-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Does not support 128K system configurations.

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.
THIS ECO REPLACES MD-X8-DIKAA-A.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author : Don Rice
Submitting Engineer : Don Rice
Product Engineer : Straka/Cook
Manufacturing Engineer : WAIVERED
Charge Number : V89-08202

Maintaining Group : Sml Sys
Maintainer : MISNER
Field Service Engineer : Carl Cline
Release Engineer : K Fleming
Coordination Number : MC2198

A

A

Component Part Number : AF-C238B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 00

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXKAB-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXKABBO DEC/X8 MOD RANMRI

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AK-C240B-MA		AC-C238B-MA		AH-C239B-MA			

-----PRODUCTS OBSOLETE-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.
HISTORY COUNT STARTS AT REV B0.

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.
THIS ECO REPLACES MD-X8-DIKAB-A.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0005949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2199

A

A

Component Part Number : AF-C241C-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXKAC-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXKACCO DEC/X8 MOD OPRATE

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AK-C243C-MA		AC-C241C-MA		AH-C242C-MA			

-----PRODUCTS OBSOLETED-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.
HISTORY STARTS AT REV B0.

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128k.
THIS ECO REPLACES MD-X8-DIKAC-B-0.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2200

A

Component Part Number : AF-C244C-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXKAD-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXKADCO DEC/X8 MDO NOTFUN

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AK-C246C-MA		AC-C244C-MA		AH-C245C-MA			

-----PRODUCTS OBSOLETE-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.
HISTORY STARTS AT REV B-0.

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128K.
THIS ECO REPLACES MD-X8-DIKAD-B-0.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2201

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C247C-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXKEA-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXKEA0 DEC/X8 MOD EAFALL

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C249C-MA		AC-C247C-MA		AH-C248C-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DOES NOT SUPPORT 128k SYSTEM CONFIGURATIONS.
HISTORY STARTS AT REV B-0.

-----SOLUTION/CORRECTION-----

UPDATED TO SUPPORT MAXIMUM SYSTEM SIZE OF 128K.
THIS ECO REPLACES MD-X8-DIKEA-B-0.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: STRAKA/COOK	Field Service Engineer	: CARL CLINE
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2202

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C253C-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXKLB-C0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 01-Aug-78

Description : NA

1ST Copyright year : 1974

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AK-C255C-MA		AC-C253C-MA		AH-C254C-MA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

Does not support 128K system configurations.
HISTORY COUNT STARTS AT REV. B.

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128K.
THIS ECO REPLACES MD-X8-DIKLB-B.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	:	Don Rice	Maintaining Group	:	Sml Sys
Submitting Engineer	:	Don Rice	Maintainer	:	Glenn Johnson
Product Engineer	:	Straka/Cook	Field Service Engineer	:	Carl Cline
Manufacturing Engineer	:	WAIVERED	Release Engineer	:	K Fleming
Charge Number	:	V89-08202	Coordination Number	:	MC2205

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C260B-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXKLD-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXKLDB0 DEC/X8 MOD MSLULP

1ST Copyright year : 1976

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C262B-MA		AC-C260B-MA		AH-C261B-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Does not support 128K system configurations.

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128K.
THIS ECO REPLACES MD-X8-DIKLD-A0/00.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2207

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-C692B-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXLAA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXLAABO DEC/X8 MOD LA180

1ST Copyright year : 1977

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C694B-MA		AC-C692B-MA		AH-C693B-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Does not support 128K system configurations.

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128K.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : LA180

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K. Fleming
Charge Number	: V89-08202	Coordination Number	: MC2208

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C263B-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXLDA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXLDAB0 DEC/X8 MOD LPD8

1ST Copyright year : 1975

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C265B-MA		AC-C263B-MA		AH-C264B-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Does not support 128K system configurations.

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128K.
THIS ECO REPLACES MD-X8-DILDA-A.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2209

A

Component Part Number : AF-C267C-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXLPA-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXLPACO DEC/X8 MOD PRINTER

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C269C-MA		AC-C267C-MA		AH-C268C-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Does not support 128K system configurations.
HISTORY STARTS AT REV B0.

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128K.
THIS ECO REPLACES MD-X8-DILPA-B0.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2210

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-C192B-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXLQA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXLQAB0 DECX/8 MOD LQP-8

1ST Copyright year : 1977

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C195B-MA		AC-C192B-MA		AH-C194B-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Does not support 128K system configurations.
THIS ECO REPLACES MD-X8-DHLQA-A0/00.

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128K.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : 00000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2211

A

Component Part Number : AF-C270B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXPAAB0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXPAAB0 DEC/X8 MOD TYPSET

1ST Copyright year : 1973

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C272B-MA		AC-C270B-MA		AH-C271B-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Does not support 128K system configurations.
THIS ECO REPLACES MD-X8-DIPAA-A.

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128K.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2212

A

Component Part Number : AF-C273B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXPCA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXPCAB0 DEC/X8 MOD HSRHSP

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AK-C275B-MA		AC-C273B-MA		AH-C274B-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Does not support 128K system configurations.
THIS ECO REPLACES MD-X8-DIPCA-A/00.

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128k.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2213

A

Component Part Number : AF-C276E-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 03

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXQAB-E0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : NA

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AK-C278E-MA		AC-C276E-MA		AH-C277E-MA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

Does not support 128K systems.
THIS ECO REPLACES MD-X8-DIQAB-D2/02.

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128K.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZF014 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2214

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-C282E-M0

Component Part Description : ECO TALLY 02

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXQAD-E0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXQADE0 DEC/X8 DETAILED DESC

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C282E-MA		AH-C283E-MA					

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Does not support 128K systems.
HISTORY COUNT STARTS AT REV C.

-----SOLUTION/CORRECTION-----

Updated to support maximum size of 128k.
THIS ECO REPLACES MD-X8-DIQAD-D.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 89 90 91 92 93

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number :

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: MK-DIAG
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2216

A

Component Part Number : AF-C612B-A0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXQQB-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXQQAB0 APT-8 SYS DEC/X8

1ST Copyright year : 1975

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C613B-AA		AC-C612B-AA		AL-C614B-NA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DOES NOT SUPPORT 128K SYSTEMS.

-----SOLUTION/CORRECTION-----

Updated to support maximum size of 128K.
THIS ECO REPLACES MD-X8-QIQAB-A.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors : 12 88 89 90 91 92

Operational Environment : 99

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number :

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2217

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C279B-M0

Component Part Description : ECO 1st Y 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXQAC-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXQACB0 DEC/X8 SW INTFCG SPEC

1st Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C279B-MA							

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Document does not reflect the latest external symbol table.
THIS ECO REPLACES MD-X8-DIQAC-A.

-----SOLUTION/CORRECTION-----

Documentation change to appendix A to update the external symbol table to the latest level.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : . ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number :

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	:
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2215

1 OF 1
: B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-00000-MC

Component Part Description : ECO TALLY 01

ECO Purpose : Patch

Approved : No

Diagnostic Package Code : AHDRH-A2

-----PRODUCT IDENTIFICATION-----
Patch Level : 2

Product Date : 18-Apr-79

Description : DR8-ED DIAGNOSTIC

1ST Copyright year : 1975

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

LOGIC TEST DOES HALT INSTRUCTION, WAITS FOR OPERATOR TO DO "START" OR "CLEAR", "CONTINUE" IN ORDER TO TEST LOGIC SIGNALS. SOME MACHINES DO NOT HAVE THESE SWITCHES.

-----SOLUTION/CORRECTION-----

INSTALL PATCH ON MACHINES THAT DO NOT HAVE "START" OR "CLEAR", "CONTINUE" SWITCH.

-----DEPO PATCH AREA-----

Loc	From	To	Mnemonic	Loc	From	To	Mnemonic
1647	7640	7300					

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : *No

Processors : 88

Operational Environment : 00

Device Affected : DR8-ED

Problem Reports Affected :

Kit Number : ZF013 ZF223

-----AUTHORIZATION-----

Author	: E BADGER	Maintaining Group	: PRO ENH
Submitting Engineer	: ED BADGER	Maintainer	: J. VROBEL
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. BEIKE	Release Engineer	: S. DUMDEY
Charge Number	: D40-07921	Coordination Number	: MC3129

A

1 OF 1
: B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-6315D-M0

Component Part Description : ECO TALLY 03

ECO Purpose : Change

Approved : No

Diagnostic Package Code : AHLQA-D0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 13-Aug-79

Description : AHLQAD LQP-8 PRINTER DIAG

1ST Copyright year : 1977

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-6315D-MA		AK-6318D-MA		AH-6317D-MA		AL-6319D-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

PROGRAM DOES NOT OVERWRITE FOR BITS 10 AND 11 IN STATUS REGISTER WHEN RUNNING ON A VT78. AFTER MAINDEC TITLE IS PRINTED PROGRAM DOES NOT COME BACK WITH SR=0000, SO YOU CAN HAVE THE OPTION OF USING PSEUDO SR.

-----SOLUTION/CORRECTION-----

PROGRAM NOW OVERWRITES FOR BITS 10 AND 11 IN STATUS REGISTER IF RUNNING ON A VT78. AFTER MAINDEC TITLE IS PRINTED, COMES BACK WITH SR=0000 SO YOU CAN HAVE THE OPTION OF USING PSEUDO SR.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 99

Device Affected : VT78 LQP

Problem Reports Affected :

Kit Number : ZF008 ZF014

-----AUTHORIZATION-----

Author	: DAVE ORIN	Maintaining Group	: PROD. ENH.
Submitting Engineer	: H. CZIRIA	Maintainer	: JOHN VROBEL
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. SEIKE	Release Engineer	: S. DUMDEY
Charge Number	: V98-05460	Coordination Number	: MC3260

A

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-A825C-M0

Component Part Description : ECO TALLY 03

ECO Purpose : Change

Approved : No

Diagnostic Package Code : AKVTB-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 20-Jul-79

Description : AKVTBC0 VT78 CPU DIAG

1ST Copyright year : 1977

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-A825C-MA		AK-A825C-MA		AH-A827C-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DIAG DOES NOT RELIABLY TEST SLU2 AND SLU3 WITH EXTERNAL JUMPERS. DOCUMENTATION NEEDED TO DEFINE HARDWARE CONFIGURATION NEEDED TO TEST SLU'S WITH EXTERNAL JUMPERS.

-----SOLUTION/CORRECTION-----

HARDWARE CONFIGURATION SETTING (HW3) BIT5=1 DISABLES THE PROGRAMMABLE SLU LOOPBACK AND ALLOWS YOU TO SUBSTITUTE EXTERNAL JUMPERS. JUMPER PINS 2 & 3 ON SLU2 AND JUMPER PINS 2 & 3 ON SLU3.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 20 2nd Pass : 20 ACT Sequence Number : Multimedia Affected : Yes

Processors : 95

Operational Environment : 00 20 99

Device Affected : VT78

Problem Reports Affected : CC0001010

Kit Number : ZF014

-----AUTHORIZATION-----

Author	: B. POLAND	Maintaining Group	: PRO ENH
Submitting Engineer	: H. CZIRIA	Maintainer	: J. VROBEL
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. BEIKE	Release Engineer	: S. DUMDEY
Charge Number	: V98-05960	Coordination Number	: MC3236

A

Component Part Number : AF-C276E-M1

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 04

ECO Purpose : Patch

Approved : No

Diagnostic Package Code : AXQAB-E1

PRODUCT IDENTIFICATION

Patch Level : 1

Product Date : 01-Aug-78

Description : AXQABE1 DEC/X8 USERS GUIDE

1ST Copyright year : 1972

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THE EAEDP AND EAEALL MODULES FAIL WITH KT8A
ABOVE 64K OF MEMORY. THE FAILURE ONLY OCCURS
WHEN RUNNING ABOVE 64K OF MEMORY.

-----SOLUTION/CORRECTION-----

INSTALL CONDITIONAL PATCH TO CORRECT PROBLEM.

-----DEPO PATCH AREA-----

Loc	From	To	Mnemonic	Loc	From	To	Mnemonic
21674	7450	7000					
21675	5300	6005					
21676	6005	7200					

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : *Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0001009

Kit Number : ZF229 ZF014 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: J. VROBEL	Maintainer	: D. CASALETTO
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. CASELLA	Release Engineer	: S. DUMDEY
Charge Number	: V28-05460	Coordination Number	: MC3160

OF 1
B

A
C
C
D
D
E
P
A
N
R
P
O
D
P
K
A
S
P
M
C

A

Component Part Number : AF-C612B-A1

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 02

ECO Purpose : Patch

Approved : No

Diagnostic Package Code : AXQQB-B1

-----PRODUCT IDENTIFICATION-----

Patch Level : 1

Product Date : 01-Aug-79

Description : AXQQB1 APT-8 SYS DEC/X8

1ST Copyright year : 1975

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THE EAEDP AND EAEALL MODULES FAIL WITH KT8A
ABOVE 64K OF MEMORY. THE FAILURE ONLY OCCURS
WHEN RUNNING ABOVE 64K OF MEMORY.

-----SOLUTION/CORRECTION-----

INSTALL CONDITIONAL PATCH TO CORRECT PROBLEM.

-----DEPO PATCH AREA-----

Loc	From	To	Mnemonic	Loc	From	To	Mnemonic
21674	7450	7000					
21675	5300	6005					
21676	6005	7200					

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : *No

Processors : 12 88 89 90 91 92

Operational Environment : 99

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number :

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: MK-DIAG
Submitting Engineer	: J. VROBEL	Maintainer	: Glenn Johnson
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. CASELLA	Release Engineer	: S. DUMDEY
Charge Number	: V98-05460	Coordination Number	: MC3161

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-E752A-A0

Component Part Description : ECO TALLY 00

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : ARRXA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 16-Aug-78

Description : ARRXAA0 RX28E BRUTUS

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-E752A-AA		AK-E751A-AA		AL-E753A-NA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

PROGRAM NEEDED TO VERIFY AND DEBUG DESIN CHARACTERISTICS OF RX02. ALSO PROGRAM MAY BE USED TO REPAIR MODULES OF KNOW FAILURES

-----SOLUTION/CORRECTION-----

WRITE A BRUTE FORCE DRIVER TO ENGINEERING SPECIFICATIONS IN HOUSE USE ONLY.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors : 89 90 91 92 93 95

Operational Environment : 00 99

Device Affected : RX02

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author	: B IRRGANG	Maintaining Group	: SML SYS
Submitting Engineer	: B IRRGANG	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: DAVE BROWN	Release Engineer	: T.DAVIES
Charge Number	: V98-05350	Coordination Number	: MC2159

A
Co
Co
Di
De
Ex
TH
BE
Ru
Pr
Op
De
Pr
Ki
Au
Su
Pr
Ma
Ch
AH
AJ
AJ
AJ
AJ
AJ
08
AJ

A

Component Part Number : AF-E589A-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 00

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXRXC-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 16-Aug-78

Description : AXRXCA0 DEC/X8 MOD RX02

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-E589A-MA		AK-E591A-MA		AH-E590A-MA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

NEW DEC/X8 MOUDLE REQUIRED TO SUPPORT RX02.

-----SOLUTION/CORRECTION-----

MODIFY OLD "FLOPPY" DEC/X8 TO CREATE NEW MODULE TO SUPPORT RX02.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92 95

Operational Environment : 50

Device Affected : RX02

Problem Reports Affected :

Kit Number : ZF229 ZF238 ZK229

-----AUTHORIZATION-----

Author	: R.IRRGANG	Maintaining Group	: SML SYS
Submitting Engineer	: B.IRRGANG	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: DAVE BROWN	Release Engineer	: T.DAVIES
Charge Number	: V98-05350	Coordination Number	: MC2160

A

Component Part Number : AF-6585F-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 07

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIRXB-F0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 16-Aug-78

Description : NA

1ST Copyright year : 1975

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-6587F-MA		AC-6585F-MA		AH-6586F-MA		AL-6588F-NA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

Program needs enhancing to include support of RX02 and VI78. Also problems exist with existing program and has outstanding depo. Problems are: document error suggesting support of 'Cntrl E' character and with print routine.

-----SOLUTION/CORRECTION-----

Clear up outstanding Depo, fix problems in print routine (Change temp. storage for subroutines from loc 23 to some other location), correct documentation concerning 'Cntrl E', and enhance program for RX02. THIS ECO REPLACES MD-08-DIRXB-E1.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :	2nd Pass :	ACT Sequence Number :	Multimedia Affected : Yes
Processors	: 88 89 90 91 92 93 94 95		
Operational Environment	: 00 20 99		
Device Affected :	RX01 RX02		
Problem Reports Affected	: CC0000858 CC0000736		
Kit Number	: ZF008 ZF013 ZF220 ZF014 ZF010		

-----AUTHORIZATION-----

Author	: B Irrgang	Maintaining Group	: Sml Sys
Submitting Engineer	: B Irrgang	Maintainer	: G Johnson
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: K Fleming
Charge Number	: V98-05350	Coordination Number	: MC2186

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-E505B-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJKTA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 25-May-78

Description : AJKTAB0 KT8-A MEM MNGMT OPT

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-E506B-MA		AC-E505B-MA		AH-E507B-MA		AL-E508B-MA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Diagnostic would cause 'hung diagnostic' error message when run on the APT system. Diagnostic does not support PDP-8E XOR.

-----SOLUTION/CORRECTION-----

Corrected timing problems to allow diagnostic to run on the APT system. Provided PDP-8E XOR hooks. THIS ECO REPLACES MD-08-DJKTA-A0/00.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 90 2nd Pass : 90 ACT Sequence Number : Multimedia Affected : Yes

Processors : 92

Operational Environment : 00 20 99

Device Affected : KT8A

Problem Reports Affected : CC0000940

Kit Number : ZF233

-----AUTHORIZATION-----

Author	: D Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: D Rice	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: Carl Cline
Manufacturing Engineer	:	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2187

A

Component Part Number : AF-C189B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXKED-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXKEDB0 DEC/X8 MOD EAEDP

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AK-C191B-MA		AC-C189B-MA		AH-C190B-MA			

-----PRODUCTS OBSOLETED-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128K.
THIS ECO REPLACES MD-X8-DHKEA-A.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2203

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-C256B-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXKLC-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Aug-78

Description : AXKLCB0 DEC/X8 MOD MULSLU

1ST Copyright year : 1976

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C258B-MA		AC-C256B-MA		AH-C257B-MA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

DOES NOT SUPPORT 128K SYSTEM CONFIGURATIONS.

-----SOLUTION/CORRECTION-----

Updated to support maximum system size of 128K.
THIS ECO REPLACES MD-X8-DIKLC-A.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : CC0000949

Kit Number : ZF229 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: Sml Sys
Submitting Engineer	: Don Rice	Maintainer	: MISNER
Product Engineer	: Straka/Cook	Field Service Engineer	: Carl Cline
Manufacturing Engineer	: WAIVERED	Release Engineer	: K Fleming
Charge Number	: V89-08202	Coordination Number	: MC2206

A

Component Part Number : AF-6581E-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 02

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIRXA-E0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 05-Sep-78

Description : AIRXAEO RX01/02 FUNCT TEST

1ST Copyright year : 1975

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-6581E-MA		AK-6583E-MA		AH-6582E-MA		AL-6584E-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

PROGRAM NEEDS ENHANCING TO SUPPORT RX02.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88 89 90 91 93 94 95 92

Operational Environment : 00 02 99

Device Affected : RX01 RX02

Problem Reports Affected : CC0000966

Kit Number : ZF008 ZF013 ZF220 ZF014 ZF010

-----AUTHORIZATION-----

Author : B IRRGANG
Submitting Engineer : B IRRGANG
Product Engineer :
Manufacturing Engineer :
Charge Number : V98-05350

Maintaining Group : SML SYS
Maintainer : G JOHNSON
Field Service Engineer :
Release Engineer : R RAWSKI
Coordination Number : MC2363

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AH-65711-M0

Component Part Description : ECO TALLY 08

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIGAC-10

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Oct-78

Description : AIGAC10 PDP-8 MAINDEC INDEX

1ST Copyright year : 1976

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-65711-MA		AH-65721-MA					

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

INDEX UPDATED TO REFLECT CHANGES TO PDP-8 DIAGNOSTICS.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors : :

Operational Environment : :

Device Affected : INDEX

Problem Reports Affected : :

Kit Number : :

-----AUTHORIZATION-----

Author	: Release Eng	Maintaining Group	: Release Eng
Submitting Engineer	: D Beausoleil	Maintainer	: C Cinnamon
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: C Cinnamon	Release Engineer	: T.DAVIES
Charge Number	: V98-08162	Coordination Number	: MC2378

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-F101J-M0

Component Part Description : ECO TALLY 09

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIZAA-J0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Oct-78

Description : AIZAAJ0 PDP-8 MULTI-MEDIA

1ST Copyright year : 1976

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THE FOLLOWING MULTI-MEDIA REVISIONS WILL
BE EFFECTIVE IN OCT. 1978.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :	2nd Pass :	ACT Sequence Number :	Multimedia Affected : Yes
Processors :			
Operational Environment :			
Device Affected :			
Problem Reports Affected :			
Kit Number :			

-----AUTHORIZATION-----

Author :	Release Eng	Maintaining Group :	Release Eng
Submitting Engineer :	D Beausoleil	Maintainer :	C Cinnamon
Product Engineer :		Field Service Engineer :	
Manufacturing Engineer :	C Cinnamon	Release Engineer :	K Fleming
Charge Number :	V98-08162	Coordination Number :	MC2380

-----CONTINUATION-----

AH05 Q R COS 300 RK	AJRXF D E RX01 #3
AJRLZ NEW A RL01 DSK	AJRXG B C RX01 #4
AJRXA M N CL/8 #1	AJRXH B C WS202 RX
AJRXB F G PDP-8 RX	08-DKRXA A AKRXA-B VT78 RX
AJRXC I J RX01 #1	AXQAA N O DEC/X8 LT
08-DJRXD D AJRXD-E RX01 #2	AXQAE N O DEC/X8 DT
08-DJRXE C -- CL/8 #2	AXRXA H I DEC/X8 RX

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C290M-M0

Component Part Description : ECO TALLY 06

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXQAF-M0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Oct-78

Description : AXQAFM0 DEC/X8 SW MOD INX

1ST Copyright year : 1973

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C290M-MA		AH-C292M-MA					

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DOCUMENT UPDATED TO REFLECT DEC/X8 MODULE CHANGES.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors : :

Operational Environment : :

Device Affected : :

Problem Reports Affected : :

Kit Number : ZK229 ZF229

-----AUTHORIZATION-----

Author	: REL ENG	Maintaining Group	: Rel Eng
Submitting Engineer	: D Beausoleil	Maintainer	: C Cinnamon
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: C Cinnamon	Release Engineer	: TDAVIES
Charge Number	: V98-05077	Coordination Number	: MC2379

1 OF 1
: B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-6585F-M1

Component Part Description : ECO TALLY 08

ECO Purpose : Patch

Approved : Yes

Diagnostic Package Code : AIRXB-F1

-----PRODUCT IDENTIFICATION-----

Patch Level : 1

Product Date : 18-Oct-78

Description : AIRXBF1 RX01/02 PERF EXER

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

PROGRAMS GET LOST AT END OF PASS AND WILL NOT RESTART.

-----SOLUTION/CORRECTION-----

THIS PROBLEM ONLY OCCURS WHEN AN ERROR HAPPENS ON A PASS.
PROBLEM IS IN ROUTINE 'ERROR 3' DCA TO ADDRESS 'MDIRECTIVE'
IS TO WRONG FIELD. SOLUTION NOP'S THE DEA.
THIS WILL BE CLEARED UP BETTER IN NEXT REVISION.

-----DEPO PATCH AREA-----

Loc	From	To	Mnemonic	Loc	From	To	Mnemonic
1161	3221	7200					
11701	6000	6100					

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors : 88 89 90 91 92 93 94 95

Operational Environment : 00 20 99

Device Affected : RX01 RX02

Problem Reports Affected : CC0001007

Kit Number : ZF008 ZF013 ZF220 ZF014 ZF010

-----AUTHORIZATION-----

Author	: B Irrgang	Maintaining Group	: DIAG ENG
Submitting Engineer	: B Irrgang	Maintainer	: SML SYS
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: MAUREEN HANSEN
Charge Number	: V98-05350	Coordination Number	: MC2479

A

Component Part Number : AF-E629A-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 00

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AKDPA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 13-Nov-78

Description : AKDPAA0 DP78 DATA AND REG TST

1ST Copyright year : 1978

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-E629A-MA		AK-E630A-MA		AH-E631A-MA		AL-E632A-MA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

NEW SUBMISSION

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 120 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 95

Operational Environment : 00 20 99

Device Affected : DP78

Problem Reports Affected :

Kit Number : ZF014

-----AUTHORIZATION-----

Author : D.RICE	Maintaining Group : SML SYS
Submitting Engineer : D.RICE	Maintainer : MISNER
Product Engineer :	Field Service Engineer :
Manufacturing Engineer :	Release Engineer : MAUREEN HANSEN
Charge Number : V89-03396	Coordination Number : MC2537

OF 1
B

A

Component Part Number : AF-F101K-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 10

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIZAA-K0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Dec-78

Description : AIZAAK0 PDP-8 MULTI-MEDIA

1ST Copyright year : 1976

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THE FOLLOWING MULTI-MEDIA REVISIONS WILL
BE EFFECTIVE IN DEC. 1978.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : No

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : REL ENG
Submitting Engineer : D Beausoleil
Product Engineer :
Manufacturing Engineer : C Cinnamon
Charge Number : V98-08815

Maintaining Group : Release Eng
Maintainer : C Cinnamon
Field Service Engineer :
Release Engineer : K Fleming
Coordination Number : MC2560

-----CONTINUATION-----

AH05-R-S-COS 300 RK
AJRLZ-A-B-RL01 DSK
AJRXA-N-O-CL/8 #1
AJRXB-G-H-PDP-8 RX
AJRXC-J- RX01 #1
AJRXD-E RX01 #2
08-DJRXE-C CL/8 #2
AJRXF-E RX01 #3

AJRXG-C RX01 #4
AJRXH-C-D WS202 RX
AKRXA-B-C VT78 RX
AJRXI-A-NEW DEC 88 RX
AXQAA-O DEC/X8 LT
AXQAE-O DEC/X8 DT
AXRXA-I DEC/X8 RX

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-6653C-MO

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJEXC-CO

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 28-Nov-78

Description : AJEXCCO 4K IO 32K PROC EXER

1ST Copyright year : 1975

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-6653C-MA		AK-6655C-MA		AH-6654C-MA		AL-6656C-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DIAGNOSTIC GETS LOST OR PRINT BAD ERROR INFORMATION ON A VT78.

-----SOLUTION/CORRECTION-----

PROGRAM UPDATED TO ENHANCE ERROR REPORTS, DATA CHECKING WAS PROVIDED, AND ORIGINAL DATA REPLACED AFTER EXECUTION.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92 95

Operational Environment : 00 20 99

Device Affected : PDP8A

Problem Reports Affected : CC0001019

Kit Number : ZF008 ZF014 ZF009 ZF016 ZF214 ZF010

-----AUTHORIZATION-----

Author	: BRUCE HANSEN	Maintaining Group	: DIAG-MK
Submitting Engineer	: B POLAND	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: K. MASSEY	Release Engineer	: S. DUMDEY
Charge Number	: V89 -08202	Coordination Number	: MC2790

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-6229C-M0

Component Part Description : ECO TALLY 02

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AHDRA-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 30-Jan-79

Description : AHDRA0 DR8-EA 12 CHAN INTFC

1ST Copyright year : 1972

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-6229C-MA		AK-6231C-MA		AH-6230C-MA		AL-6232C-NA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

WHEN RUNNING AHDRA UNDER APT THE DIAG. WILL HANG IN AN ERROR LOOP.

-----SOLUTION/CORRECTION-----

TO EFFECTIVELY RUN AHDRA UNDER APT, LOCATION 4414 WAS CHANGED TO A CMA TO CORRECTLY SET UP THE INTERRUPT JUMPER MASK FOR INPUT REGISTER BITS.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 90 89 91 92

Operational Environment : 00 20

Device Affected : DR8-EA

Problem Reports Affected : CC0000915

Kit Number : ZF013 ZF136

-----AUTHORIZATION-----

Author	: D. MACOMBER	Maintaining Group	: PRO ENH
Submitting Engineer	: H. CZIRIA	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: G. BEAN	Release Engineer	: S. DUMDEY
Charge Number	: V98 -05460	Coordination Number	: MC2842

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-F382A-M0

Component Part Description : ECO TALLY 00

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXRLB-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 23-Feb-79

Description : AXRLBA0 DEC/X8 MOD RL8/RL02

1ST Copyright year : 1979

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-F382A-MA		AK-F383A-MA		AH-F384A-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

NONE, NEW PROGRAM.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected :

Kit Number : ZF241

-----AUTHORIZATION-----

Author	: HANK POULTER	Maintaining Group	: SMALL SYSTEMS
Submitting Engineer	: HANK POULTER	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. BEIKE	Release Engineer	: S. DUMDEY
Charge Number	: P89-08202	Coordination Number	: MC2952

A

Component Part Number : AF-6315C-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 02

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AHLQA-C0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 29-Mar-79

Description : AHLQACO LQP-8 PRINTER DIAG

1ST Copyright year : 1977

Last Copyright Year : 1979

Expanded Description :

Component		Media		Component		Media	
Part Number	Variable						
AC-6315C-MA		AK-6318C-MA		AL-6319C-NO		AH-6317C-MA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

SPECIAL ADDRESS LOCATIONS IN DIAGNOSTIC DHLQAB,
SECTION 8.2, ARE INCORRECT FOR REV. B.

-----SOLUTION/CORRECTION-----

SPECIAL ADDRESS LOCATIONS:
LINE LOC 127 CHANGED TO 131.
SPACE LOC 125 CHANGED TO 127.
I.F LOC 126 CHANGED TO 130.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 99

Device Affected : VT78 LOP8

Problem Reports Affected : CC0001016

Kit Number : ZF008 ZF014

-----AUTHORIZATION-----

Author	: DAVE ORIN	Maintaining Group	: PROD. ENH.
Submitting Engineer	: H. CZIRIA	Maintainer	: JOHN VROBEL
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: M. HANSEN
Charge Number	: 098-05460	Coordination Number	: MC2811

Component Part Number : AF-F101L-M0

Component Part Description : ECO TALLY 11

Diagnostic Package Code : AIZAA-L0

Description : AIZAA0 PDP-8 MULTI-MEDIA

Expanded Description :

ECO Purpose : Change

PRODUCT IDENTIFICATION

Patch Level : 0

1ST Copyright year : 1976

Approved : Yes

Product Date : 01-feb-79

Last Copyright Year : 1979

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THE FOLLOWING MULTI-MEDIA REVISIONS WILL BE
EFFECTIVE IN FEB. 1979.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :	2nd Pass :	ACT Sequence Number :	Multimedia Affected : *No
Processors :			
Operational Environment :			
Device Affected :			
Problem Reports Affected :			
Kit Number :			

-----AUTHORIZATION-----

Author :	REL ENG	Maintaining Group :	Release Eng
Submitting Engineer :	D Beausoleil	Maintainer :	MISNER
Product Engineer :		Field Service Engineer :	
Manufacturing Engineer :	C Cinnamon	Release Engineer :	M. HANSEN
Charge Number :	V98-08162	Coordination Number :	MC2839

-----CONTINUATION-----

AH05B--S--T	AJRXG--C--
AJRLZ--B--C	AJRXH--D--E
AJRXA--O--P	AJRXI--A--B
AJRXB--H--I	AKRXB--NEW--A
AJRXC--J--	AXQAA--O--
AJRXD--E--	AXQAE--O--
08-DJRXE--C--	AXRXA--I--
AJRXF--E--	AKRXA--C--D

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-C656C-M0

Component Part Description : ECO TALLY 02

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLA-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 29-Mar-79

Description : AJRLACO RL8-A DSKLS CTRLR

1ST Copyright year : 1978

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-C656C-MA		AK-C658C-MA		AH-C657C-MA		AL-C659C-NA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

DOCUMENTATION DOES NOT INCLUDE RL02.

-----SOLUTION/CORRECTION-----

CHANGE DOCUMENTATION AND TEXT FILE TO SAY THAT THIS PROGRAM WILL TEST BOTH THE RL8/RL01 AND RL8/RL02.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 5 2nd Pass : 90 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A RL02

Problem Reports Affected :

Kit Number : ZF241

-----AUTHORIZATION-----

Author	: HANK POULTER	Maintaining Group	: Small Sys
Submitting Engineer	: HANK POULTER	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: GREG BEAN	Release Engineer	: M. HANSEN
Charge Number	: P89-08202	Coordination Number	: MC2951

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-F362A-M0

Component Part Description : ECO TALLY 00

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLH-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 29-Mar-79

Description : AJRLHA0 RL8/RL02

1ST Copyright year : 1979

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-F362A-MA		AK-F363A-MA		AH-F364A-MA		AL-F365A-MA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

NONE, NEW PROGRAM.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 390

2nd Pass : 390

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A/RL0

Problem Reports Affected :

Kit Number : ZF241

-----AUTHORIZATION-----

Author : HANK POULTER
Submitting Engineer : HANK POULTER
Product Engineer :
Manufacturing Engineer :
Charge Number : P89-08202

Maintaining Group : SMALL SYSTEMS
Maintainer : MISNER
Field Service Engineer :
Release Engineer : M. HANSEN
Coordination Number : MC2950

1 OF 1
: B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-F366A-M0

Component Part Description : ECO TALLY 0

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLI-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 29-Mar-79

Description : AJRLIA0 RL8/RL02

1ST Copyright year : 1979

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-F366A-MA		AK-F367A-MA		AH-F368A-MA		AL-F369A-MA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

NONE, NEW PROGRAM.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 120 2nd Pass : 300 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A/RL0

Problem Reports Affected :

Kit Number : ZF241

-----AUTHORIZATION-----

Author : HANK POULTER
Submitting Engineer : HANK POULTER
Product Engineer :
Manufacturing Engineer :
Charge Number : P89-08202

Maintaining Group : SMALL SYS.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : M. HANSEN
Coordination Number : MC2949

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-F370A-M0

Component Part Description : ECO TALLY 0

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLJ-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 29-Mar-79

Description : AJRLJA0 RL8/RL02 DRV CPT

1ST Copyright year : 1979

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-F370A-MA		AK-F371A-MA		AH-F372A-MA		AL-F373A-MA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

NONE, NEW PROGRAM

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 300 2nd Pass : 300 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8ARL02

Problem Reports Affected :

Kit Number : ZF241

-----AUTHORIZATION-----

Author	: HANK POULTER	Maintaining Group	: SMALL SYS
Submitting Engineer	: HANK POULTER	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: M. HANSEN
Charge Number	: F89-08202	Coordination Number	: MC2948

A

Component Part Number : AF-F374A-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 0

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLK-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 29-Mar-79

Description : AJRLKA0 RL8/RL02 PERF EXER

1ST Copyright year : 1979

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-F374A-MA		AK-F375A-MA		AH-F376A-MA		AL-F377A-MA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

NONE, NEW PROGRAM.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 300 2nd Pass : 32767 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A/RL0

Problem Reports Affected :

Kit Number : ZF241

-----AUTHORIZATION-----

Author : HANK POULTER
Submitting Engineer : HANK POULTER
Product Engineer :
Manufacturing Engineer :
Charge Number : P89-08202

Maintaining Group : SMALL SYS.
Maintainer : MISNER
Field Service Engineer :
Release Engineer : M. HANSEN
Coordination Number : MC2947

OF 1
B

A

Component Part Number : AF-F378A-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 0

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLL-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 29-Mar-79

Description : AJRLLA0 RL8/RL02 PCK VFYR

1ST Copyright year : 1979

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AF-F378A-MA		AK-F379A-MA		AH-F380A-MA		AL-F381A-MA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

NONE, NEW PROGRAM.

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 40 2nd Pass : 960 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A/RL0

Problem Reports Affected :

Kit Number : ZF241

-----AUTHORIZATION-----

Author	: HANK POULTER	Maintaining Group	: SMALL SYS.
Submitting Engineer	: HANK POULTER	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: M. HANSEN
Charge Number	: P89-08202	Coordination Number	: MC2946

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Patch

Approved : Yes

Diagnostic Package Code : MD-08-DKVTB-A1

-----PRODUCT IDENTIFICATION-----

Patch Level : 1

Product Date : 01-Jan-79

Description :

1ST Copyright year : 1977

Last Copyright Year : 1979

Expanded Description : VT78 CPU DIAGNOSTIC

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

VT78 CPU DIAGNOSTIC DOES NOT SUPPORT THE
RX02.

-----SOLUTION/CORRECTION-----

INSERT THE FOLLOWING PATCH.

-----DEPO PATCH AREA-----

Loc	From	To	Mnemonic	Loc	From	To	Mnemonic
15172	277	227					

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 20 2nd Pass : 20 ACT Sequence Number : Multimedia Affected : *No

Processors : 95

Operational Environment : 00 20 99

Device Affected : VT78

Problem Reports Affected :

Kit Number : ZF014

-----AUTHORIZATION-----

Author	: DIAG ENG.	Maintaining Group	: DIAG ENG.
Submitting Engineer	: SAM CARPENTER	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: M. HANSEN
Charge Number	: V89-08202	Coordination Number	: MC2812

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Patch

Approved : Yes

Diagnostic Package Code : MD-08-DHLQB-B1

PRODUCT IDENTIFICATION

Patch Level : 1

Product Date : 29-Mar-79

Description :

1ST Copyright year : 1977

Last Copyright Year : 1979

Expanded Description : LQP8 MULTIPLE PRINTER DIAGNOSTIC

PRODUCT COMPONENTS AFFECTED

Component Part Number	Media Variable						
DHLQB-B-D		DHLQB-B-PB		DHLQB-B-UA			

PRODUCTS OBSOLETED

PROBLEM/DESCRIPTION

1) PROGRAM DESIGNED TO RUN ON SPECIAL HARDWARE AND THEREFORE RESTRICTED DISTRIBUTION TO MANUFACTURING ONLY. WPS 80 PRODUCT LINE HAS SYSTEMS WITH UP TO 4 LQP PRINTERS AND WOULD LIKE TO USE THIS PROGRAM ON THEIR KIT.

SOLUTION/CORRECTION

A TWO LOCATION PATCH WILL ALLOW THE PROGRAM TO BE RUN ON THE WPS80/WPS200 AND BE INCLUDED IN THE ZF0016 KIT. THE PATCH WILL ALLOW THE USE OF DEVICE CODES 650X THRU 653X.

PRODUCT CHARACTERISTICS

Run Time (seconds) 1st Pass :	2nd Pass :	ACT Sequence Number :	Multimedia Affected : Yes
Processors : 89 90 91			
Operational Environment : 00 99			
Device Affected : LQP8 (M8366)			
Problem Reports Affected :			
Kit Number :			

AUTHORIZATION

Author : DAVID ORIN	Maintaining Group : SML SYS
Submitting Engineer : D. ORIN	Maintainer : MISNER
Product Engineer :	Field Service Engineer :
Manufacturing Engineer :	Release Engineer : M. HANSEN
Charge Number : V89-08202	Coordination Number : MC3063

CONTINUATION

FLD 0 ADRS 0341 FROM 7750 TO 7774

FLD 0 ADRS 4576 FROM 7750 TO 7774

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

Component Part Number :

Component Part Description :

ECO Purpose : Patch

Approved : Yes

Diagnostic Package Code : MD-08-DZZZZ-D2

-----PRODUCT IDENTIFICATION-----

Patch Level : 2

Product Date : 12-Aug-79

Description :

1ST Copyright year : 1979

Last Copyright Year : 1979

Expanded Description : AZZZZ-D2 EXPANDED DESCRIPTION

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AF-00000-D2		AK-00000-M2					

-----PRODUCTS OBSOLETE-----

NO PROBLEM

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

NO SOLUTION

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 01 02

Operational Environment : 32 01 70

Device Affected :

Problem Reports Affected :

Kit Number : ZJ124

-----AUTHORIZATION-----

Author	: K FLEMING	Maintaining Group	: DIAGNOSTICS
Submitting Engineer	: K FLEMING	Maintainer	: C CINNAMON
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: K FLEMING
Charge Number	: 000-00000	Coordination Number	: MC9997

A

Component Part Number : AF-C2900-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 13

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXQAF-00

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Oct-79

Description : AXQAF00 DEC/X8 SW MOD INX

1ST Copyright year : 1973

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C2900-MA		AH-C2920-MA					

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

INDEX NEEDS UPDATING

-----SOLUTION/CORRECTION-----

INDEX UPDATED

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number : ZF229

-----AUTHORIZATION-----

Author	: REL ENG	Maintaining Group	: REL ENG
Submitting Engineer	: D Beausoleil	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: C Cinnamon	Release Engineer	: TDAVIES
Charge Number	: 098-08815	Coordination Number	: MC3546

-----CONTINUATION-----

?

Component Part Number : AF-B839C-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AHXYA-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 15-Oct-79

Description : AHXYACO PLTR CTRL & DSPLY

1ST Copyright year : 1971

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-B839C-MA		AK-B841C-MA		AH-B840C-MA		AL-B842C-NA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

TIMING PROBLEM, PLLP IOT WITH AC=NN SET FLAG PRIOR TO SMS. PROGRAM DOES NOT TAKE INTO CONSIDERATION SOME TTY DO NOT HAVE AN ALTMODE BUT USE AN ESCAPE KEY. PROGRAM DOES NOT RUN ON AN UNENCODED 663 CAL COMP PLOTTER SERIES.

-----SOLUTION/CORRECTION-----

BECAUSE OF DIFFERENT KINDS OF MEMORY, TIMING CONSTANTS WERE CHANGED TO SO IT TAKES THIS INTO CONSIDERATION. BECAUSE OF TTY DIFFERENCES, PROGRAM TESTS FOR ALTMODE OR ESCAPE KEY. PROGRAM CHANGED TO TEST FOR UNENCODED OR ENCODED, 8 OR 24 VECTORS PLOTTER SERIES.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 92

Operational Environment : 00

Device Affected : XY8-E

Problem Reports Affected : HH0000340

Kit Number : ZF011 ZF194

-----AUTHORIZATION-----

Author	: L. BEYERSDORFER	Maintaining Group	: PRO ENH
Submitting Engineer	: H. CZIRIA	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. CASELLA	Release Engineer	: S. DUMDEY
Charge Number	: V98-05460	Coordination Number	: MC3408

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

A

Component Part Number : AF-6208B-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AHDHA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 25-Oct-79

Description : AHDHAB0 DH8E HOST PROGRAM

1ST Copyright year : 1976

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-6208B-MA		AK-6210B-MA		AH-6209B-MA		AL-6211B-NA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

WOULD NOT READ DECX/8 MULTIPLE SEGMENT PAPER
TAPES OR FILES.

-----SOLUTION/CORRECTION-----

ENHANCED PROGRAM TO READ DEC/X8 MULTIPLE SEGMENT
PAPER TAPES OR FILES.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 50

Device Affected : DH8E

Problem Reports Affected : CC0000707

Kit Number : ZF230 ZF238

-----AUTHORIZATION-----

Author	: J. ADAMS	Maintaining Group	: PRO ENH
Submitting Engineer	: H. CZIRIA	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. BEIKE	Release Engineer	: S. DUMDEY
Charge Number	: V98-05460	Coordination Number	: MC3423

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-65710-M0

Component Part Description : ECO TALLY 12

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIQAC-00

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Jan-80

Description : AIQAC00 PDP-8 MAINDEC INDEX

1ST Copyright year : 1976

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-65710-MA		AH-65720-MA					

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

INDEX NEEDS UPDATING

-----SOLUTION/CORRECTION-----

INDEX UPDATED

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number	:	ZF001	ZF002	ZF003	ZF004	ZF005	ZF006	ZF007	ZF008	ZF009	ZF010
		ZF011	ZF012	ZF013	ZF014	ZF015	ZF016	ZF017			

-----AUTHORIZATION-----

Author	:	Release Eng	Maintaining Group	:	REL ENG
Submitting Engineer	:	D Beausoleil	Maintainer	:	CINNAMON
Product Engineer	:		Field Service Engineer	:	
Manufacturing Engineer	:	C Cinnamon	Release Engineer	:	MAUREEN HANSEN
Charge Number	:	G98-08815	Coordination Number	:	MC3547

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-F775A-M0

Component Part Description : ECO TALLY 00

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : AILQA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 17-Mar-80

Description : AILQAAO LQPF DIAGNOSTIC

1ST Copyright year : 1980

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-F775A-MA		AK-F777A-MA		AH-F776A-MA		AL-F778A-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THIS PROGRAM RESIDES ON FLOPPY: AS-E113?
-MA (?=REV)

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 600 2nd Pass : 600 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92 93 94

Operational Environment : 00 99

Device Affected : LQPF

Problem Reports Affected :

Kit Number : ZF008 ZF014 ZF016

-----AUTHORIZATION-----

Author	: B. CRAFT	Maintaining Group	: DIAG-MK
Submitting Engineer	: B. CRAFT	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: JOHN BEIKE	Release Engineer	: M. HANSEN
Charge Number	: D40-02312	Coordination Number	: MC3608

1 OF 1
: B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDEP

PAGE 1 OF 1
Form : B

Component Part Number : AF-F952A-M0

Component Part Description : ECO TALLY 00

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : AKVTC-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 17-Mar-80

Description : AKVTCA0 WS78 AUTOMATIC TEST

1ST Copyright year : 1980

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AS-F952A-MA		AS-F953A-NA					

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

OPERATOR NUISANCE CALLS

-----SOLUTION/CORRECTION-----

RELEASE OPERATOR RUNNABLE CHECKOUT DISKETTES.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 1200

2nd Pass : 3600

ACT Sequence Number :

Multimedia Affected : *No

Processors :

Operational Environment : 00 99

Device Affected : WS78

Problem Reports Affected :

Kit Number : ZF242

-----AUTHORIZATION-----

Author : BILL CRAFT
Submitting Engineer : BILL CRAFT
Product Engineer :
Manufacturing Engineer : J. BEIKE
Charge Number : D40-07921

Maintaining Group : DIAG-MK
Maintainer : MISNER
Field Service Engineer :
Release Engineer : M. HANSEN
Coordination Number : MC3607

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-S064A-M0

Component Part Description : ECO TALLY 00

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : AKVTD-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 17-Mar-80

Description : AKVTD A0 LQP PRINT QUALITY TST

1ST Copyright year : 1980

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AS-S064A-MA		AS-S065A-NA					

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

OPERATOR NUISANCE CALLS

-----SOLUTION/CORRECTION-----

RELEASE OPERATOR RUNNABLE CHECKOUT DISKETTES.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 180 2nd Pass : 180 ACT Sequence Number : Multimedia Affected : *No

Processors :

Operational Environment : 00 99

Device Affected : LQP78

Problem Reports Affected :

Kit Number : ZF242

-----AUTHORIZATION-----

Author : ED BADGER
Submitting Engineer : B. CRAFT
Product Engineer :
Manufacturing Engineer : J. BEIKE
Charge Number : D40-07921

Maintaining Group : DIAG-MK
Maintainer : MISNER
Field Service Engineer :
Release Engineer : M. HANSEN
Coordination Number : MC3606

A

Component Part Number : AF-C672B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLE-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 07-Mar-80

Description : AJRLEB0 RL8-A/RL01 PERF EXER

1ST Copyright year : 1978

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C672B-MA		AK-C674B-MA		AH-C673B-MA		AL-C675B-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THE RL8A DIAGNOSTIC WILL HANG UP IF YOU DO NOT TEST DRIVE 0 AT START OF DIAGNOSTIC.

-----SOLUTION/CORRECTION-----

THE DIAGNOSTIC WAS ENHANCED SO IF DRIVE 0 WAS NOT TESTED FIRST IT WOULD NOT HANG UP.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 75 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 99 20

Device Affected : RL8A RL01

Problem Reports Affected : HH0000535

Kit Number : ZF233 ZF015 ZF017 ZF239 ZF240 ZF238

-----AUTHORIZATION-----

Author	: D. Orin	Maintaining Group	: PRO ENH
Submitting Engineer	: H. CZIRIA	Maintainer	: VROBEL
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: D. ARSENAULT	Release Engineer	: S. DUMDEY
Charge Number	: V98 -05460	Coordination Number	: MC3587

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-6571P-MA

Component Part Description : 8INDEX

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIQAC-PO

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Apr-80

Description : AIQACPO PDP-8 MAINDEC INDEX

1ST Copyright year : 1976

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-6571P-MA		AH-6572P-MA					

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : *No

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number	:	ZF001	ZF002	ZF003	ZF004	ZF005	ZF006	ZF007	ZF008	ZF009	ZF010
		ZF011	ZF012	ZF013	ZF014	ZF015	ZF016	ZF017			

-----AUTHORIZATION-----

Author	:	Release Eng	Maintaining Group	:	PRO ENH
Submitting Engineer	:	M.HANSEN	Maintainer	:	VROBEL
Product Engineer	:		Field Service Engineer	:	
Manufacturing Engineer	:	VROBEL	Release Engineer	:	MAUREEN HANSEN
Charge Number	:	098-08815	Coordination Number	:	MC3650

A
Co
Co
Di
De
Ex
C
Pa
AC

MU
AT
FR
FR

SO
IN
TO
EX
SO

Ru
Pr
Op
De
Pr
Ki

Au
Su
Pr
Ma
Ch

A

Component Part Number :

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description :

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : MD-08-DJADA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 09-Dec-74

Description :

1ST Copyright year : 1974

Last Copyright Year : 1975

Expanded Description : A/D CONVERTER MULTIPLEXER DIAGNOSTIC

-----PRODUCT COMPONENTS AFFECTED-----

Component
Part Number
DJADA-A-D

Media
Variable

Component
Part Number
DJADA-A-PB

Media
Variable

Component
Part Number
DJADA-A-UA

Media
Variable

Component
Part Number

Media
Variable

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THIS IS A NEW DIAGNOSTIC FOR A NEW HARDWARE OPTION
SIMILAR TO THE AD8E.

-----SOLUTION/CORRECTION-----

NEW DIAGNOSTIC FOR NEW HARDWARE OPTION.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88

Operational Environment : 00

Device Affected : AD8A PDP8

Problem Reports Affected :

Kit Number : ZF216

-----AUTHORIZATION-----

Author : V. BREUER
Submitting Engineer : V. BREUER
Product Engineer :
Manufacturing Engineer : E. LANGTON
Charge Number : V00-00000

Maintaining Group : CRO PRO
Maintainer : SHOOP
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC0000

A

Component Part Number : AF-E113H-M1

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 00

ECU Purpose : Patch

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : AJRXH-H1

Patch Level : 1

Product Date : 27-Jun-80

Description : AJRXHH1 WS200 FLP

1ST Copyright year : 1978

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AS-E113H-M1							

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THE AILQAAO LQPF DIAGNOSTIC IS INITIALIZED TO ASSUME
A VT78 SYSTEM AND WILL FAIL ON NON-VT78 SYSTEMS.

-----SOLUTION/CORRECTION-----

INITIALIZE DIAGNOSTIC ON FLOPPY FOR NON VT78 SYSTEM.
INSTALL PATCH.

-----DEPO PATCH AREA-----

Loc	From	To	Mnemonic	Loc	From	To	Mnemonic
0022	1400	0400					

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : *No

Processors : 88 90 91 92 89

Operational Environment : 00 99

Device Affected : WS200

Problem Reports Affected :

Kit Number : ZF016

-----AUTHORIZATION-----

Author	: J. VROBEL	Maintaining Group	: PRO ENH
Submitting Engineer	: H. CZIRIA	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. CASELLA	Release Engineer	: S. DUMDEY
Charge Number	: V98 -05460	Coordination Number	: MC3723

A

Component Part Number : AF-F952B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AKVTC-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 03-Jul-80

Description : AKVTCB0 WS78 AUTOMATIC TEST

1ST Copyright year : 1980

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AS-F952B-MA		AS-F953B-NA					

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

CURRENT WS78 AUTOMATIC TEST DOES NOT HANDLE
RX02 SYSTEMS.

-----SOLUTION/CORRECTION-----

RELEASE NEW VERSION TO TEST RX02 BASED WS78 SYSTEMS

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 1200 2nd Pass : 3600 ACT Sequence Number : Multimedia Affected : *No

Processors : :

Operational Environment : 00 99

Device Affected : WS78

Problem Reports Affected : :

Kit Number : ZF242

-----AUTHORIZATION-----

Author	: BILL CRAFT	Maintaining Group	: DIAG-MK
Submitting Engineer	: BILL CRAFT	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. BEIKE	Release Engineer	: M. HANSEN
Charge Number	: D20 -07921	Coordination Number	: MC3742

A

Component Part Number : AF-S064B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AKVTD-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 14-Jul-80

Description : AKVTDB0 LQP PRINT QUALITY TST

1ST Copyright year : 1980

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AS-S064B-MA		AS-S065B-NA					

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

REV. A HAS 2 MISTAKES
BACKSLASH IS CALLED SLASH AND SLASH IS CALLED BACKSLASH.

-----SOLUTION/CORRECTION-----

RELEASE REV. B TO CORRECT THE ABOVE MISTAKES.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 180 2nd Pass : 180 ACT Sequence Number : Multimedia Affected : *No

Processors :

Operational Environment : 00 99

Device Affected : LQP78

Problem Reports Affected :

Kit Number : ZF242

-----AUTHORIZATION-----

Author	: ED BADGER	Maintaining Group	: DIAG-MK
Submitting Engineer	: B. CRAFT	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. BEIKE	Release Engineer	: S. DUMDEY
Charge Number	: D40 -07921	Coordination Number	: MC3743

A

Component Part Number : AF-B829C-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 02

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AHMIB-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 07-Mar-80

Description : AHMIBCO MI8-E BOOTSTRAP DIAG

1st Copyright year : 1972

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-B829C-MA		AK-B833C-MA		AK-B834C-MA		AH-B830C-MA	
AL-B832C-NA							

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THE DIAGNOSTIC DID NOT TEST THE APT-8 VERSION OF THE MI8-E BOOTSTRAP OPTION.

-----SOLUTION/CORRECTION-----

THE DIAGNOSTIC WAS ENHANCED TO TEST THE APT-8 VERSION OF THE MI8-E OPTION. (NOTE: AN APT-8 KL8 MODULE, CONNECTED IN LOOP BACK MODE, IS NECESSARY FOR TESTING).

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 60 2nd Pass : 60 ACT Sequence Number : Multimedia Affected : Yes

Processors : 90 89 91

Operational Environment : 00

Device Affected : MI8-E

Problem Reports Affected : CC0000263

Kit Number : ZF159 ZF238

-----AUTHORIZATION-----

Author	: J. VROBEL	Maintaining Group	: PRO ENH
Submitting Engineer	: H. CZIRIA	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: D. ARSENAULT	Release Engineer	: S. DUMDEY
Charge Number	: V98 -05460	Coordination Number	: MC3585

E 1 OF 1
m : B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C660C-M0

Component Part Description : ECO TALLY 02

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLB-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 12-Feb-80

Description : AJRLBC0 RL8-A/RL01 DR PT1

1ST Copyright year : 1978

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C660C-MA		AK-C662C-MA		AH-C661C-MA		AL-C663C-NA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

DIAGNOSTIC GIVES THE DRIVE ONLY 10 MS TO SET THE READY BIT AFTER A ZERO DIFFERENCE SEEK.

-----SOLUTION/CORRECTION-----

DIAGNOSTIC CHANGED FROM 10 MS TO 20 MS TO ALLOW DRIVE TO SET THE READY BIT AFTER A ZERO SEEK DIFFERENCE.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 150 2nd Pass : 150 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A RL01

Problem Reports Affected : CC0000358

Kit Number : ZF233 ZF238 ZF016 ZF239 ZF240 ZF015 ZF017

-----AUTHORIZATION-----

Author	: J. RICH	Maintaining Group	: PRO ENH
Submitting Engineer	: H. CZIRIA	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: D. ARSENAULT	Release Engineer	: S. DUMDEY
Charge Number	: E98 -05460	Coordination Number	: MC3586

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-A821B-M0

Component Part Description : ECO ITALY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AKVTA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-May-80

Description : AKVTAB0 VT78 MOS-MEMORY DIAG

1ST Copyright year : 1977

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-A821B-MA		AK-A822B-MA		AH-A823B-MA		AL-S133B-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

WHEN CONTROL C IS TYPED PROGRAM WILL NOT RETURN TO MONITOR WHEN USING AN RX02 AS SYSTEM DISK.

-----SOLUTION/CORRECTION-----

PROGRAM NOW SAVES AND RESTORES FIELD 2 WHERE PART OF THE RX02 DEVICE HANDLER IS STORED.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 75 2nd Pass : 75 ACT Sequence Number : Multimedia Affected : Yes

Processors : 92

Operational Environment : 00 20 99

Device Affected : VT78

Problem Reports Affected : EE0000098

Kit Number : ZF014

-----AUTHORIZATION-----

Author	: B. LECOQ	Maintaining Group	: PRO ENH
Submitting Engineer	: H. CZIRIA	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: JOHN BEIKE	Release Engineer	: S. DUMDEY
Charge Number	: V98 -05460	Coordination Number	: MC3671

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-6573B-M0

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIRFA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 09-May-80

Description : AIRFAB0 RF08 DISK DATA TEST

1ST Copyright year : 1969

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-6573B-MA		AK-6575B-MA		AH-6574B-MA		AL-6576B-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DIAGNOSTIC IS NOT SET UP TO TEST FOR MULTIPLE FIELDS OR DRIVES.

-----SOLUTION/CORRECTION-----

RFVISION WAS MADE TO INCLUDE THE OPTION TO SELECT MULTIPLE DISKS OR FIELDS ADDITIONAL CODE ENHANCES THE AVAILABILITY TO CHANGE THE IOT CODES. TEXT ADDED TO PRINT OUT DRIVE NUMBER WHICH ALLOWS EASIER RECOGNITION OF DRIVE WHERE ERROR OCCURRED.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass ; ACT Sequence Number : Multimedia Affected : Yes

Processors : 88 93 94 89 12

Operational Environment : 00 20 40

Device Affected : RF08

Problem Reports Affected : CC0000521 CC0000695 CC0000366

Kit Number : ZF175 ZF238

-----AUTHORIZATION-----

Author	: W. HEAVEY	Maintaining Group	: PRO ENH
Submitting Engineer	: H. CZIRIA	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: JOHN BEIKE	Release Engineer	: S. DUMDEY
Charge Number	: V98 -05460	Coordination Number	: MC3679

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-6315D-M1

Component Part Description : ECO TALLY 04

ECO Purpose : Patch

Approved : Yes

Diagnostic Package Code : AHLQA-D1

-----PRODUCT IDENTIFICATION-----

Patch Level : 1

Product Date : 27-Jun-80

Description : AHLQAD1 LQP-8 PRINTER DIAG

1ST Copyright year : 1977

Last Copyright Year : 1979

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DIAG. PRINTS OUT AHLQAC INSTEAD OF AHLQAD.

-----SOLUTION/CORRECTION-----

CHANGE REV C TO A D
INSTALL PATCH BELOW
THIS IS AN UNCONDITIONAL PATCH

-----DEPO PATCH AREA-----

Loc	From	To	Mnemonic	Loc	From	To	Mnemonic
6120	0340	0440					
6177	0340	0440					

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 99

Device Affected : VT78 LQP

Problem Reports Affected :

Kit Number : ZF008 ZF014 ZF016

-----AUTHORIZATION-----

Author	: DAVE ORIN	Maintaining Group	: PRO ENH
Submitting Engineer	: H. CZIRIA	Maintainer	: VROBEL
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. BEIKE	Release Engineer	: S. DUMDEY
Charge Number	: V98-05460	Coordination Number	: MC3725

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-6315E-M0

Component Part Description : ECO TALLY 05

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AHLQA-E0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 27-Jun-80

Description : AHLQAE0 LQP-8 PRINTER DIAG

1ST Copyright year : 1977

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-6315E-MA		AK-6318E-MA		AH-6317E-MA		AL-6319E-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

PRINTS OUT AHLQAC INSTEAD OF AHLQAD

-----SOLUTION/CORRECTION-----

CHANGE TWO LOCATIONS WHICH WILL PRINT OUT THE LATEST REV WHICH IS E.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 99

Device Affected : VT78 LQP-8

Problem Reports Affected : EE0000333

Kit Number : ZF008 ZF014 ZF016

-----AUTHORIZATION-----

Author	: DAVE ORIN	Maintaining Group	: PRO ENH
Submitting Engineer	: H. CZIRIA	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. BEIKE	Release Engineer	: S. DUMDEY
Charge Number	: V98-05460	Coordination Number	: MC3726

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-6585G-M0

Component Part Description : ECO TALLY 09

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIRXB-G0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 19-May-80

Description : AIRXBG0 RX01/02 PERF EXER

1ST Copyright year : 1975

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number
AC-6585G-MA

Media Variable

Component Part Number
AK-6587G-MA

Media Variable

Component Part Number
AH-6586G-MA

Media Variable

Component Part Number
AL-6588G-NA

Media Variable

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

ANY ATTEMPTS TO RESTART DIAGNOSTIC VIA 'CIRVG' THEN
'LF' WILL RESULT IN A HUNG LOOP WHEN RUN ON A PDP8A
OR VT78 WITH NO CONSOLE.

-----SOLUTION/CORRECTION-----

ENTERED A NOP SO IF ON A SYSTEM THAT HAS NO CONSOLE
THE CAF WOULD NOT BE BY-PASSED. DCA PASSES SO
COUNTER WILL BE AT ZERO AGAIN.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :

2nd Pass :

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 88 89 90 91 92 93 94 95

Operational Environment : 00 20 99

Device Affected : RX01 RX02 VT78

Problem Reports Affected : CC0000405

Kit Number : ZF008 ZF013 ZF220 ZF014 ZF010 ZF016 ZF238 ZF239 ZF240

-----AUTHORIZATION-----

Author : B. IRRGANG
Submitting Engineer : H. CZIRIA
Product Engineer :
Manufacturing Engineer : J. CASELLA
Charge Number : V98 -05460

Maintaining Group : PRO ENH
Maintainer : MISNER
Field Service Engineer :
Release Engineer : S. DUMDEY
Coordination Number : MC3691

A

Component Part Number : Af-C672C-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 02

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLE-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 09-Mar-80

Description : AJRLECO RL8-A/RL01 PERF EXER

1ST Copyright year : 1978

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component
Part Number
AC-C672C-MA

Media
Variable

Component
Part Number
AK-C674C-MA

Media
Variable

Component
Part Number
AH-C673C-MA

Media
Variable

Component
Part Number
AL-C675C-NA

Media
Variable

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THIS DIAGNOSTIC WILL NOT RETURN TO THE MONITOR WHEN CONTROL C IS TYPED BECAUSE A DATA PATTERN IS WRITTEN INTO ALL OF FIELD 2 WHERE PART OF THE RL01 AND RX02 DEVICE HANDLER RESIDES.

-----SOLUTION/CORRECTION-----

DIAGNOSTIC WAS ENHANCED SO IF YOU HAD AN RL01 OR RX02 AS SYSTEM DISK YOU WOULD NOT OVERWRITE FIELD 2 BEYOND 7400 AND YOU WOULD BE ABLE TO RETURN TO THE MONITOR WHEN A CONTROL C IS TYPED.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 150

2nd Pass : 150

ACT Sequence Number :

Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 99 20

Device Affected : RL8A RL01

Problem Reports Affected : AA0000299

Kit Number : ZF233 ZF015 ZF239 ZF238 ZF240 ZF017

-----AUTHORIZATION-----

Author : D. ORIN
Submitting Engineer : H. CZIRIA
Product Engineer :
Manufacturing Engineer : J. BEIKE
Charge Number : V98 -05460

Maintaining Group : PRO ENH
Maintainer : MISNER
Field Service Engineer :
Release Engineer : S. DUMDEY
Coordination Number : MC3680

OF 1
B

A

Component Part Number : AF-C253D-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 02

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXKLB-D0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 27-Jun-80

Description : AXKLB00 DEC/X8 MOD TTYLUP

1ST Copyright year : 1974

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C253D-MA		AK-C255D-MA		AH-C254D-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

MULTIPLE KL8'S CUT TO A HIGH BAUD RATE (I.E., 8 KL8'S AT 9600) INTERRUPT AT A HIGH FREQUENCY RATE. INTERRUPTS FROM OTHER SOFTWARE MODULES ARE NOT BEING SERVICED AS FREQUENTLY CAUSING AN UNEQUAL RATE OF DATA TRANSFERS.

-----SOLUTION/CORRECTION-----

SOLUTION IS IN DOCUMENTATION UNDER ATTENTION. AFTER INITIALIZATION OF MODULE USE CONTROL 0 TO CHANGE LOC'S TO INSERT A PRESET COUNTER WHICH ON REACHING ZERO WILL EXIT TO THE INTERRUPT SERVICE; TO SERVICE THE OTHER SOFTWARE MODULES MORE FREQUENTLY.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : DD0000078

Kit Number : ZF229 ZK229 ZF238

-----AUTHORIZATION-----

Author	: J. VROBEL	Maintaining Group	: PRO ENH
Submitting Engineer	: H. CZIRIA	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. BEIKE	Release Engineer	: S. DUMDEY
Charge Number	: V98 -05460	Coordination Number	: MC3722

A

Component Part Number : AF-F775B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 Of 1
Form : B

Component Part Description : ECO TALLY 01

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AILQA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 02-Jul-80

Description : AILQAB0 LQPF DIAGNOSTIC

1ST Copyright year : 1980

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-F775R-MA		AK-F777B-MA		AH-F776B-MA		AL-F778B-NA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

SECOND PASS SELF TEST GIVES ERRORS IF ON A VT78
(TIMING PROBLEM).

-----SOLUTION/CORRECTION-----

AILQAB TO RESOLVE TIMING PROBLEM.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 600 2nd Pass : 600 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92 93 94

Operational Environment : 00 99

Device Affected : LQPF

Problem Reports Affected :

Kit Number : ZF008 ZF014 ZF016

-----AUTHORIZATION-----

Author	: B. CRAFT	Maintaining Group	: DIAG-MK
Submitting Engineer	: B. CRAFT	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: JOHN BEIKE	Release Engineer	: M. HANSEN
Charge Number	: D40-02312	Coordination Number	: MC3736

A

Component Part Number : AF-S241A-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 00

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : AKVTF-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 02-Jul-80

Description : AKVTFA0 32K-128K MOS MEM TST

1ST Copyright year : 1980

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-S241A-MA		AK-S240A-MA		AH-S242A-MA		AL-S239A-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

NO DIAGNOSTIC AVAILABLE FOR PDP8A MEMORIES
GREATER THAN 32K. THIS DIAGNOSTIC WILL RESIDE
ON FLOPPY AS-E113?-MA (?=REV).

-----SOLUTION/CORRECTION-----

RELEASE DIAGNOSTIC TO TEST MEMORY TO 128K.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 840 2nd Pass : 840 ACT Sequence Number : Multimedia Affected : Yes

Processors : 92

Operational Environment : 00 99

Device Affected : MOS MEM

Problem Reports Affected :

Kit Number : ZF016

-----AUTHORIZATION-----

Author	: B. CRAFT	Maintaining Group	: DIAG-MK
Submitting Engineer	: B. CRAFT	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J. BEIKE	Release Engineer	: S. DUMDEY
Charge Number	: D40 -07084	Coordination Number	: MC3738

A

Component Part Number : AF-6581F-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 03

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIRXA-F0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 22-Sep-80

Description : AIRXAFO RX01/02 FUNCT TEST

1ST Copyright year : 1975

Last Copyright Year : 1980

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-6581F-MA		AK-6583F-MA		AH-6582F-MA		AL-6584F-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THIS DIAGNOSTIC WAS NOT UPWARD COMPATIBLE WITH NEW PRODUCTS.

-----SOLUTION/CORRECTION-----

THE DIAGNOSTIC WAS REDESIGNED TO SUPPORT NEW PRODUCTS AND CORRECT DEFICIENCIES. OUTSTANDING DEPO'S WERE INCORPORATED.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 600 2nd Pass : 600 ACT Sequence Number : Multimedia Affected : Yes

Processors : 88 89 90 91 93 94 95 92

Operational Environment : 00 02 99

Device Affected : RX01 RX02 RX8E

Problem Reports Affected :

Kit Number : ZF008 ZF010 ZF220 ZF014 ZF016 ZF238 ZF239 ZF240

-----AUTHORIZATION-----

Author	: J. PITTMAN	Maintaining Group	: SSDE
Submitting Engineer	: J. PITTMAN	Maintainer	: MISNER
Product Engineer	: D. CASALETTO	Field Service Engineer	:
Manufacturing Engineer	: WAIVERED	Release Engineer	: S. DUMDEY
Charge Number	: E72 -02316	Coordination Number	: MC3795

A

Compo

Compo

Diagn

Descr

Expan

Comp

Part

AS-F9

TEST
TO TH

REVIS
LA180
THE P
REVIS
BIT A

Run T

Proce

Opera

Devic

Probl

Kit N

Autho

Submi

Produ

Manuf

Charg

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-S298A-A0

Component Part Description : ECO TALLY 00

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : AJADC-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 21-Jul-80

Description : AJADCA0 AD8-A TAG WRPARD TST

1ST Copyright year : 1980

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-S298A-AA		AK-S299A-AA		AL-S300A-NA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DIAGNOSTICS WAS NEVER RELEASE SINCE IT'S
CREATION IN 1975

-----SOLUTION/CORRECTION-----

ORIGINAL RELEASE OF DIAGNOSTIC

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : *No

Processors : 88

Operational Environment :

Device Affected : PDP8 AD8A

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author	: VERA BREUER	Maintaining Group	: DIAG-MK
Submitting Engineer	: GEORGE STEVENS	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J.BEIKE10/01/80	Release Engineer	: S.DUMDEY
Charge Number	: V063-07976	Coordination Number	: MC3763

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-C276E-M2

Component Part Description : ECO TALLY 05

ECO Purpose : Patch

Approved : Yes

Diagnostic Package Code : AXQAB-E2

-----PRODUCT IDENTIFICATION-----

Patch Level : 2

Product Date : 28-Sep-80

Description : AXQABE2 DEC/X8 USERS GUIDE

1ST Copyright year : 1972

Last Copyright Year : 1978

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DEC/X8 MONITOR HANGS ON JOB SCATTER ROUTINE
RANDOM GENERATOR LOCKS-UP ON A RAMDON NUMBER
OF ZERO

-----SOLUTION/CORRECTION-----

INSTALL CONDITIONAL PATCH TO CORRECT PROBLEM

-----DEPO PATCH AREA-----

Loc	From	To	Mnemonic	Loc	From	To	Mnemonic
32637	5220	5227					

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : *Yes

Processors : 12 88 89 90 91 92 93 94

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : HH0000861

Kit Number : ZF229 ZF014 ZK229

-----AUTHORIZATION-----

Author : Don Rice
Submitting Engineer : H.CZIRIA
Product Engineer
Manufacturing Engineer : J.BEIKE12/17/80
Charge Number : V098-05460

Maintaining Group : DIAG-MK
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC3877

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C276F-M0

Component Part Description : ECO TALLY

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXQAB-F0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 30-Sep-80

Description : AXQABF0 DEC/X8 USEFS GUIDE

1ST Copyright year : 1972

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C276F-MA		AK-C278F-MA		AH-C277F-MA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DEC/X8 MONITOR HANGS ON JOB SCATTER ROUTINE -
LOCKS UP ON A RANDOM NUMBER OF ZERO.

-----SOLUTION/CORRECTION-----

INSTALL A RANDOM NUMBER GENERATOR ROUTINE
THAT PREVENTS THE JOB SCATTER ROUTINE FROM LOCKING
UP BY INHIBITING A RANDOM NUMBER OF ZERO.
INCORPORATED OTHER OUTSTANDING PATCHES.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 12 88 89 90 91 92 93 94

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : HH0000861

Kit Number : ZF229 ZF014 ZK229

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: DIAG-MK
Submitting Engineer	: H.CZIRIA	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J.BEIKE12/17/80	Release Engineer	: T.DAVIES
Charge Number	: V098-05460	Coordination Number	: MC3878

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C282F-A0

Component Part Description : ECO TALLY

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXQAD-F0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 28-Sep-80

Description : AXQADFO DEC/X8 DETAILED DESC

1ST Copyright year : 1972

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C282F-AA							

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DEC/X8 MONITOR HANGS ON JOB SCATTER ROUTINE -
LOCKS-UP ON A RANDOM NUMBER OF ZERO.

-----SOLUTION/CORRECTION-----

TO INCORPORATE ALL OUTSTANDING PATCHES SO DOCUMENTATION
WILL REFLECT THE CHANGES WITHIN THE PROGRAM.
INSTALL A RANDOM NUMBERS GENERATOR ROUTINE THAT PREVENTS
THE JOB SCATTER ROUTINE FROM LOCKING UP BY INHIBITING
A RANDOM NUMBER OF ZERO.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors : 12 89 90 91 92 93 94 88

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected : HH0000861

Kit Number :

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: DIAG-MK
Submitting Engineer	: H.CZIRIA	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J.BEIKE12/17/80	Release Engineer	: T.DAVIES
Charge Number	: V098-05460	Coordination Number	: MC3880

OF 1
B

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-C612C-A0

Component Part Description : ECO TALLY

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AXQQB-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 30-Sep-80

Description : AXQQB00 APT-8 SYS DEC/X8

1ST Copyright year : 1975

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AK-C613C-AA		AC-C612C-AA		AL-C614C-NA			

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DEC/X8 MONITOR HANGS ON JOB SCATTER ROUTINE - LOCKSUP
ON A RANDOM NUMBER OF ZERO

-----SOLUTION/CORRECTION-----

TO INCORPORATE ALL OUTSTANDING PATCHES SO DOCUMENTATION
AND PROGRAM WILL REFLECT THE CHANGES WITHIN THE PROGRAM.
INSTALLED A RANDOM NUMBERS GENERATOR ROUTINE THAT PREVENTS
THE JOB SCATTER ROUTINE FROM LOCKING-UP BY INHIBITING A
RANDOM NUMBER OF ZERO.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : No

Processors : 12 88 89 90 91 92

Operational Environment : 99

Device Affected : DEC/X8

Problem Reports Affected : HH0000861

Kit Number :

-----AUTHORIZATION-----

Author	: Don Rice	Maintaining Group	: DIAG-MK
Submitting Engineer	: H.CZIRIA	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J.BEIKE12/17/80	Release Engineer	: T.DAVIES
Charge Number	: V098-05460	Coordination Number	: MC3879

Component Part Number : AF-S464A-M0
 Component Part Description : ECO TALLY 00
 Diagnostic Package Code : AXKAE-A0
 Description : AXKAEAO DEC/X8 MOD MEMORY
 Expanded Description :

ECO Purpose : New
 Patch Level : 0
 1ST Copyright year : 1980

Approved : Yes
 Product Date : 05-Oct-80
 Last Copyright Year : 1981

-----PRODUCT IDENTIFICATION-----

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-S464A-MA		AK-S465A-MA		AH-S466A-MA			

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

ORIGINAL RELEASE OF PROGRAM

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 93 89 88 94 92 12

Operational Environment : 50

Device Affected : DEC/X8

Problem Reports Affected :

Kit Number : ZF229 ZF238

-----AUTHORIZATION-----

Author	: BRUCE THOMPSON	Maintaining Group	: DIAG-MK
Submitting Engineer	: BRUCE THOMPSON	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J.BEIKE12/17/80	Release Engineer	: T.DAIVES
Charge Number	: D040-03428	Coordination Number	: MC3917

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE : 01 1
Form : B

Component Part Number : AF-A821C-MA

Component Part Description : ECO TALLY 03

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AKVTA-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 17-Nov-80

Description : AKVTACO VT278/VT78 MOS MEMORY

1ST Copyright year : 1977

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-A821C-MA		AK-A822C-MA		AH-A823C-MA		AL-S133C-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

VT278 ENHANCEMENTS REQUIRED

-----SOLUTION/CORRECTION-----

MODIFIED EXISTING MEMORY TESTS TO RUN IN 16K
CHUNKS ON A VT278

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 30 2nd Pass : 30 ACT Sequence Number : Multimedia Affected : Yes

Processors : 92

Operational Environment : 00 20 99

Device Affected : VT78 VI278

Problem Reports Affected :

Kit Number : ZF014

-----AUTHORIZATION-----

Author	: M.LETENDR	Maintaining Group	: DIAG-MK
Submitting Engineer	: M.LETENDRE	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: C.CLINE 12/02/80
Manufacturing Engineer	: DAVILL112/03/80	Release Engineer	: T.DAVIES
Charge Number	: E072-02316	Coordination Number	: MC3885

A

Component Part Number : AF-S410A-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 00

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : ALDPA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 17-Dec-80

Description : ALDPAA0 DP278 FUNC TST

1ST Copyright year : 1981

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-S410A-MA		AK-S411A-MA		AH-S412A-MA		AL-S413A-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

ORIGINAL RELEASE OF PROGRAM

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 4 2nd Pass : 4 ACT Sequence Number : Multimedia Affected : *No

Processors : 92

Operational Environment : 00 20 99

Device Affected : VT278 VT78

Problem Reports Affected :

Kit Number : ZF243

-----AUTHORIZATION-----

Author	: D.RICE	Maintaining Group	: DIAG-MK
Submitting Engineer	: D.RICE	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: C.CLIN12/02/80
Manufacturing Engineer	: DAVILL112/03/80	Release Engineer	: T.DAVIES
Charge Number	: E072-02316	Coordination Number	: MC3887

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-S418A-A0

Component Part Description : ECO TALLY 00

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : ALVTB-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 17-Nov-80

Description : ALVTBA0 278 CNTRL PANEL ROM

1ST Copyright year : 1981

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-S418A-AA		AL-S421A-NA					

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

ORIGINAL RELEASE OF PROGRAM

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : *No

Processors : 92

Operational Environment : 00 20 99

Device Affected : VT278 VT78

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : D.RICE
Submitting Engineer : D.RICE
Product Engineer :
Manufacturing Engineer : DAVILL112/03/80
Charge Number : E072-02316

Maintaining Group : DIAG-MK
Maintainer : MISNER
Field Service Engineer : C.CLIN12/02/80
Release Engineer : T.DAVIES
Coordination Number : MC3888

A

Component Part Number : AF-S422A-A0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 00

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : ALVTC-A0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 17-Nov-80

Description : ALVTCA0 278 FOREIGN CHAR ROM

1ST Copyright year : 1981

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-S422A-AA		AL-S425A-NA					

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

ORIGINAL RELEASE OF PROGRAM

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : *No

Processors :

Operational Environment : 00 20 99

Device Affected :

Problem Reports Affected :

Kit Number :

-----AUTHORIZATION-----

Author : D.RICE
Submitting Engineer : D.RICE
Product Engineer :
Manufacturing Engineer : DAVILL112/03/80
Charge Number : E072-02316

Maintaining Group : DIAG-MK
Maintainer : MISNER
Field Service Engineer : C.CLIN12/02/80
Release Engineer : T.DAVIES
Coordination Number : MC3889

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-F952C-MC

Component Part Description : ECO TALLY 02

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AKVIC-CO

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Dec-80

Description : AKVTCCO WS78 AUTOMATIC TEST

1ST Copyright year : 1980

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AS-F952C-MA		AS-F953C-NA					

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

TEST FAILS IF A LA180 PRINTER IS ATTACHED TO THE SYSTEM

-----SOLUTION/CORRECTION-----

REVISE TEST TO HANDLE EITHER A LA180 PRINTER OR A LQP PRINTER AT THE PARALLEL PORT.
REVISE KEYBOARD TEST TO HANDLE 7 OR 8 BIT ASCII

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 1200 2nd Pass : 3600 ACT Sequence Number : Multimedia Affected : *No

Processors : :

Operational Environment : 00 99

Device Affected : WS78

Problem Reports Affected : :

Kit Number : ZF242

-----AUTHORIZATION-----

Author	: BILL CRAFT	Maintaining Group	: DIAG-MK
Submitting Engineer	: BILL CRAFT	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J.BEIKE	Release Engineer	: T.DAVIES
Charge Number	: D20 -07921	Coordination Number	: MC3915

A

Component Part Number : AF-S064C-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 02

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AKVTD-C0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 27-Nov-80

Description : AKVTDC0 LQP PRINT QUALITY TST

1ST Copyright year : 1980

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AS-S064C-MA		AS-S065C-NA					

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

FIELD SERVICE REQUIRED PRINT QUALITY TEST FOR
ENTIRE PDP-8 FAMILY. TEST CURRENTLY
SUPPORTS ONLY WS78

-----SOLUTION/CORRECTION-----

UPDATE PRINT TEST TO SUPPORT PDP-8 FAMILY

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 180 2nd Pass : 180 ACT Sequence Number : Multimedia Affected : *No

Processors : 88 89 90 91 92 93 94

Operational Environment : 00 99

Device affected : LQP78

Problem Reports Affected :

Kit Number : ZF242

-----AUTHORIZATION-----

Author	: ED BADGER	Maintaining Group	: DIAG-MK
Submitting Engineer	: G.SANDY	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: J.BEIKE	Release Engineer	: T.DAVIES
Charge Number	: D40 -07921	Coordination Number	: MC3916

A

Component Part Number : AF-6581G-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 4

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIRXA-G0

-----PRODUCT IDENTIFICATION-----

Patcl. Level : 0

Product Date : 01-Jun-81

Description : AIRXAGO RX01/RX02 FUNC TST

1ST Copyright year : 1975

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-6581G-MA		AK-6583G-MA		AH-6582G-MA		AL-6584G-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

AIRXA REQUIRES SUPPORT OF 278

-----SOLUTION/CORRECTION-----

UPDATE AND RELEASE NEW VERSION OF AIRXA

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 600 2nd Pass : 600 ACT Sequence Number : Multimedia Affected : Yes

Processors : 88 89 90 91 93 94 95 92

Operational Environment : 00 02 99

Device Affected : RX01 RX02 RX8E

Problem Reports Affected :

Kit Number : ZF008 ZF010 ZF220 ZF014 ZF016 ZF238 ZF239 ZF240 ZF243

-----AUTHORIZATION-----

Author	: J. PITTMAN	Maintaining Group	: DIAG-MK
Submitting Engineer	: J. PITTMAN	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: F.RAFFA02/20/81
Manufacturing Engineer	: DAVILLI03/04/81	Release Engineer	: T.DAVIES
Change Number	: E72 -02316	Coordination Number	: MC4031

A

Component Part Number : AF-6586H-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 10

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIRXB-H0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Jun-81

Description : AIRXBH0 RX01/02 PERF EXER

1ST Copyright year : 1975

Last Copyright Year : 1981

Expanded Description :

-----PRGDUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-6585H-MA		AK-6587H-MA		AH-6586H-MA		AL-6588H-NA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

AIRXB REQUIRES SUPPORT OF 278

-----SOLUTION/CORRECTION-----

UPDATE AND RELEASE NEW VERSION OF AIRXB

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 88 89 90 91 92 93 94 95

Operational Environment : 00 02 99

Device Affected : RX01 RX02 VT78

Problem Reports Affected :

Kit Number : ZF008 ZF013 ZF220 ZF014 ZF010 ZF016 ZF238 ZF239 ZF240 ZF243

-----AUTHORIZATION-----

Author	: J.PITTMAN	Maintaining Group	: DIAG-MK
Submitting Engineer	: PITTMAN02/20/81	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: F.FAFFA02/20/81
Manufacturing Engineer	: DAVILLI03/04/81	Release Engineer	: T.DAVIES
Charge Number	: E072-02316	Coordination Number	: MC4032

A

Component Part Number : AF-6571S-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIQAC-S0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Jun-81

Description : AIQACS0 PDP-8 MAINDEC INDEX

1ST Copyright year : 1976

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----	
Component Part Number	Media Variable
AC-6571S-MA	
Component Part Number	Media Variable
AH-6572S-MA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

NEW RELEASE CYCLE REQUIRES UPDATING THE INDEX

-----SOLUTION/CORRECTION-----

UPDATE AND RELEASE THE INDEX

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : *No

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number	:	ZF001	ZF002	ZF003	ZF004	ZF005	ZF006	ZF007	ZF008	ZF009	ZF010
		ZF011	ZF012	ZF013	ZF014	ZF016					

-----AUTHORIZATION-----

Author : MK-DIAG
Submitting Engineer : T.DAVIES
Product Engineer :
Manufacturing Engineer :
Charge Number : D020-05463

Maintaining Group : DIAG-MK
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC4041

A

Component Part Number : AF-F952D-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 03

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AKVTC-D0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 01-Jun-81

Description : AKVTCDO WS78 AUTOMATIC TEST

1ST Copyright year : 1980

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AS-F952D-MA		AS-F953D-NA					

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

THE WS78 AUTOTEST (AKVTCDO) FAILS THE RX PORTION. THE TEST ALWAYS FAILS WHILE RUNNING ON RX02'S SWITCHED IN RX02 MODE.

-----SOLUTION/CORRECTION-----

UPDATE AND RELEASE NEW VERSION OF WS78 AUTOTEST (AKVTCDO)

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 1200 2nd Pass : 3600 ACT Sequence Number : Multimedia Affected : *No

Processors :

Operational Environment : 00 99

Device Affected : WS78

Problem Reports Affected :

Kit Number : ZF242

-----AUTHORIZATION-----

Author	: BILL CRAFT	Maintaining Group	: DIAG-MK
Submitting Engineer	: BILL CRAFT	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	: BEIKE03/18/81	Release Engineer	: T.DAVIES
Charge Number	: D20 -07921	Coordination Number	: MC4043

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-F952E-M0

Component Part Description : ECO TALLY 04

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AKVTC-F:0

-----PRODUCT IDENTIFICATION-----
Patch Level : 0

Product Date : 01-Jun-81

Description : AKVTCEO WS78 AUTOMATIC TEST

1ST Copyright year : 1980

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AF-F952E-MA		AS-F953E-NA					

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

THE WS78 (AKVTCB0, AKVTCC0) BOTH FAIL THE RX PORTION. THE TEST ALWAYS FAILS WHILE RUNNING ON RX02'S SWITCHED IN RX02 MODE. (AKVTCDO) WAS PRODUCED FOR QUICK PRE-RELEASE THIS VERSION (AKVTCEO) IS RELEASED THRU THE NORMAL PATH.

-----SOLUTION/CORRECTION-----

SUBMIT AND RELEASE AKVTCEO WS78 AUTOMATIC TEST

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 1200 2nd Pass : 3600 ACT Sequence Number : Multimedia Affected : *No

Processors :

Operational Environment : 00 99

Device Affected : WS78

Problem Reports Affected :

Kit Number : ZF242

-----AUTHORIZATION-----

Author : BILL CRAFT
Submitting Engineer : BILL CRAFT
Product Engineer :
Manufacturing Engineer : BEIKE03/18/81
Charge Number : D20 -07921

Maintaining Group : DIAG-MK
Maintainer : MISNER
Field Service Engineer :
Release Engineer : T.DAVIES
Coordination Number : MC4081

A

Component Part Number : AF-C656D-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 4

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLA-DC

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 07-Jul-81

Description : AJRLADO RL8-A DSKLS CTR.R

1ST Copyright year : 1978

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----	
Component Part Number	Media Variable
AC-C656D-MA	
Component Part Number	Media Variable
AK-C658D-MA	
Component Part Number	Media Variable
AH-C657D-MA	
Component Part Number	Media Variable
AL-C659D-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Diagnostic would not run correctly on a VT278,
due to Instruction Set and architectural differences.

-----SOLUTION/CORRECTION-----

Modified Diagnostic to recognize Instruction Set
and the architectural differences.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 5 2nd Pass : 90 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A RL02 RL01 RL278

Problem Reports Affected :

Kit Number : ZF241 ZF233 ZF016 ZF017 ZF238 ZF239 ZF240

-----AUTHORIZATION-----

Author	: HANK POULTER	Maintaining Group	: MK-DIAG
Submitting Engineer	: M.LETENDRE	Maintainer	: MISNER
Product Engineer	: S.CARPENTER	Field Service Engineer	: A.TSHUDY6/29/81
Manufacturing Engineer	: A.WALKER6/29/81	Release Engineer	: T.DAVIES
Charge Number	: E720- 6002	Coordination Number	: MC4232

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-C660D-M0

Component Part Description : ECO TALLY 4

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLB-D0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 07-Jul-81

Description : AJRLBDO RL8-A/RL01 DR PT1

1ST Copyright year : 1978

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C660D-MA		AK-C662D-MA		AH-C661D-MA		AL-C663D-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Diagnostic would not run correctly on a VT278,
due to Instruction Set and architectural differences.

-----SOLUTION/CORRECTION-----

Modified Diagnostic to recognize Instruction Set
and architectural differences:

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 150 2nd Pass : 150 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A RL01 RL278

Problem Reports Affected : CC0000908

Kit Number : ZF233 ZF238 ZF016 ZF239 ZF240 ZF017

-----AUTHORIZATION-----

Author	: J. RICH	Maintaining Group	: MK-DIAG
Submitting Engineer	: M.LETENDRE	Maintainer	: MISNER
Product Engineer	: S.CARPENTER	Field Service Engineer	: A.TSHUDY6/29/81
Manufacturing Engineer	: A.WALKER6/29/81	Release Engineer	: T.DAVIES
Charge Number	: E720- 6002	Coordination Number	: MC4233

A

Compo

Compo

Diagn

Descr

Expans

Comp

Part

AC-S2

REQUI

OF MEI

CHANG

AND E

TESTI

Run T

Proce

Opera

Devic

Probl

Kit N

Autho

Submi

Produ

Manuf

Charg

A

Component Part Number : AF-C664B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 2

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLC-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 07-Jul-81

Description : AJRLCB0 RL8-A/RL01 DR PT2

1ST Copyright year : 1978

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C664B-MA		AK-C666B-MA		AH-C665B-MA		AL-C667B-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Diagnostic would not run correctly on a VT278,
due to Instruction Set and architectural differences.

-----SOLUTION/CORRECTION-----

Modified Diagnostic to recognize Instruction Set
and architectural differences.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 60 2nd Pass : 300 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A RL01 RL278

Problem Reports Affected :

Kit Number : ZF233 ZF016 ZF017 ZF238 ZF239 ZF240

-----AUTHORIZATION-----

Author	: J. Rich	Maintaining Group	: MK-DIAG
Submitting Engineer	: M.LETENDRE	Maintainer	: MISNER
Product Engineer	: S.CARPENTER	Field Service Engineer	: A.TSHUDY6/29/81
Manufacturing Engineer	: A.WALKER6/29/81	Release Engineer	: T.DAVIES
Charge Number	: E720- 6002	Coordination Number	: MC4234

A

Component Part Number : AF-C668B-MO

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 2

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLD-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 07-Jul-81

Description : AJRLDBO RL-8/RL01 DR CPT VFY

1ST Copyright year : 1978

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C668B-MA		AK-C670B-MA		AH-C669B-MA		AL-C671B-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Diagnostic would not run correctly on a VT278,
due to Instruction Set and architectural differences

-----SOLUTION/CORRECTION-----

Modified Diagnostic to recognize Instruction Set
and architectural differences.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass :	2nd Pass :	ACT Sequence Number :	Multimedia Affected : Yes
Processors : 89 90 91 92			
Operational Environment : 00 99 20			
Device Affected : RL8A RL278			
Problem Reports Affected : CC0001092 HH0000872			
Kit Number : ZF233 ZF238 ZF016 ZF017 ZF240 ZF239			

-----AUTHORIZATION-----

Author : D.ORIN	Maintaining Group : MK-DIAG
Submitting Engineer : M.LETENDRE	Maintainer : MISNER
Product Engineer : S.CARPENTER	Field Service Engineer : A.TSHUDY6/29/81
Manufacturing Engineer : A.WALKER6/29/81	Release Engineer : T.DAVIES
Charge Number : E720- 6002	Coordination Number : MC4235

A

Component Part Number : AF-C672D-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 4

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLE-D0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 07-Jul-81

Description : AJRLE0 RL8-A/RL01 PERF EXER

1ST Copyright year : 1978

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-C672D-MA		AK-C674D-MA		AH-C673D-MA		AL-C675D-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Diagnostic would not correctly run on a VT278,
due to Instruction Set and architectural differences.

-----SOLUTION/CORRECTION-----

Modified Diagnostic to recognize Instruction Set
and architectural differences.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 150 2nd Pass : 150 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 99 20

Device Affected : RL8A RL01 RL278

Problem Reports Affected : CC0000986

Kit Number : ZF233 ZF239 ZF238 ZF240 ZF017

-----AUTHORIZATION-----

Author	: D. ORIN	Maintaining Group	: DIAG-MK
Submitting Engineer	: M.LETENDRE	Maintainer	: MISNER
Product Engineer	: S.CARPENTER	Field Service Engineer	: A.TSHUDY6/29/81
Manufacturing Engineer	: A.WALKER6/29/81	Release Engineer	: T.DAVIES
Change Number	: E720- 6002	Coordination Number	: MC4236

A

Component Part Number : AF-C682B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 2

ECO Purpose : Change

Approved : [Signature]

Diagnostic Package Code : AJRLG-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 07-Jul-81

Description : AJRLGBO RL8-A/RL01 PCK VFYR

1ST Copyright year : 1978

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-C682B-MA		AK-C684B-MA		AH-C683B-MA		AL-C685B-NA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

Diagnostic would not run correctly on a Vt278,
due to Instruction Set and architectural differences.

-----SOLUTION/CORRECTION-----

Modified Diagnostic to recognize Instruction Set
and architectural differences.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A RL01 RL278

Problem Reports Affected : CC0001091

Kit Number : ZF233 ZF038 ZF017 ZF239 ZF240

-----AUTHORIZATION-----

Author	: Jack Rich	Maintaining Group	: DIAG-MK
Submitting Engineer	: M.LETENDRE	Maintainer	: FISNER
Product Engineer	: S.CARPENTER	Field Service Engineer	: A.TSHUDY6/29/81
Manufacturing Engineer	: A.WALKER6/29/81	Release Engineer	: T.DAVIES
Charge Number	: E720- 6002	Coordination Number	: 237

A

Component

Component

Diagnostic

Description

Expanded

PASS CO

MFG ONL
ALLOW F

Loc
4231

Run Tim

Process

Operati

Device

Problem

Kit Num

Author
Submitt
Product
Manufac
Charge

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Number : AF-F362B-M0

ECO Purpose : Change

Approved : Yes

Component Part Description : ECO TALLY 2

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : AJRLH-B0

Patch Level : 0

Product Date : 07-Jul-81

Description : AJRLH0 RL8/RL02 DR PT1

1ST Copyright year : 1979

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-F362B-MA		AK-F363B-MA		AH-F364B-MA		AL-F365B-NA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

Diagnostic would not run correctly on a VT278,
due to Instruction Set and architectural differences.

-----SOLUTION/CORRECTION-----

Modified Diagnostic to recognize Instruction Set
and architectural differences.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 390 2nd Pass : 390 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A RL02 RL278

Problem Reports Affected :

Kit Number : ZF241 ZF016 ZF017

-----AUTHORIZATION-----

Author	: HANK POULTER	Maintaining Group	: DIAG-MK
Submitting Engineer	: M.LETENDRE	Maintainer	: MISNER
Product Engineer	: S.CARPENTER	Field Service Engineer	: A.TSHUDY6/29/81
Manufacturing Engineer	: A.WALKER6/29/81	Release Engineer	: T.DAVIES
Charge Number	: E720- 6002	Coordination Number	: MC4238

A

Component Part Number : AF-F366B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECU TALLY 2

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLI-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 07-Jul-81

Description : AJRLIB0 RL8/RL02 DR PT2

1ST Copyright year : 1979

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-F366B-MA		AK-F367B-MA		AH-F368B-MA		AL-F369B-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Diagnostic would not run correctly on a VT278,
due to Instruction Set and architectural differences.

-----SOLUTION/CORRECTION-----

Modified Diagnostic to recognize Instruction Set
and architectural differences

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 120 2nd Pass : 300 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A RL02 RL278

Problem Reports Affected :

Kit Number : ZF241 ZF016 ZF017

-----AUTHORIZATION-----

Author	: HANK POULTER	Maintaining Group	: DIAG-MK
Submitting Engineer	: M.LETENDRE	Maintainer	: MISNER
Product Engineer	: S.CARPENTER	Field Service Engineer	: A.TSHUDY6/29/81
Manufacturing Engineer	: A.WALKER6/29/81	Release Engineer	: T.DAVIES
Charge Number	: E720- 6002	Coordination Number	: MC4239

OF 1
B

A

Component Part Number : AF-F370B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

Component Part Description : ECO TALLY 2

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLJ-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 07-Jul-81

Description : AJRLJBO RL8/RL02 DRV CPT

1ST Copyright year : 1979

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-F370B-MA		AK-F371B-MA		AH-F372B-MA		AL-F373B-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Diagnostic would not run correctly on a VT278 due to Instruction Set and architectural differences.

-----SOLUTION/CORRECTION-----

Modified Diagnostic to recognize Instruction Set and architectural differences.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 300 2nd Pass : 300 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A RL02 RL278

Problem Reports Affected :

Kit Number : ZF241 ZF016 ZF017

-----AUTHORIZATION-----

Author	: HANK POULTER	Maintaining Group	: DIAG-MK
Submitting Engineer	: M.LETENDRE	Maintainer	: MISNER
Product Engineer	: S.CARPENTER	Field Service Engineer	: A.TSHUDY6/29/81
Manufacturing Engineer	: A.WALKER6/29/81	Release Engineer	: T.DAVIES
Charge Number	: E720- 6002	Coordination Number	: MC4240

A

Component Part Number : AF-F374B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 2

ECO Purpose : Change

Approved : Yes

-----PRODUCT IDENTIFICATION-----

Diagnostic Package Code : AJRLK-B0

Patch Level : 0

Product Date : 07-Jul-81

Description : AJRLK B0 RL8/RL02 PERF EXER

1ST Copyright year : 1979

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-F374B-MA		AK-F375B-MA		AH-F376B-MA		AL-F377B-NA	

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

Diagnostic would not run correctly on a Vt278,
due the instruction set and architectural differences.

-----SOLUTION/CORRECTION-----

Modified Diagnostic to recognize instruction set and
the architectural differences.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 300 2nd Pass : 32767 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RLBA RL02 RL278

Problem Reports Affected :

Kit Number : ZF241 ZF016 ZF017

-----AUTHORIZATION-----

Author	: HANK POULTER	Maintaining Group	: DIAG-7K
Submitting Engineer	: M.LETENDRE	Maintainer	: MISNER
Product Engineer	: S.CARPENTER	Field Service Engineer	: A.TSHUDY6/29/81
Manufacturing Engineer	: A.WALKER6/29/81	Release Engineer	: T.DAVIES
Charge Number	: E720-6002	Coordination Number	: MC4241

A

Component Part Number : AF-F378B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 2

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AJRLL-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 07-Jul-81

Description : AJRLLB0 RL8/RL02 PCK VFYR

1ST Copyright year : 1979

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-F378B-MA		AK-F379B-MA		AH-F380B-MA		AL-F381B-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

Diagnostic would not run correctly on a VT278 due to instruction set and architectural differences.

-----SOLUTION/CORRECTION-----

Modified Diagnostic to recognize instruction set and architectural differences.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 40 2nd Pass : 960 ACT Sequence Number : Multimedia Affected : Yes

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A RL02 RL278

Problem Reports Affected :

Kit Number : ZF241 ZF016 ZF017

-----AUTHORIZATION-----

Author	: HANK POULTER	Maintaining Group	: DIAG-MK
Submitting Engineer	: M.LETENDRE	Maintainer	: MISNER
Product Engineer	: S.CARPENTER	Field Service Engineer	: A.TSHUDY6/29/81
Manufacturing Engineer	: A.WALKER6/29/81	Release Engineer	: T.DAVIES
Charge Number	: E720- 6002	Coordination Number	: MC4242

A

Component Part Number : AF-S938A-A0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 0

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : ALVTD-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 07-Jul-81

Description : ALVTD A0 RL02 278 SELFTEST ROM

1ST Copyright year : 1981

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AL-S938A-NA							

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

PRODUCT LINE REQUIRED A RL02 278 SELF TESTING ROM

-----SOLUTION/CORRECTION-----

RELEASE ALVTD

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2 2nd Pass : 2 ACT Sequence Number : Multimedia Affected : *No

Processors : :

Operational Environment : :

Device Affected : RL278 RL02

Problem Reports Affected : :

Kit Number : :

-----AUTHORIZATION-----

Author	: M.LETENDRE	Maintaining Group	: DIAG-MK
Submitting Engineer	: M.LETENDRE	Maintainer	: MISNER
Product Engineer	: S.CARPENTER	Field Service Engineer	: A.TSHUDY6/29/81
Manufacturing Engineer	: A.WALKER6/29/81	Release Engineer	: T.DAVIES
Charge Number	: E720- 6002	Coordination Number	: MC4243

A

Component Part Number : AF-6571T-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 20

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AIQAC-T0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 07-Jul-81

Description : AIQACTO PDP-8 MAINDEC INDEX

1ST Copyright year : 1976

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----							
Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable	Component Part Number	Media Variable
AC-6571T-MA		AH-6572T-MA					

-----PRODUCTS OBSOLETED-----

-----PROBLEM/DESCRIPTION-----

NEW RELEASE CYCLE REQUIRES UPDATE OF INDEX

-----SOLUTION/CORRECTION-----

RELEASE AIQACTO

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 2nd Pass : ACT Sequence Number : Multimedia Affected : *No

Processors :

Operational Environment :

Device Affected :

Problem Reports Affected :

Kit Number	:	ZF001	ZF002	ZF003	ZF004	ZF005	ZF006	ZF007	ZF008	ZF009	ZF010
		ZF011	ZF012	ZF013	ZF014	ZF016					

-----AUTHORIZATION-----

Author : MK-DIAG
Submitting Engineer : T.DAVIES
Product Engineer :
Manufacturing Engineer : NOT REQUIRED
Charge Number : D020-05463

Maintaining Group : DIAG-MK
Maintainer : MISNER
Field Service Engineer : NOT REQUIRED
Release Engineer : T.DAVIES
Coordination Number : MC4244

A

Component Part Number : AF-S241B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY !

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : AKVTF-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 07-Jul-81

Description : AKVTFB0 WPS-8 MEM TEST

1ST Copyright year : 1980

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----	
Component Part Number	Media Variable
AC-S241B-MA	
AK-S240B-MA	
AH-S242B-MA	
AL-S239B-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----
REQUIRED TITLE CHANGE AND DID NOT COVER ENTIRE RANGE
OF MEMORY OPTIONS AVAILABLE.

-----SOLUTION/CORRECTION-----
CHANGE TITLE TO WPS-8 MEMORY TEST
AND ENHANCE BY EXPANDING CAPABILITIES TO INCLUDE
TESTING OF ALL WORD PROCESSORS.

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 840 2nd Pass : 840 ACT Sequence Number : Multimedia Affected : Yes

Processors : 92

Operational Environment : 00 99

Device Affected : WPS

Problem Reports Affected :

Kit Number : ZF016

-----AUTHORIZATION-----

Author	: B. CRAFT	Maintaining Group	: DIAG-MK
Submitting Engineer	: B. CRAFT	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	:
Manufacturing Engineer	:	Release Engineer	: T.DAVIES
Charge Number	: D040-03428	Coordination Number	: MC4231

A

Component Part Number : AF-S410B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 1

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : ALDPA-B0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 29-Jun-81

Description : ALDPAB0 DP278 FUNC TST

1ST Copyright year : 1981

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-S410B-MA		AK-S411B-MA		AH-S412B-MA		AL-S413B-NA	

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

DIFFERENCE BETWEEN 2652 AND 5025 COMMUNICATION DEVICES
IN BCP MODE
2. CHIP PROBLEM FOR DUMMY READ TO CLEAR BUFFER

-----SOLUTION/CORRECTION-----

1. ALLOW THREE SYNC CHARACTERS TO BE TRANSFERED
2. INCLUDE A DUMMY READ

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 4	2nd Pass : 4	ACT Sequence Number :	Multimedia Affected : Yes
Processors : 92			
Operational Environment : 00 20 99			
Device Affected : VT278	VT78		
Problem Reports Affected :			
Kit Number : ZF243			

-----AUTHORIZATION-----

Author : D.RICE	Maintaining Group : DIAG-MK
Submitting Engineer : D.RICE	Maintainer : MISNER
Product Engineer :	Field Service Engineer : A.TSHUDY7/08/81
Manufacturing Engineer : DAVILLI7/08/81	Release Engineer : T.DAVIES
Charge Number : E072-02316	Coordination Number : MC4273

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-S414A-M0

Component Part Description : ECO TALLY 00

ECO Purpose : New

Approved : Yes

Diagnostic Package Code : ALVTA-A0

-----PRODUCT IDENTIFICATION-----

Patch Level : 0

Product Date : 17-Nov-80

Description : ALVTAA0 278 CONFIDENCE TEST

1ST Copyright year : 1981

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

Component Part Number	Media Variable						
AC-S414A-MA		AK-S415A-MA		AH-S416A-MA		AL-S417A-NA	
BA-S968A-MA							

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

ORIGINAL RELEASE OF PROGRAM

-----SOLUTION/CORRECTION-----

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 90 2nd Pass : 90 ACT Sequence Number : Multimedia Affected : *No

Processors : 92

Operational Environment : 00 20 99

Device Affected : VT278 VT78

Problem Reports Affected :

Kit Number : ZF243

-----AUTHORIZATION-----

Author	: D.RICE	Maintaining Group	: DIAG-MK
Submitting Engineer	: D.RICE	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: C.CLIN12/02/80
Manufacturing Engineer	: DAVILLI12/03/80	Release Engineer	: T.DAVIES
Charge Number	: E072-02316	Coordination Number	: MC3886

A

Component Part Number : AF-S414B-M0

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING CHANGE ORDER

PAGE 1 OF 1
Form : B

Component Part Description : ECO TALLY 1

ECO Purpose : Change

Approved : Yes

Diagnostic Package Code : ALVTA-B0

~~PRODUCT IDENTIFICATION~~

Patch Level : 0

Product Date : 29-Jun-81

Description : ALVTAB0 DECmate SYSTEM TEST

1ST Copyright year : 1981

Last Copyright Year : 1981

Expanded Description :

~~PRODUCT COMPONENTS AFFECTED~~

Component Part Number	Media Variable						
AC-S414B-MA		AK-S415B-MA		AH-S416B-MA		AL-S417B-NA	
BA-S968B-MA							

~~PRODUCTS OBSOLETED~~

~~PROBLEM/DESCRIPTION~~

~~SOLUTION/CORRECTION~~

~~PRODUCT CHARACTERISTICS~~

Run Time (seconds) 1st Pass : 90 2nd Pass : 90 ACT Sequence Number : Multimedia Affected : *No

Processors : 92

Operational Environment : 00 20 99

Device Affected : VT278 VT78

Problem Reports Affected :

Kit Number : ZF243

~~AUTHORIZATION~~

Author	: D.RICE	Maintaining Group	: DIAG-MK
Submitting Engineer	: D.RICE	Maintainer	: MISNER
Product Engineer	:	Field Service Engineer	: A.TSHUDY7/08/81
Manufacturing Engineer	: DAVILL17/08/81	Release Engineer	: T.DAVIES
Charge Number	: E072-02316	Coordination Number	: MC4274

A

DIGITAL EQUIPMENT CORPORATION
DIAGNOSTIC ENGINEERING PATCH ORDER

PAGE 1 OF 1
Form : B

Component Part Number : AF-C656D-M1

Component Part Description : ECO TALLY 04

ECO Purpose : Patch

Approved : Yes

Diagnostic Package Code : AJRLA-D1

-----PRODUCT IDENTIFICATION-----

Patch Level : 1

Product Date : 18-Sep-81

Description : AJRLAD1 RL8-A DSKLS CTRLR

1ST Copyright year : 1978

Last Copyright Year : 1981

Expanded Description :

-----PRODUCT COMPONENTS AFFECTED-----

-----PRODUCTS OBSOLETE-----

-----PROBLEM/DESCRIPTION-----

PASS COUNT WOULD FREEZE AT 7777 WHEN REACHED.

-----SOLUTION/CORRECTION-----

MFG ONLY PATCH
ALLOW PASS COUNT TO INCREMENT TO 0 INSTALL FOLLOWING PATCH

-----DEPO PATCH AREA-----

Loc	From	To	Mnemonic	Loc	From	To	Mnemonic
4231	7240	7300					

-----PRODUCT CHARACTERISTICS-----

Run Time (seconds) 1st Pass : 5 2nd Pass : 90 ACT Sequence Number : Multimedia Affected : *No

Processors : 89 90 91 92

Operational Environment : 00 20 99

Device Affected : RL8A RL02 RL01 RL278

Problem Reports Affected :

Kit Number : ZF241 ZF233 ZF016 ZF017 ZF238 ZF239 ZF240

-----AUTHORIZATION-----

Author : HANK POULTER
Submitting Engineer : M.LETENDRE
Product Engineer : S.CARPENTER
Manufacturing Engineer : A.WALKER6/29/81
Charge Number : E217-08002

Maintaining Group : DIAG-MK
Maintainer : MISNER
Field Service Engineer : A.TSHUDY6/29/81
Release Engineer : T.DAVIES
Coordination Number : MC4299