






Contrary to DEC drawings:
 CC2 is not grounded, but DN2 is.
 DN1 is not grounded.

Reg. Bus Gating	
TITLE: M8300B	
Document Number:	REV: E
Date: 10/8/2020 4:23:31 PM	Sheet: 1/3



MA, AC, PC	
TITLE: M8300B	
Document Number:	REV: E
Date: 10/8/2020 4:23:31 PM	Sheet: 3/3

VCC